

# Roads ACT



**BROWN**

## **BLACK SPOT FEASIBILITY STUDY 2009**

### **Kingsford Smith Drive / Kuringa Drive FINAL ENGINEERING REPORT**

**JOB NO: C09051**

**OCTOBER 2009**

**TABLE OF CONTENTS**

<b>1</b>	<b>INTRODUCTION .....</b>	<b>1</b>
<b>2</b>	<b>KINGSFORD SMITH DRIVE / KURINGA DRIVE .....</b>	<b>3</b>
<b>2.1</b>	<b>BACKGROUND INFORMATION.....</b>	<b>4</b>
<b>2.2</b>	<b>TRAFFIC IMPACT ASSESSMENT.....</b>	<b>4</b>
<b>2.3</b>	<b>FINDINGS OF THE AUDIT .....</b>	<b>7</b>
<b>2.3.1</b>	<b>Geometric Layout.....</b>	<b>8</b>
<b>2.3.2</b>	<b>Pavement and Drainage.....</b>	<b>11</b>
<b>2.3.3</b>	<b>Signage and Pavement Markings.....</b>	<b>12</b>
<b>2.4</b>	<b>ACCIDENT HISTORY .....</b>	<b>13</b>
<b>2.5</b>	<b>PROPOSED TREATMENTS .....</b>	<b>16</b>
<b>2.6</b>	<b>BCA.....</b>	<b>16</b>

**APPENDICES**

<b>APPENDIX A:</b>	<b>PRELIMINARY REMEDIAL WORKS PLANS</b>
<b>APPENDIX B:</b>	<b>TRAFFIC DATA</b>
<b>APPENDIX C:</b>	<b>COLLISION ACCIDENT DIAGRAM (2004 - 2008)</b>
<b>APPENDIX D:</b>	<b>INTERSECTION OPINION OF COSTS AND BENEFIT COST ANALYSIS</b>

**BLACK SPOT FEASIBILITY STUDY  
FINAL REPORT**



**1 INTRODUCTION**

Brown Consulting (ACT) Pty Ltd was commissioned by Roads ACT in August 2009 to undertake an engineering feasibility study of road safety improvements to 'Black Spot' sites. The sites assessed and the dates of each visit by the assessment team are shown below (our pavement and traffic engineer made visits independent of / in addition to the audit) :

Daytime Inspections	Night-time Inspections
<p><b>Thursday 13<sup>th</sup> August 9am – 12:30pm</b></p> <ul style="list-style-type: none"> <li>◦ Kingsford Smith Dr / Kuringa Dr</li> <li>◦ Northbourne Ave / Antill St</li> <li>◦ Cowper St / Limestone Ave</li> </ul>	<p><b>Tuesday 25<sup>th</sup> August 5:30pm – 9:00pm</b></p> <ul style="list-style-type: none"> <li>◦ Kingsford Smith Dr / Kuringa Dr</li> <li>◦ Northbourne Ave / Antill St</li> <li>◦ Cowper St / Limestone Ave</li> <li>◦ Boldrewood St / David St</li> </ul>
<p><b>Friday 14<sup>th</sup> August 9am – 12:30pm</b></p> <ul style="list-style-type: none"> <li>◦ Boldrewood St / David St</li> <li>◦ Parkes Way (Clunies Ross St-Edinburgh Ave)</li> <li>◦ Brisbane Ave / State Cir</li> </ul>	<ul style="list-style-type: none"> <li>◦ Parkes Way (Clunies Ross St-Edinburgh Ave)</li> </ul> <p><b>Wednesday 26<sup>th</sup> August 5:30pm – 9:00pm</b></p> <ul style="list-style-type: none"> <li>◦ Brisbane Ave / State Cir</li> <li>◦ Canberra Ave / Eyre St</li> <li>◦ Wentworth Ave / Burke Cr</li> <li>◦ Hindmarsh Dr / Yamba Dr</li> <li>◦ Yamba Dr / Melrose Dr</li> <li>◦ Hindmarsh Dr / Melrose Dr</li> <li>◦ Hindmarsh Dr / Brierly St</li> </ul>
<p><b>Tuesday 18<sup>th</sup> August 9am – 12:30pm</b></p> <ul style="list-style-type: none"> <li>◦ Canberra Ave / Eyre St</li> <li>◦ Wentworth Ave / Burke Cr</li> <li>◦ Hindmarsh Dr / Yamba Dr</li> </ul>	<p><b>Friday 28<sup>th</sup> August 5:30pm – 9:00pm</b></p> <ul style="list-style-type: none"> <li>◦ Paddys River Rd (Laurel Camp Rd-Tidbinbilla Tracking Stn)</li> <li>◦ Tidbinbilla Rd (Corin Rd-Point Hut Rd)</li> <li>◦ Uriarra Rd (Coppins Crossing Rd-Cotter Rd)</li> </ul>
<p><b>Wednesday 19<sup>th</sup> August 9am – 12:30pm</b></p> <ul style="list-style-type: none"> <li>◦ Yamba Dr / Melrose Dr</li> <li>◦ Hindmarsh Dr / Melrose Dr</li> <li>◦ Hindmarsh Dr / Brierly St</li> </ul>	
<p><b>Thursday 20<sup>th</sup> August 9am – 12:30pm</b></p> <ul style="list-style-type: none"> <li>◦ Paddys River Rd (Laurel Camp Rd-Tidbinbilla Tracking Stn)</li> <li>◦ Tidbinbilla Rd (Corin Rd-Point Hut Rd)</li> <li>◦ Uriarra Rd (Coppins Crossing Rd-Cotter Rd)</li> </ul>	

## BLACK SPOT FEASIBILITY STUDY FINAL REPORT



The study is based on historical traffic volumes, speed data and site accident history data over the last five years as provided by Roads ACT as well as site inspections.

Each site was visited both during the day and at night and deficiencies noted. No sites were visited during wet weather.

The report is structured as follows:

1. Background Information
2. Traffic Impact Assessment – Considers traffic related issues associated with the site including consideration of the intersection phasing (if applicable)
3. Findings of the Audit – Tabulates the deficiency log and expands on any critical findings categorized in the below format:
  - a. Geometric Layout
  - b. Pavement and Drainage
  - c. Signage and Pavement Markings
  - d. Lateral Clearance to Roadside Objects
  - e. Bus Stop
  - f. Non-motorised Traffic
  - g. Lighting and Reflectors

In the absence of any of the above categories, it can be assumed that no such audit deficiency has been identified or that they have minimal inherent risk.

4. Accident History – Summarises and provides interpretation of the accident data from the preceding five year period (January 2004 – December 2008). This history should be read in conjunction with the collision diagram attached in Appendix C.
5. Proposed Treatments – Outlines cost effective remedial treatments identified targeted to address numerous and/or severe crash types
6. Benefit Cost Analysis (BCA) – Determination of the Benefit Cost Ratio (BCR) for the proposed short term treatments. A BCR >2 is considered cost effective.

## **2 Kingsford Smith Drive / Kuringa Drive**

The giveaway controlled tee intersection between Kingsford Smith Drive / Kuringa Drive was inspected on Thursday 13th August 9am – 12:30pm and Tuesday 25th August 5:30pm – 9:00pm. This intersection facilitates approximately 10,000 vehicle movements per weekday. The predominant movements in the AM peak period are relatively balanced between the left turn out of and right turn into Kingsford Smith Drive and the eastbound movement on Kuringa Drive. The counter westbound movement as well as the left turn out of and right turn into Kingsford Smith Drive are assumed to carry the greatest volume during the PM peak period.

The key deficiencies identified by the road safety audit involve:

- The absence of a sightboard at the tee head
- No advance tee intersection warning on the southern approach
- Sight distance is restricted to the left
- Westbound through vehicles are hidden behind left turning vehicles (no separation)

In order to address the relatively high accident rate associated with the right turn movement out of the Kingsford Smith Drive approach (responsible for 42% of crashes at the intersection) it is recommended that the give way control is upgraded to a stop control for this movement (Treatment 1).

A problem that exists when looking right from the southern approach is the difficulty in observing a through vehicle immediately behind a left turning vehicle. In order to address this deficiency it is recommended that the gore area is widened through the use of chevrons. This is likely to reduce the frequency of incidents involving vehicles turning right out of Kingsford Smith Drive and westbound through vehicles on Kuringa Drive (Treatment 5).

Other more minor treatments involve the installation of a tee warning sign, extending the median through the use of linemarking and a sightboard at the tee head. The Benefit Cost Ratio (BCR) calculated based on these treatments was 13.8; hence the treatments are cost effective and should be undertaken. The most cost effective remedial action involves implementing treatments 1 and 5 (BCR of 15.3)

## **2.1 Background Information**

Kingsford Smith Drive is a north-south arterial, predominantly carrying through traffic during peak periods. It serves as an important link between the north-western suburbs of Spence and Flynn south to Hawker where it becomes William Hovell Drive. Kuringa Drive is an east-west arterial with a rural road environment to the west of Kingsford Smith Drive, connecting to the suburb of Fraser and a more urban midblock to the east, terminating at the Barton Highway. There are no fronting landuses within the study area. The nearest intersection is a giveway controlled tee intersection between Kingsford Smith Drive / Magrath Crescent, 165m to the south of Kuringa Drive.

A left slip lane is present on the eastern approach. The Kingsford Smith Drive approach flares to accommodate left and right turning vehicles. Kingsford Smith Drive reduces down from 4 lanes to 2 lanes 70m south of the intersection.

Speed data was not available for this intersection.

## **2.2 Traffic Impact Assessment**


An intersection turn count was undertaken between 7:45-9am on 31<sup>st</sup> August 2009. The intersection facilitates approximately 10,000 vehicle movements per weekday.

The predominant movements in the AM peak period are relatively balanced between the left turn out of and right turn into Kingsford Smith Drive and the eastbound movement on Kuringa Drive. The counter westbound movement as well as the left turn out of and right turn into Kingsford Smith Drive are assumed to carry the greatest volume during the PM peak period.

The criteria for evaluating the operational performance of intersections is provided by the RTA Guidelines to Traffic Generating Developments and reproduced in Table 1.


**Table 1 Performance Criteria for Intersections**

Level of Service	Average Delay Per Vehicle (secs/vehicle)	Traffic Signals, Roundabout	Give-Way and Stop Signs
A	Less than 14	Good Operation	Good operation
B	15 to 28	Good with acceptable delays and spare capacity	Acceptable delays and spare capacity
C	29 to 42	Satisfactory	Satisfactory but accident study required
D	43 to 56	Operating near capacity	Near capacity and other accident study required
E	57 to 70	At capacity; at signals incidents will cause excessive delays	At capacity and requires other control mode
F	Greater than 70	Roundabouts require other control mode	



**Figure 1 AM peak period performance for Kingsford Smith Dr / Kuringa Drive**

As illustrated in Figure 1, the intersection performs well during the AM peak period.



**Figure 2 PM peak period performance for Kingsford Smith Dr / Kuringa Dr**

As illustrated in Figure 2, the intersection performs well during the PM peak period.

Consideration was given to reversing the priority at this intersection, essentially creating a continuous movement out of Kingsford Smith Drive to Kuringa Drive (eastbound exit), following the alignment of the westbound left slip lane, and teeing Kuringa Drive (eastern approach) to the back of the curve. This measure was considered with the aim of reducing the most common and severe accident type, involving vehicles turning right out of Kingsford Smith Drive. This treatment would also serve to slow vehicles approaching from the west and eliminate the sight distance constraint looking left from the Kingsford Smith Drive hold line (refer to Findings of the Audit).

The number of through vehicle movements on Kuringa Drive (eastbound – AM, westbound – PM) however balanced the right turn out Kingsford Smith Drive and would not lend an improvement to the intersections operation from a traffic efficiency point of view. It is not recommended that this option is pursued, primarily on this basis<sup>1</sup>. A concept illustrating this treatment is included in Appendix A (Drawing No. C09051-T01.2)

<sup>1</sup> This is also a high cost treatment

**BLACK SPOT FEASIBILITY STUDY  
FINAL REPORT**



**2.3 Findings of the Audit**

No	Location	Description	Assessed Risk
1.	Kuringa Drive	No sightboard present at T head	Low
2.	Kingsford Smith Drive - northbound	No intersection approach T warning on Kingsford Smith Drive	Low
3.	Kuringa Drive – both directions	No Shoulders beyond kerbed section Shoulder breakaway and drop-off up approximately 150mm. (photo)	Low
4.	Kuringa Drive - eastbound	70 km/h regulatory sign partially obscured by vegetation (photo)	Low
5.	Kuringa and Kingsford Smith Drs	No formal exit point for connections to maintenance access/ fire trail	Low
6.	Kuringa and Kingsford Smith Drs	No provision for on-road cycling Existing arrangement shared lane width approx 3.6m	MEDIUM
7.	Kingsford Smith Dr - northbound	Vehicle at hold line – driver with passenger may experience visibility restriction to traffic approaching from west on curved alignment – behind the drivers line of sight.	MEDIUM
8.	Kingsford Smith Dr - northbound	Vehicle at hold line – driver may experience visibility restriction to traffic approaching from west through alignment of roadside furniture.	MEDIUM
9.	Kuringa Dr	Compound curve/ Reverse curve approach Ratio of curve radii within compound less than desirable for some elements	Low
10.	Kuringa Dr	Compound curve/ Reverse curve approach Length of curve less than desirable for 60km/h	Low
11.	Kuringa Dr Westbound	Left slip movement held at acute angle and does not sufficiently slow approaching vehicles	MEDIUM

**BLACK SPOT FEASIBILITY STUDY  
FINAL REPORT**




12.	Kingsford Smith Dr - northbound	Vehicle at hold line – driver may experience visibility restriction to traffic approaching from east through obstruction from left turning vehicle.	MEDIUM
-----	---------------------------------	---	--------

**2.3.1 Geometric Layout**

The giveway controlled tee intersection between Kingsford Smith Drive / Kuringa Drive has single lane approaches on all legs. No on-road cycling is provided, and while adequate width is provided on Kingsford Smith Drive, Kuringa Drive has 3.6m wide lanes, 0.1m short of the minimum required for shared width. The cyclist volume on this road is anticipated to be very low however and no cyclist / vehicle accidents have been reported in the last five years. The following speed limits are posted:

- Kuringa Drive (western leg) - 60km/hr
- Kuringa Drive (eastern leg) - 80km/hr
- Kingsford Smith Drive – 70km/hr



**Figure 3** Kerb is setback to accommodate heavy vehicles, however linemarking would provide better definition for light vehicles

A problem that exists when looking right from the southern approach (refer to Figure 3) is the difficulty in observing a through vehicle immediately behind a left turning vehicle.



**Figure 4** The median on the southern approach could be reconstructed to permit two southbound lanes

As Figure 4 illustrates, it would be relatively straight forward to widen the southbound exit on Kingsford Smith Drive to two lanes, allowing a continuous left turn movement from Kuringa Drive (east). While this would address audit deficiency 11 and reduce eliminate the potential left through conflict, following a review of the traffic volumes, which revealed that the counter Kuringa Drive right turn movement was very light during peak periods and an examination of the crash history; no such crashes have occurred during the past five years, no action is recommended.

2.3.2 Pavement and Drainage



**Figure 5 Pavement deterioration on westbound left slip**

Pavement surface is Dense Grade Asphalt with some coarse aggregate surface texture in good condition. All pavement is bounded by kerb & gutter. The left turn slip lane to Kingsford Smith has 5m of shear cracking at start of the splitter island & 3m of shear cracking with deformation mid-way along island. Existing surface is 40 – 80mm higher than lip of gutter due to not being keyed-in during the overlay.

Linemarking & RPM's are in a satisfactory condition.

Stormwater inlets are free from blockage & pits appear to be free draining.




**Figure 6** Lack of grass & loss of backfill behind Kuringa Drive eastbound kerb indicates possible use of verge by heavy vehicles

During time on site a small number of cars & CV's were noted at excessive speed.

### **2.3.3 Signage and Pavement Markings**

During inspection vehicles waiting to turn right into Kuringa Dr stopped 2 – 3m before Hold Line probably due to obscured vision from signage due to street light columns to the left. Deficiencies 1, 2 while considered low risk are inexpensive and signage should be instated (refer to Figure 7).

Upgrading the intersection control for the right turning movement from the current giveway to a stop condition would address the medium risk deficiencies 7, 8 and 12 and the warrant is further examined in Proposed Treatments. It should be noted that the intersection flares adequately to retain the giveway control for the left turn movement.



**Figure 7** Sightboard required

#### 2.4 Accident History

The accident history for the Kingsford Smith Drive / Kuringa Drive intersection has been determined from Site Accident History by Injury Type collision data which was provided by TAMS for the five year period between 01/01/2004 and 31/12/2008. A Collision Diagram which represents this data is included in **Appendix C**, refer Drawing C09051-AD01.

A total of 31 accidents were recorded at the intersection during this five year period, more than half (17, 55% of all accidents) occurred within the intersection itself as a result of adjacent or approaching directions (refer to Figure 8). These collision types (DCA Codes 101-109 and 202-207) tend to have a high severity.


There were 10 (32%) rear end collisions (DCA Codes 301-304), 80% of which occurred between vehicles intending to turn right from Kingsford Smith Drive into Kuringa Drive. This indicates that drivers may not be identifying counter vehicles that they need to give way to with enough advance warning.



**Injuries/fatalities**

Of the 31 accidents, seven (23%) resulted in injury. All of these accidents occurred within the intersection. Six of these accidents (86%) were between vehicles turning right into Kuringa Drive and colliding with Westbound traffic on their right (4 times, 57%) or with Eastbound traffic on their left (2 times, 29%).

No fatalities were recorded within the data period.

The intersection operates worse than what would typically be expected for the number of vehicle movements it facilitates, with 2.7 crashes per million entering vehicles (C/MEV). As a general rule, 1 crash per million entering vehicles is the threshold.





**Notes**

1. Collision type by DCA sub groups
2. Intersection collisions are represented in both approaches

Source: TAMS Site Accident History by Injury Type collision data, 01/01/2004 to 31/12/2008

**Figure 8: Breakdown of Collision Types by approach at Kingsford Smith Drive / Kuringa Drive**

## 2.5 Proposed Treatments

Treatments have been identified following consideration of the road safety audit findings and a review of the crash history at each site. The next section outlines the estimated crash reduction associated with the measures proposed and the associated economic benefit.

Treatment	Location	Proposed Treatment	Based on AUDIT findings / CRASH history
1	Southern Approach (right turn movement)	Replace Give Way with Stop sign	AUDIT and CRASH
2	Southern Approach	Install Tee warning sign	AUDIT
3	Intersection	Install Sightboard at tee head	AUDIT
4	Southern Approach (median)	Extend median through linemarking	AUDIT
5	Eastern Approach (left slip movement)	Improve separation between westbound through and left movement through use of chevrons	AUDIT and CRASH

Treatments 2, 3 and 4 were identified as part of the audit and there is no accident history associated with these deficiencies.

## 2.6 BCA

Treatment 1, upgrade from giveway to stop, is likely to increase the frequency of rear enders (301-303), however decrease the number of more severe adjacent approach incidents (101-109) by the same percentage (50%). The RTA Accident Reduction guide was used to determine the effectiveness of the proposed countermeasure in this instance (20: New signing STOP) in the absence of an equivalent treatment in the Austroads guide.

## BLACK SPOT FEASIBILITY STUDY FINAL REPORT



Treatment 5, enlarge gore area on eastern approach to achieve greater separation between westbound through and left movement through the use of chevrons, will likely reduce the frequency of adjacent approach incidents (104 - vehicles turning right out of Kingsford Smith Drive and westbound through vehicles on Kuringa Drive). The effectiveness of this treatment has been estimated through reviewing Treatment Code K6: Improve sight lines (30% reduction to 104, Austroads) and Separate Left Turn Deceleration Lane, Painted or Channelised (15% reduction to 104, 60% reduction to 301-303, RTA). As the proposed treatment simply improves the separation and does not create a new left turn deceleration lane, a custom reduction of 15% to incidents involving vehicles turning right out of Kingsford Smith Drive and westbound through vehicles on Kuringa Drive and a 20% reduction to rear enders on the southern approach is considered appropriate.

As both Treatments 1 and 5 have overlapping accident reduction potential, the net cumulative reduction needs to be determined. The combination of these two treatments is expected to reduce adjacent approach incidents (101-109) by 50% at conflict location 4 and 8 (refer to Drawing No. C09051-AD01) and by 58% at conflict location 3. Similarly at conflict location 1, a net increase in rear enders of 20% has been assumed.

Two treatment packages have been assessed; Option 1 includes only treatments with a demonstrated accident reduction potential, while Option 2 includes all treatments.

### Option 1

The capital costs used in the BCA of \$5,900 include treatments 1 and 5. A relatively low 1% compound traffic growth rate was assumed for this intersection. A conservative annual maintenance loading of \$2,000 per year was also accommodated. A discount rate of 7% over ten years was applied, with the assumption that the treatments would be carried out during the 20010/2011 financial year. The BCR calculated on this basis was 14.5.

**Option 2**

The capital costs used in the BCA of \$10,000 include treatments 1 - 5. A relatively low 1% compound traffic growth rate was assumed for this intersection. A conservative annual maintenance loading of \$2,000 per year was also accommodated. A discount rate of 7% over ten years was applied, with the assumption that the treatments would be carried out during the 20010/2011 financial year. As noted in Section 2.5, only treatment 1 and 5 is anticipated to reduce the crash rate at Kuringa Drive / Kingsford Smith Drive. Implementing treatments 2, 3 and 4 will not reduce the overall crash rate for the purpose of this analysis. **The BCR calculated on this basis was 12.1.**

---



**APPENDIX A**

**PRELIMINARY REMEDIAL WORKS PLANS:**

**C09051 – RT01**

**C09051 – RT1.2**





BRANDON TYPE  
**KINGSFORD SMITH DRIVE - KURINGA DRIVE INTERSECTION REVERSE PRIORITY**  
 DRAWING NUMBER: C09051-RT01.2+

Best Practice (ACT) P114, Engineers & Architects  
 15/14/2009, Lymington ACT, Australia 2602  
 15/14/2009, Lymington ACT, Australia 2602  
 15/14/2009, Lymington ACT, Australia 2602  
 15/14/2009, Lymington ACT, Australia 2602  
**BRANDON CONSULTING**



ROADS ACT  
**BLACKSPOT FEASIBILITY STUDY**  
 2009 - 2010

SCALE: 1:500  
 AS SHOWN  
 SCALE: 1:500  
 1:500

FOR DISCUSSION  
 PURPOSES ONLY

REV	DATE	BY	CHKD	APPD	DATE
1	15/11/09	...	...	...	15/11/09
2	...	...	...	...	...
3	...	...	...	...	...
4	...	...	...	...	...
5	...	...	...	...	...
6	...	...	...	...	...
7	...	...	...	...	...
8	...	...	...	...	...
9	...	...	...	...	...
10	...	...	...	...	...







---

**APPENDIX B**

**TRAFFIC DATA**

**SIDRA**  
**INTERSECTION**

# Movement Summary

## Kingsford Smith Dr / Kuringa Dr

AM

Give-way

### Vehicle Movements


Mov ID	Turn	Dem Flow (veh/h)	%HV	Deg of Satn (v/c)	Aver Delay (sec)	Level of Service	95% Back of Queue (m)	Prop. Queued	Eff. Stop Rate	Aver Speed (km/h)
<b>Kingsford Smith Dr S leg</b>										
1	L	13	7.7	0.500	16.0	LOS B	28	0.66	0.94	45.7
3	R	298	5.0	0.501	17.2	LOS B	28	0.66	1.01	48.0
<b>Approach</b>		<b>311</b>	<b>5.1</b>	<b>0.501</b>	<b>17.2</b>	<b>LOS B</b>	<b>28</b>	<b>0.66</b>	<b>1.00</b>	<b>47.9</b>
<b>Kuringa Dr E leg</b>										
4	L	332	5.1	0.236	10.6	LOS A	11	0.10	0.63	57.3
5	T	132	5.3	0.070	2.6	LOS A	0	0.00	0.23	71.0
<b>Approach</b>		<b>464</b>	<b>5.2</b>	<b>0.236</b>	<b>8.3</b>	<b>LOS A</b>	<b>11</b>	<b>0.07</b>	<b>0.52</b>	<b>60.5</b>
<b>Kuringa Dr W leg</b>										
11	T	285	4.9	0.165	0.5	LOS A	9	0.27	0.00	59.9
12	R	22	4.5	0.164	9.7	LOS A	9	0.27	0.65	48.5
<b>Approach</b>		<b>307</b>	<b>4.9</b>	<b>0.165</b>	<b>1.1</b>	<b>LOS A</b>	<b>9</b>	<b>0.27</b>	<b>0.05</b>	<b>59.0</b>
<b>All Vehicles</b>		<b>1082</b>	<b>5.1</b>	<b>0.501</b>	<b>8.8</b>	<b>Not Applicable</b>	<b>28</b>	<b>0.30</b>	<b>0.52</b>	<b>55.8</b>

Symbols which may appear in this table:

Following Degree of Saturation  
 # x = 1.00 for Short Lane with resulting Excess Flow  
 \* x = 1.00 due to minimum capacity

Following LOS  
 # - Based on density for continuous movements

Following Queue  
 # - Density for continuous movement



Site: AM  
 H:\C09000\C09051\traffic\1 King\_Kuri\King\_Kuri.aap  
 Processed Sep 09, 2009 05:19:35PM

A0607, Brown Consulting (ACT) Pty Ltd, Medium Office  
 Produced by SIDRA Intersection 3.2.2.1563  
 Copyright ©2000-2008 Akcelik and Associates Pty Ltd  
[www.sidrasolutions.com](http://www.sidrasolutions.com)

SIDRA  
INTERSECTION

# Movement Summary

## Kingsford Smith Dr / Kuringa Dr

PM

Give-way

### Vehicle Movements


Mov ID	Turn	Dem Flow (veh/h)	%HV	Deg of Satn (v/c)	Aver Delay (sec)	Level of Service	95% Back of Queue (m)	Prop. Queued	Eff. Stop Rate	Aver Speed (km/h)
<b>Kingsford Smith Dr S leg</b>										
1	L	22	4.5	0.550	16.3	LOS B	34	0.68	1.04	45.4
3	R	332	5.1	0.554	17.6	LOS B	34	0.68	1.04	47.7
<b>Approach</b>		<b>354</b>	<b>5.1</b>	<b>0.554</b>	<b>17.5</b>	<b>LOS B</b>	<b>34</b>	<b>0.68</b>	<b>1.04</b>	<b>47.5</b>
<b>Kuringa Dr E leg</b>										
4	L	298	5.0	0.210	10.5	LOS A	9	0.07	0.64	57.5
5	T	285	4.9	0.151	2.6	LOS A	0	0.00	0.23	71.0
<b>Approach</b>		<b>583</b>	<b>5.0</b>	<b>0.210</b>	<b>6.7</b>	<b>LOS A</b>	<b>9</b>	<b>0.04</b>	<b>0.44</b>	<b>63.2</b>
<b>Kuringa Dr W leg</b>										
11	T	132	5.3	0.080	1.1	LOS A	5	0.40	0.00	58.4
12	R	13	7.7	0.080	10.3	LOS A	5	0.40	0.68	48.0
<b>Approach</b>		<b>145</b>	<b>5.5</b>	<b>0.080</b>	<b>1.9</b>	<b>LOS A</b>	<b>5</b>	<b>0.40</b>	<b>0.06</b>	<b>57.4</b>
<b>All Vehicles</b>		<b>1082</b>	<b>5.1</b>	<b>0.554</b>	<b>9.6</b>	<b>Not Applicable</b>	<b>34</b>	<b>0.30</b>	<b>0.58</b>	<b>56.1</b>

Symbols which may appear in this table:

Following Degree of Saturation  
 # x = 1.00 for Short Lane with resulting Excess Flow  
 \* x = 1.00 due to minimum capacity

Following LOS  
 # - Based on density for continuous movements

Following Queue  
 # - Density for continuous movement



Site: PM  
 H:\C09000\C09051\traffic\1 King\_Kuri\King\_Kuri.aap  
 Processed Sep 11, 2009 11:06:37AM

A0607, Brown Consulting (ACT) Pty Ltd, Medium Office  
 Produced by SIDRA Intersection 3.2.2.1563  
 Copyright ©2000-2008 Akcelik and Associates Pty Ltd  
[www.sidrasolutions.com](http://www.sidrasolutions.com)



Kingsford Smith Dr / Kuringa Dr  
 AM  
 Intersection ID: 1  
 Give-Way Sign Controlled Intersection

Lane No.	Dem Flow (veh/h)			Tot	Min	Tot	Deg. x	Lane Util %
	Lef	Thru	Rig		Cap (veh/h)	Cap (veh/h)		
-----								
South: Kingsford Smith Dr S leg								
1 LR	13	0	298	311	60	621	0.501	100
-----								
East: Kuringa Dr E leg								
1 L	332	0	0	332	60	1405	0.236	100
2 T	0	132	0	132	132	1885	0.070	100
-----								
West: Kuringa Dr W leg								
1 TR	0	285	22	307	60	1865	0.165	100
-----								

The capacity value for priority and continuous movements is obtained by adjusting the basic saturation flow for heavy vehicle and turning vehicle effects. Saturation flow scale applies if specified.



SIDRA SOLUTIONS

Site: AM  
 H:\C09000\C09051\traffic\1 King\_Kuri\King\_Kuri.aap  
 Processed Sep 09, 2009 05:19:35PM

A0607, Brown Consulting (ACT) Pty Ltd, Medium Office  
 Produced by SIDRA Intersection 3.2.2.1563  
 Copyright ©2000-2008 Akcelik and Associates Pty Ltd  
[www.sidrasolutions.com](http://www.sidrasolutions.com)

SIDRA  
INTERSECTION

## Output Tables

### Kingsford Smith Dr / Kuringa Dr

PM

#### Run Information

\* Basic Parameters:

Intersection Type: Unsignalised - Give Way  
 Driving on the left-hand side of the road  
 Input data specified in Metric units  
 Model Defaults: Standard Left  
 Peak Flow Period (for performance): 30 minutes  
 Unit time (for volumes): 60 minutes.  
 Delay definition: Control delay  
                   Geometric delay included  
 SIDRA Standard Delay model used  
 SIDRA Standard Queue model used  
 Level of Service based on: Delay (RTA NSW)  
 Queue definition: Back of queue, 95th Percentile

**Table B.1 - Movement Definitions and Flow Rates (Origin-Destination)**

Kingsford Smith Dr / Kuringa Dr  
 PM  
 Intersection ID: 1  
 Give-Way Sign Controlled Intersection

From Approach	To Approach	Mov ID	Turn	Flow Rate		Flow Scale	Peak Flow Factor
				LV	HV		
-----							
South: Kingsford Smith Dr S leg							
	East	3	Right	315	17	1.00	0.95
	West	1	Left	21	1	1.00	0.95
-----							
East: Kuringa Dr E leg							
	South	4	Left	283	15	1.00	0.95
	West	5	Thru	271	14	1.00	0.95
-----							
West: Kuringa Dr W leg							
	South	12	Right	12	1	1.00	0.95
	East	11	Thru	125	7	1.00	0.95
-----							

Unit Time for Volumes = 60 minutes

Peak Flow Period = 30 minutes

Flow Rates include effects of Flow Scale and Peak Flow Factor

**Table S.8 - Lane Flow and Capacity Information**

Kingsford Smith Dr / Kuringa Dr  
 PM  
 Intersection ID: 1  
 Give-Way Sign Controlled Intersection

Lane No.	Dem Flow (veh/h)			Tot	Min	Tot	Deg. x	Lane Util %
	Lef	Thru	Rig		Cap (veh/h)	Cap (veh/h)		
-----								
South: Kingsford Smith Dr S leg								
1 LR	22	0	332	354	60	639	0.554	100
-----								
East: Kuringa Dr E leg								
1 L	298	0	0	298	60	1417	0.210	100
2 T	0	285	0	285	285	1890	0.151	100
-----								
West: Kuringa Dr W leg								
1 TR	0	132	13	145	60	1818	0.080	100
-----								

The capacity value for priority and continuous movements is obtained by adjusting the basic saturation flow for heavy vehicle and turning vehicle effects. Saturation flow scale applies if specified.



SIDRA SOLUTIONS

Site: PM  
 H:\C09000\C09051\traffic\1 King\_Kuri\King\_Kuri.aap  
 Processed Sep 11, 2009 11:06:37AM

A0607, Brown Consulting (ACT) Pty Ltd, Medium Office  
 Produced by SIDRA Intersection 3.2.2.1563  
 Copyright ©2000-2008 Akcelik and Associates Pty Ltd  
[www.sidrasolutions.com](http://www.sidrasolutions.com)



---

**APPENDIX C**



**ACCIDENT DIAGRAMS (2004 – 2008)**



**LEGEND**

- ACCIDENT CAUSING INJURY
- ACCIDENT CAUSING FATALITY
- % APPROACH CRASHES
- % INTERSECTION CRASHES
- DRY AND CLEAR
- LIGHT RAIN
- WET WITH LIGHT RAIN
- WET WITH HEAVY RAIN
- LOOSE SURFACE
- MUDDY / OILY SURFACE
- DRY AND FOGGY
- UNKNOWN

01	02	03	04	05	06	07	08	09	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	31	32	33	34	35	36	37	38	39	40	41	42	43	44	45	46	47	48	49	50	51	52	53	54	55	56	57	58	59	60	61	62	63	64	65	66	67	68	69	70	71	72	73	74	75	76	77	78	79	80	81	82	83	84	85	86	87	88	89	90	91	92	93	94	95	96	97	98	99	100
----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	-----



KURINGA DR

KURINGA DR

KINGSFORD SMITH DR

ACCIDENT DATA PERIOD  
01-01-2004 TO 31-12-2008

DATE: 01/01/2009  
DRAWN BY: J. SMITH  
CHECKED BY: J. SMITH  
SCALE: AS SHOWN  
PROJECT NO: C09051-A001+

CLIENT: Roads ACT  
PROJECT: BLACKSPOT FEASIBILITY STUDY 2009 - 2010

BLACKSPOT FEASIBILITY STUDY 2009 - 2010

FOR DISCUSSION PURPOSES ONLY

REV	DATE	BY	CHKD	DESC
A	01/01/09	J.S.	J.S.	ISSUE FOR DISCUSSION
B				
C				
D				
E				
F				

SCALE 1:200  
SCALE 1:100

CLIENT: Roads ACT  
PROJECT: BLACKSPOT FEASIBILITY STUDY 2009 - 2010

FOR DISCUSSION PURPOSES ONLY

DATE: 01/01/2009  
DRAWN BY: J. SMITH  
CHECKED BY: J. SMITH  
SCALE: AS SHOWN  
PROJECT NO: C09051-A001+



---

**APPENDIX D**

**OPINION OF COSTS AND  
BENEFIT COST ANALYSIS**

**BLACK SPOT FEASIBILITY STUDY  
FINAL REPORT**



**Kingsford Smith Drive / Kuringa Drive Opinion of Cost 15/10/2009**

	SUMMARY	UNIT	QTY	RATE	AMOUNT
0	Preliminaries				\$1,800.00
1	Provision For Traffic				\$1,000.00
2	Earthworks				\$800.00
10	Road Signs				\$1,730.00
11	Pavement Marking				\$991.40
	<b>TOTAL LUMP SUM Cost Estimate</b>				<b>\$7,000.00</b>
	<b>Including 30% Contingency</b>				<b>\$10,000.00</b>

Page 1

- Notes:
1. Estimate is based on current market rates as per recent tender assessments made by Brown Consulting
  2. Service Relocations includes Provisional sums for works by Agility, ActewAGL and Telstra

# BLACK SPOT FEASIBILITY STUDY FINAL REPORT



## ACT TRANSPORT CAPITAL WORKS PROGRAMME DISCOUNTED CASH FLOW ANALYSIS - USER GUIDE TEMPLATE

### 10 year time horizon

BASIC DISCOUNTED CASH FLOW ANALYSIS TO BE USED IN ACCORDANCE WITH THE CAPITAL WORKS PROGRAMMING GUIDELINES and APPENDIX B - Social Audit of Transport Projects.

This Table calculates the Present Value of various cost and benefit streams entered by the ANALYST in accordance with the procedures described in Appendix B of the Manual. The Discounted Cash Flow Analysis table needs to be completed for each option being analysed, including, where appropriate, the Base Case.

PROJECT NAME = Kuringa Drive / Kingsford Smith Drive PROJECT ID No = C09051  
 OPTION = Opt 1 Stop control and Improved separation on E approach ANALYSIS DATE = 15-Oct-09

DISCOUNTED CASH FLOW ANALYSIS FOR 10-YEAR TIME HORIZON											
Discount Rate:		7.0%		4.0%		10.0%					
Traffic (Benefit) Growth Rate:		1.0%		1.0%		1.0%					
YEAR	COSTS (show as +ve)				BENEFITS (show as +ve)			OTHER BENEFITS		TOTALS (Sum of Columns A to F) (\$'000)	
	CAPITAL (\$'000) Column A	RECURRENT Annual Operating (\$'000) Column B	RECURRENT Maintenance Annual (\$'000) Column C	RECURRENT Cyclic (\$'000) Column D	Vehicle Operating Cost Savings (\$'000) Column E	Travel Time Savings (\$'000) Column F	Accident Cost Savings (\$'000) Column G	(\$'000) Column H	(\$'000) Column I		Column J
2010	(\$6)	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	(\$6)	
2011	\$0	\$0	(\$2)	\$0	\$0	\$0	\$40	\$0	\$0	\$38	
2012	\$0	\$0	(\$2)	\$0	\$0	\$0	\$40	\$0	\$0	\$38	
2013	\$0	\$0	(\$2)	\$0	\$0	\$0	\$40	\$0	\$0	\$38	
2014	\$0	\$0	(\$2)	\$0	\$0	\$0	\$41	\$0	\$0	\$39	
2015	\$0	\$0	(\$2)	\$0	\$0	\$0	\$41	\$0	\$0	\$39	
2016	\$0	\$0	(\$2)	\$0	\$0	\$0	\$42	\$0	\$0	\$40	
2017	\$0	\$0	(\$2)	\$0	\$0	\$0	\$42	\$0	\$0	\$40	
2018	\$0	\$0	(\$2)	\$0	\$0	\$0	\$43	\$0	\$0	\$41	
2019	\$0	\$0	(\$2)	\$0	\$0	\$0	\$43	\$0	\$0	\$41	
2020	\$0	\$0	(\$2)	\$0	\$0	\$0	\$43	\$0	\$0	\$41	
<b>Total</b>	<b>(\$6)</b>	<b>\$0</b>	<b>(\$20)</b>	<b>-\$0</b>	<b>\$0</b>	<b>\$0</b>	<b>\$415</b>	<b>\$0</b>	<b>\$0</b>	<b>\$389</b>	
CALCULATED PRESENT VALUE (PV)										<b>NETT PV</b>	
DATE OF ANALYSIS = 15-Oct-09										<b>\$270</b>	
PV @ 7%										<b>\$270</b>	
Checksum = 0?											
Sensitivity Test Discount Rates											
PV @ 4%										<b>\$313</b>	
PV @ 10%										<b>\$235</b>	
										<b>BCR @ 7%</b>	<b>14.50</b>
										<b>BCR @ 4%</b>	<b>15.27</b>
										<b>BCR @ 10%</b>	<b>14.06</b>
										<b>NPV/CC @ 6%</b>	<b>45.76</b>
										<b>NPV/CC @ 4%</b>	<b>53.05</b>
										<b>NPV/CC @ 10%</b>	<b>39.83</b>

# BLACK SPOT FEASIBILITY STUDY FINAL REPORT



## ACT TRANSPORT CAPITAL WORKS PROGRAMME DISCOUNTED CASH FLOW ANALYSIS - USER GUIDE TEMPLATE

### 10 year time horizon

BASIC DISCOUNTED CASH FLOW ANALYSIS TO BE USED IN ACCORDANCE WITH THE CAPITAL WORKS PROGRAMMING GUIDELINES and APPENDIX B - Social Audit of Transport Projects.

This Table calculates the Present Value of various cost and benefit streams entered by the ANALYST in accordance with the procedures described in Appendix B of the Manual. The Discounted Cash Flow Analysis table needs to be completed for each option being analysed, including, where appropriate, the Base Case.

PROJECT NAME = Kuringa Drive / Kingsford Smith Drive PROJECT ID No = C09051  
OPTION = Option 2 - All treatments ANALYSIS DATE = 15-Oct-09

YEAR	COSTS (show as -ve)				BENEFITS (show as +ve)			OTHER BENEFITS		TOTALS (sum of Columns A to F) (\$'000)
	CAPITAL (\$'000) Column A	RECURRENT Annual Operating (\$'000) Column B	RECURRENT Maintenance Annual (\$'000) Column C	RECURRENT Cyclic (\$'000) Column D	Vehicle Operating Cost Savings (\$'000) Column E	Travel Time Savings (\$'000) Column F	Accident Cost Savings (\$'000) Column G	(\$'000) Column H	(\$'000) Column I	
2010	(\$10)	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	(\$10)
2011	\$0	\$0	(\$2)	\$0	\$0	\$0	\$40	\$0	\$0	\$38
2012	\$0	\$0	(\$2)	\$0	\$0	\$0	\$40	\$0	\$0	\$38
2013	\$0	\$0	(\$2)	\$0	\$0	\$0	\$40	\$0	\$0	\$38
2014	\$0	\$0	(\$2)	\$0	\$0	\$0	\$41	\$0	\$0	\$39
2015	\$0	\$0	(\$2)	\$0	\$0	\$0	\$41	\$0	\$0	\$39
2016	\$0	\$0	(\$2)	\$0	\$0	\$0	\$42	\$0	\$0	\$40
2017	\$0	\$0	(\$2)	\$0	\$0	\$0	\$42	\$0	\$0	\$40
2018	\$0	\$0	(\$2)	\$0	\$0	\$0	\$43	\$0	\$0	\$41
2019	\$0	\$0	(\$2)	\$0	\$0	\$0	\$43	\$0	\$0	\$41
2020	\$0	\$0	(\$2)	\$0	\$0	\$0	\$43	\$0	\$0	\$41
Total	(\$10)	\$0	(\$20)	\$0	\$0	\$0	\$415	\$0	\$0	\$385
CALCULATED PRESENT VALUE (PV)										NETT PV \$266
FV @ 7%	(\$10)	\$0	(\$14)	\$0	\$0	\$0	\$290	\$0	\$0	
Sensitivity Test Discount Rates										Checksum = 0?
FV @ 4%	(\$10)	\$0	(\$16)	\$0	\$0	\$0	\$336	\$0	\$0	
FV @ 10%	(\$10)	\$0	(\$12)	\$0	\$0	\$0	\$253	\$0	\$0	

BCR @ 7%	12.08
BCR @ 4%	12.92
BCR @ 10%	11.50
NPV/CC @ 6%	26.60
NPV/CC @ 4%	30.90
NPV/CC @ 10%	23.10



# Street History Report

Printed for: Mazur, Gosia

6-Oct-2011


Street History for : KURINGA DR

Accident date between 01/01/2008 and 31/07/2011

Police Reference	Date/time	Severity	Injury Type	Acc. Type	Num Cas	Num Veh	Direction	Lane	Position	Movement	Rum Code	Weather	Road Surface	Visibility Restrictions
<b>Intersection 3347 BARTON HWY, KURINGA DR, 3347</b>														
2008-9130854	05/01/08 13:00	Property Damage C		6	0	2	North bound	1st (kerb or left) lane	Good dry surface	Fine	301		Approaching Intersection	Not obstructed
				2	0	2	North bound	1st (kerb or left) lane	Within Intersection	Right turn			Right turn	Not obstructed
2008-9205923	02/03/08 11:50	Property Damage C		2	0	2	North bound	Right turn lane	Good dry surface	Fine	105		Within Intersection	Not obstructed
				2	0	2	East bound	Right turn lane	Within Intersection	Right turn			Within Intersection	Not obstructed
2008-9191039	06/06/08 18:20	Property Damage C		2	0	2	West bound	Right turn lane	Good dry surface	Fine	102		Within Intersection	Not obstructed
				2	0	2	North bound	1st (kerb or left) lane	Within Intersection	Right turn			Within Intersection	Not obstructed
2008-9271115	26/06/08 16:15	Property Damage C		6	0	2	East bound	Right turn lane	Good dry surface	Fine	303		Within Intersection	Not obstructed
				2	0	2	East bound	Right turn lane	Within Intersection	Right turn			Within Intersection	Not obstructed
2008-3801715	29/06/08 20:00	Property Damage C		2	0	2	East bound	Right turn lane	Good dry surface	Fine	102		Within Intersection	Not obstructed
				2	0	2	South bound	1st (kerb or left) lane	Within Intersection	Right turn			Within Intersection	Not obstructed
2009-9294907	05/03/09 11:10	Property Damage C		6	0	2	East bound	Right turn lane	Good dry surface	Fine	303		Within Intersection	Not obstructed
				2	0	2	East bound	Right turn lane	Within Intersection	Right turn			Within Intersection	Not obstructed
2009-0070595	30/04/09 08:15	Injury	Received medical treatment	2	3	2	South bound	Right turn lane	Good dry surface	Fine	105		Within Intersection	Not known
				2	0	2	East bound	Right turn lane	Within Intersection	Right turn			Within Intersection	Not obstructed
2009-0949134	17/06/09 18:00	Property Damage C		6	0	2	East bound	Right turn lane	Good dry surface	Fine	303		Within Intersection	Not known
				2	0	2	East bound	Right turn lane	Within Intersection	Right turn			Within Intersection	Not known
2009-9101214	27/07/09 08:20	Property Damage C		6	0	2	East bound	Right turn lane	Good dry surface	Fine	303		Within Intersection	Not known
				2	0	2	East bound	Right turn lane	Within Intersection	Right turn			Within Intersection	Not known
2009-9912102	28/07/09 07:45	Property Damage C		2	0	2	East bound	Right turn lane	Good dry surface	Fog	105		Within Intersection	Not known
				2	0	2	South bound	Right turn lane	Within Intersection	Right turn			Within Intersection	Not known

This report includes all "on road" accidents or injuries, "onroad" is defined as being from property boundary to property boundary





# Street History Report

Printed for: Mazur, Gosia

6-Oct-2011

Street History for : KURINGA DR

Accident date between 01/01/2008 and 31/07/2011

Police Reference	Date/time	Severity	Injury Type	Acc. Type	Num Cas	Num Veh	Veh Num	Direction	Lane	Position	Road Surface	Weather	Rum Code	Visibility	Restrictions
<b>Intersection 3347 BARTON HWY, KURINGA DR, 3347</b>															
2009-9121010	13/08/09	18:15	Property Damage C	2	0	2									
				1	North bound				2nd lane	Good dry surface	Fine	104		Not known	
				2	East bound				Right turn lane	Approaching Intersection	Approaching Intersection	Straight ahead		Not known	
2009-9162123	28/10/09	18:45	Property Damage C	2	0	2									
				1	East bound				Right turn lane	Within Intersection	Good dry surface	Fine	104	Not known	
				2	North bound				1st (kerb or left) lane	Within Intersection	Within Intersection	Right turn		Not known	
2009-9210821	02/11/09	17:45	Property Damage C	1	0	2									
				1	South bound				Right turn lane	Within Intersection	Good dry surface	Fine	202	Not known	
				2	North bound				1st (kerb or left) lane	Approaching Intersection	Approaching Intersection	Straight ahead		Not known	
2009-9221225	15/11/09	08:15	Property Damage C	2	0	2									
				1	East bound				Right turn lane	Within Intersection	Good dry surface	Fine	105	Not known	
				2	South bound				2nd lane	Approaching Intersection	Approaching Intersection	Right turn		Not known	
2009-9159214	18/11/09	06:20	Injury	2	1	2									
				1	East bound				Right turn lane	Within Intersection	Good dry surface	Fine	104	Not obstructed	
				2	North bound				1st (kerb or left) lane	Approaching Intersection	Approaching Intersection	Straight ahead		Not known	
2010-2132916	03/01/10	18:00	Property Damage C	2	0	2									
				1	East bound				Right turn lane	Within Intersection	Good dry surface	Fine	105	Not obstructed	
				2	South bound				Right turn lane	Within Intersection	Within Intersection	Right turn		Not obstructed	
2010-1130129	04/02/10	14:15	Property Damage C	6	0	2									
				1	East bound				Right turn lane	Within Intersection	Wet surface	Light rain	303	Not obstructed	
				2	East bound				Right turn lane	Within Intersection	Within Intersection	Right turn		Not obstructed	
				2	South bound				Right turn lane	Within Intersection	Within Intersection	Right turn		Not known	
2010-3115114	29/03/10	17:10	Property Damage C	2	0	2									
				1	South bound				Right turn lane	Within Intersection	Good dry surface	Fine	105	Not obstructed	
				2	East bound				Right turn lane	Within Intersection	Within Intersection	Right turn		Not obstructed	
2010-1110092	04/07/10	20:30	Property Damage C	2	0	2									
				1	North bound				1st (kerb or left) lane	Within Intersection	Good dry surface	Fine	104	Not obstructed	
				2	East bound				Right turn lane	Within Intersection	Within Intersection	Straight ahead		Not obstructed	
2010-3250111	18/10/10	08:00	Injury	15	1	1									
				1	North bound				1st (kerb or left) lane	Within Intersection	Good dry surface	Fine	706	Not obstructed	
2011-1125350	28/03/11	07:40	Property Damage C	2	0	2									
				1	South bound				Right turn lane	Within Intersection	Good dry surface	Fine	105	Not obstructed	

This report includes all "on road" accidents or injuries, "onroad" is defined as being from property boundary to property boundary





# Street History Report

Printed for: Mazur, Gosia

6-Oct-2011

Street History for : KURINGA DR

Accident date between 01/01/2008 and 31/07/2011

Police Reference	Date/time	Severity	Injury Type	Acc. Type	Num Cas	Num Veh	Veh Num	Direction	Lane	Position	Road Surface	Weather	Rum Code	Visibility Restrictions	
<b>Intersection 3347 KURINGA DR, BARTON HWY, 3347</b>															
2011-1125350	28/03/11	07:40	Property Damage C	2	0	2	2	0	2	East bound	Right turn lane	Good dry surface	Fine	105	Other
				2						Within intersection					
2011-2156054	17/04/11	01:20	Property Damage C	6	0	2	6	0	2	East bound	Right turn lane	Good dry surface	Fine	303	Not obstructed
				1			1			East bound	Right turn lane	Within intersection			Not obstructed
				2			2			Within intersection					
2011-3150603	19/04/11	08:20	Property Damage C	6	0	2	6	0	2	North bound	Left turn lane	Good dry surface	Fine	302	Not obstructed
				1			1			North bound	Left turn lane	Within intersection			Not obstructed
				2			2			Within intersection					
2011-2023254	26/04/11	23:25	Property Damage C	2	0	2	2	0	2	East bound	Right turn lane	Good dry surface	Fine	104	Other
				1			1			East bound	Right turn lane	Within intersection			Other
				2			2			Approaching intersection					
2011-3150604	03/05/11	17:10	Property Damage C	6	0	2	6	0	2	East bound	Right turn lane	Good dry surface	Fine	303	Not obstructed
				1			1			East bound	Right turn lane	Within intersection			Not obstructed
				2			2			Within intersection					
2011-1150902	15/05/11	09:45	Property Damage C	6	0	2	6	0	2	North bound	Left turn lane	Good dry surface	Fine	302	Other
				1			1			North bound	Left turn lane	Within intersection			Other
				2			2			Within intersection					
<b>Total Accidents: 26</b>															
<b>Intersection 5139 KURINGA DR, KINGSFORD SMITH DR, 5139</b>															
2008-9101319	08/01/08	17:30	Property Damage C	6	0	3	6	0	3	East bound	1st (kerb or left) lane	Good dry surface	Fine	301	Not obstructed
				1			1			East bound	1st (kerb or left) lane	Within intersection			Not obstructed
				2			2			East bound	1st (kerb or left) lane	Within intersection			Not obstructed
				3			3			East bound	1st (kerb or left) lane	Within intersection			Not obstructed
2008-9061501	19/01/08	11:00	Property Damage C	6	0	2	6	0	2	North bound	1st (kerb or left) lane	Good dry surface	Fine	301	Not obstructed
				1			1			North bound	1st (kerb or left) lane	Approaching intersection			Not obstructed
				2			2			North bound	1st (kerb or left) lane	Approaching intersection			Not obstructed

This report includes all "on road" accidents or injuries, "onroad" is defined as being from property boundary to property boundary





# Street History Report

Printed for: Mazur, Gosia

6-Oct-2011


Street History for : KURINGA DR

Accident date between 01/01/2008 and 31/07/2011

Police Reference	Date/time	Severity	Injury Type	Acc. Type	Num Cas	Num Veh	Veh Num	Direction	Lane	Position	Movement	Rum Code	Weather	Visibility Restrictions
<b>Intersection 5139 KURINGA DR, KINGSFORD SMITH DR, 5139</b>														
2008-9261352	20/01/08 12:00	Property Damage C		6	0	2				Good dry surface	Fine	301		
				1					Right turn lane	Within Intersection	Straight ahead			Not obstructed
				2					Right turn lane	Within Intersection	Straight ahead			Not obstructed
2008-9171214	18/09/08 22:15	Property Damage C		15	0	1				Good dry surface	Fine	706		
				1					1st (kerb or left) lane	Within Intersection	Left turn			Not obstructed
2008-3853833	27/10/08 08:10	Injury	Admitted to hospital	2	3	3				Good dry surface	Fine	102		
				1					1st (kerb or left) lane	Within Intersection	Straight ahead			Not obstructed
				2					North bound	Within Intersection	Right turn			Not obstructed
				3					West bound	Within Intersection	Straight ahead			Not obstructed
2008-9253852	20/11/08 17:30	Property Damage C		2	0	2				Good dry surface	Fine	102		
				1					East bound	Within Intersection	Straight ahead			Not obstructed
				2					North bound	Within Intersection	Right turn			Not obstructed
2008-9203912	20/12/08 17:30	Property Damage C		2	0	2				Good dry surface	Fine	102		
				1					North bound	Within Intersection	Right turn			Not obstructed
				2					East bound	Within Intersection	Straight ahead			Not obstructed
2009-0736413	28/05/09 17:30	Property Damage C		1	0	2				Good dry surface	Fine	202		
				1					West bound	Within Intersection	Straight ahead			Not known
				2					East bound	Within Intersection	Right turn			Not known
2009-9268253	22/06/09 17:30	Property Damage C		2	0	2				Good dry surface	Fine	102		
				1					East bound	Approaching Intersection	Straight ahead			Not known
				2					North bound	Within Intersection	Right turn			Not known
2009-9262940	11/09/09 08:00	Property Damage C		2	0	2				Good dry surface	Fine	102		
				1					North bound	Within Intersection	Right turn			Not known
				2					East bound	Within Intersection	Straight ahead			Not known
2009-9222104	09/10/09 11:20	Property Damage C		2	0	2				Good dry surface	Fine	102		
				1					East bound	Within Intersection	Straight ahead			Not known
				2					North bound	Within Intersection	Right turn			Not known
2009-9181222	15/11/09 10:30	Property Damage C		2	0	2				Good dry surface	Fine	105		
				1					East bound	Within Intersection	Right turn			Not known
				2					North bound	Within Intersection	Right turn			Not known

This report includes all "on road" accidents or injuries, "onroad" is defined as being from property boundary to property boundary





# Street History Report

Printed for: Mazur, Gosia

6-Oct-2011


Street History for : KURINGA DR

Accident date between 01/01/2008 and 31/07/2011

Police Reference	Date/time	Severity	Injury Type	Acc. Type	Num Cas	Num Veh	Veh Num	Direction	Lane	Position	Movement	Weather	Rum Code	Visibility	Restrictions
<b>Intersection 5139 KINGSFORD SMITH DR, KURINGA DR, 5139</b>															
2010-2220540	12/10/10	08:30	Property Damage C	2	0	2				Good dry surface	Fine		104		
				1	West bound				1st (kerb or left) lane	Within intersection	Straight ahead			Not obstructed	
				2	North bound				Right turn lane	Within intersection	Right turn			Not obstructed	
2011-1182516	10/03/11	17:10	Property Damage C	6	0	2				Good dry surface	Fine		303		
				1	North bound				Right turn lane	Within intersection	Right turn			Not known	
				2	North bound				Right turn lane	Within intersection	Right turn			Not obstructed	
<b>Total Accidents: 14</b>															
<b>Intersection 5140 KURINGA DR, OWEN DIXON DR, 5140</b>															
2008-9122103	10/10/08	18:20	Property Damage C	6	0	3				Good dry surface	Fine		301		
				1	East bound				1st (kerb or left) lane	Within intersection	Straight ahead			Not obstructed	
				2	East bound				1st (kerb or left) lane	Within intersection	Straight ahead			Glare or dazzle	
				3	East bound				1st (kerb or left) lane	Within intersection	Straight ahead			Glare or dazzle	
2009-0736423	28/05/09	18:00	Property Damage C	1	0	2				Good dry surface	Fine		202		
				1	West bound				1st (kerb or left) lane	Within intersection	Straight ahead			Not obstructed	
				2	East bound				1st (kerb or left) lane	Within intersection	Right turn			Not known	
2010-0314857	29/01/10	17:30	Property Damage C	6	0	2				Good dry surface	Fine		303		
				1	West bound				1st (kerb or left) lane	Approaching intersection	Straight ahead			Not known	
				2	West bound				1st (kerb or left) lane	Within intersection	Right turn			Not obstructed	
2010-2208575	13/08/10	14:35	Injury	5	1	2				Good dry surface	Fine		201		
				1	West bound				1st (kerb or left) lane	Approaching intersection	Straight ahead			Not obstructed	
				2	West bound				1st (kerb or left) lane	Within intersection	Right turn			Not obstructed	
2010-3131012	12/09/10	15:00	Property Damage C	1	0	2				Good dry surface	Fine		202		
				1	East bound				1st (kerb or left) lane	Within intersection	Right turn			Not obstructed	
				2	West bound				1st (kerb or left) lane	Within intersection	Straight ahead			Not obstructed	
2010-3010213	21/11/10	17:15	Property Damage C	6	0	2				Good dry surface	Fine		303		
				1	East bound				1st (kerb or left) lane	Approaching intersection	Straight ahead			Not obstructed	

This report includes all "on road" accidents or injuries, "onroad" is defined as being from property boundary to property boundary





# Street History Report

Printed for: Mazur, Gosia

6-Oct-2011

Street History for : KURINGA DR

Accident date between 01/01/2008 and 31/07/2011

Police Reference	Date/time	Severity	Injury Type	Acc. Type	Num Cas	Num Veh	Veh Num	Direction	Lane	Position	Road Surface	Weather	Movement	Rum Code	Visibility Restrictions
<b>Intersection 5140 KURINGA DR, OWEN DIXON DR, 5140</b>															
2010-3010213	21/11/10	17:15	Property Damage C	6	0	2		East bound	1st (kefb or left) lane	Good dry surface	Within Intersection	Fine	Right turn	303	Not obstructed
				2											
<b>Total Accidents: 6</b>															


<b>Midblock 5404 KURINGA DR, KINGSFORD SMITH DR, OWEN DIXON DR</b>															
2009-9021542	02/11/08	17:40	Property Damage C	19	0	1		West bound	1st (kefb or left) lane	Good dry surface	Not related to Intersection	Fine	Straight ahead	705	Not obstructed
2009-9021537	02/12/08	12:55	Property Damage C	13	0	1		West bound	Shoulder	Good dry surface	Not related to Intersection	Fine	Straight ahead	705	Not obstructed
<b>Total Accidents: 2</b>															

## Midblock 5405 KURINGA DR, KINGSFORD SMITH DR, TILLYARD DR

2008-0592392	18/01/08	18:00	Property Damage C	15	0	1		West bound	1st (kefb or left) lane	Wet surface	Not related to Intersection	Heavy rain	Straight ahead	705	Not obstructed
2008-9121114	19/01/08	23:30	Property Damage C	21	0	1		West bound	1st (kefb or left) lane	Good dry surface	Not related to Intersection	Fine	Straight ahead	705	Not obstructed
2008-9294092	09/03/08	17:00	Property Damage C	19	0	1		West bound	1st (kefb or left) lane	Good dry surface	Within Intersection	Fine	Straight ahead	803	Not obstructed
2008-9021141	16/08/08	00:50	Property Damage C	19	0	1		North bound	Shoulder	Good dry surface	Not related to Intersection	Fine	Straight ahead	804	Not obstructed
2008-9252325	10/09/08	07:45	Property Damage C	6	0	2		West bound	1st (kefb or left) lane	Good dry surface	Not related to Intersection	Fine	Straight ahead	301	Not obstructed
				1				West bound	1st (kefb or left) lane	Not related to Intersection	Not related to Intersection				Not obstructed
				2				West bound	1st (kefb or left) lane	Not related to Intersection	Not related to Intersection				Not obstructed

This report includes all "on road" accidents or injuries, "onroad" is defined as being from property boundary to property boundary





# Street History Report

Printed for: Mazur, Gosia

6-Oct-2011

Street History for : KURINGA DR

Accident date between 01/01/2008 and 31/07/2011

Police Reference	Date/time	Severity	Injury Type	Acc. Type	Num Cas	Num Veh	Veh Num	Direction	Lane	Position	Weather	Rum Code	Visibility Restrictions
<b>Midblock 5405 KURINGA DR, KINGSFORD SMITH DR, TILLYARD DR</b>													
2008-0676150	31/10/08 11:54	Property Damage C		21	0	1				Good dry surface	Fine	701	
				1				East bound	1st (kerb or left) lane	Not related to intersection	Straight ahead		Not obstructed
2009-0131067	02/05/09 09:50	Injury	Received medical treatment	19	1	1				Good dry surface	Fine	804	
				1				West bound	1st (kerb or left) lane	Not related to intersection	Straight ahead		Not obstructed
2009-3947657	21/05/09 23:50	Property Damage C		21	0	1				Wet surface	Heavy rain	802	
				1				West bound	1st (kerb or left) lane	Not related to intersection	Straight ahead		Other
2009-3957113	07/06/09 03:23	Fatality	Fatal	19	1	1				Wet surface	Light rain	804	
				1				West bound	1st (kerb or left) lane	Not related to intersection	Straight ahead		Not obstructed
2009-9258111	21/06/09 09:30	Property Damage C		19	0	1				Wet surface	Light rain	803	
				1				West bound	1st (kerb or left) lane	Not related to intersection	Straight ahead		Not known
2009-3989551	28/07/09 03:30	Property Damage C		21	0	1				Good dry surface	Fine	801	
				1				East bound	1st (kerb or left) lane	Not related to intersection	Straight ahead		Not obstructed
2009-9163616	25/12/09 19:51	Property Damage C		21	0	1				Wet surface	Heavy rain	803	
				1				West bound	1st (kerb or left) lane	Not related to intersection	Straight ahead		Windscreen, fog, etc
2010-2154840	23/01/10 12:00	Property Damage C		13	0	1				Good dry surface	Fine	805	
				1				West bound	1st (kerb or left) lane	Not related to intersection	Straight ahead		Not known
2010-2062524	12/02/10 03:00	Property Damage C		21	0	1				Wet surface	Light rain	802	
				1				West bound	1st (kerb or left) lane	Not related to intersection	Straight ahead		Not known
2010-0345926	13/02/10 20:40	Property Damage C		19	0	1				Wet surface	Light rain	703	
				1				West bound	1st (kerb or left) lane	Not related to intersection	Straight ahead		Not obstructed
2010-4141827	08/03/10 12:00	Property Damage C		21	0	1				Wet surface	Heavy rain	801	
				1				West bound	1st (kerb or left) lane	Not related to intersection	Straight ahead		Not obstructed
2010-2168435	24/04/10 20:10	Injury	Admitted to hospital	21	2	1				Wet surface	Heavy rain	802	
				1				West bound	1st (kerb or left) lane	Not related to intersection	Straight ahead		Not obstructed
2010-2084987	05/06/10 14:05	Injury	Admitted to hospital	15	1	1				Good dry surface	Fine	805	
				1				West bound	1st (kerb or left) lane	Not related to intersection	Right turn		Not obstructed
2010-2179332	19/06/10 21:17	Property Damage C		11	0	1				Good dry surface	Fine	609	
				1				West bound	1st (kerb or left) lane	Not related to intersection	Straight ahead		Not obstructed

This report includes all "on road" accidents or injuries, "onroad" is defined as being from property boundary to property boundary





# Street History Report

Printed for: Mazur, Gosia

6-Oct-2011

Street History for : KURINGA DR

Accident date between 01/01/2008 and 31/07/2011


Police Reference	Datetime	Severity	Injury Type	Acc. Type	Num Cas	Num Veh	Veh Num	Direction	Lane	Position	Road Surface	Weather	Movement	Rum Code	Visibility Restrictions
<b>Midblock 5405 KURINGA DR, TILLYARD DR, KINGSFORD SMITH DR</b>															
2010-2102396	11/11/10 17:00	Injury	Received medical treatment	13	1	1			1st (kerb or left) lane	Good dry surface	Not related to intersection	Fine	Straight ahead	805	Not obstructed
				1					West bound						
2010-2107346	30/11/10 15:00	Injury	Received medical treatment	13	1	1			1st (kerb or left) lane	Wet surface	Not related to intersection	Light rain	Straight ahead	805	Not obstructed
				1					West bound						
2010-2180213	05/12/10 13:40	Injury	Received medical treatment	20	1	1			1st (kerb or left) lane	Good dry surface	Not related to intersection	Fine	Straight ahead	805	Not obstructed
				1					West bound						
2010-2214918	12/12/10 02:45	Injury	Received medical treatment	19	1	1			1st (kerb or left) lane	Good dry surface	Not related to intersection	Fine	Straight ahead	704	Not obstructed
				1					West bound						
2010-3110209	19/12/10 14:30	Property Damage C		20	0	1			1st (kerb or left) lane	Wet surface	Not related to intersection	Heavy rain	Straight ahead	801	Not obstructed
				1					East bound						
2011-2209405	01/02/11 14:09	Injury	Admitted to hospital	13	2	1			1st (kerb or left) lane	Good dry surface	Not related to intersection	Fine	Straight ahead	805	Not obstructed
				1					West bound						
<b>Total Accidents: 25</b>															

## Midblock 5406 KURINGA DR, BARTON HWY, OWEN DIXON DR

2008-9161146	14/04/08 12:00	Property Damage C		3	0	2			Merge lane	Good dry surface	Approaching intersection	Fine	Straight ahead	305	Not obstructed
				1					North bound						
				2					3rd lane						Not obstructed
2008-9191112	06/06/08 06:00	Property Damage C		19	0	1			1st (kerb or left) lane	Good dry surface	Not related to intersection	Fine	Right turn	803	Not obstructed
				1					East bound						
2008-9172347	18/08/08 18:00	Property Damage C		19	0	1			1st (kerb or left) lane	Good dry surface	Not related to intersection	Fine	Straight ahead	703	Not known
				1					East bound						
2009-9192852	14/02/09 22:23	Injury	Received medical treatment	6	1	2			1st (kerb or left) lane	Good dry surface	Not related to intersection	Fine	Straight ahead	301	Not obstructed
				1					West bound						
				2					West bound						Not obstructed

This report includes all "on road" accidents or injuries, "onroad" is defined as being from property boundary to property boundary





# Street History Report

Printed for: Mazur, Gosia

6-Oct-2011

Street History for : KURINGA DR

Accident date between 01/01/2008 and 31/07/2011

Police Reference	Date/time	Severity	Injury Type	Acc. Type	Num Cas	Num Veh	Veh Num	Direction	Lane	Position	Road Surface	Weather	Rum Code	Visibility Restrictions
<b>Midblock 5406 KURINGA DR, OWEN DIXON DR, BARTON HWY</b>														
2010-2209695	11/03/10 04:19	Fatality	Fatal	5	2	2	1	South bound	On wrong side of road	Good dry surface	Fine	201	Not obstructed	
				2	North bound	1st. (kerb or left) lane			Not related to intersection	Not related to intersection	Light rain	803	Not obstructed	
2010-2013558	26/08/10 05:30	Property Damage C	19	0	1	1	North bound	1st. (kerb or left) lane	Wet surface	Not related to intersection	Light rain	803	Not obstructed	
<b>Total Accidents: 6</b>														



















































This report includes all "on road" accidents or injuries, "onroad" is defined as being from property boundary to property boundary



4.3 RUM Codes

00	10	20	30	40
PEDESTRIAN	INTERSECTION	VEHICLES FROM OPPOSING DIRECTIONS	VEHICLES FROM ONE DIRECTION	MANOEUVRING
Other 00	Other 10	Other 20	Other 30	Other 40
Near Side 001	Thru-Thru 101	Head On 201	Rear End 301	Leaving Parking 401
Emerging 002	Right-Thru 102	Thru-Right 202	Left-Rear 302	Parking 402
Far Side 003	Left-Thru 103	Right-Left 203	Right-Rear 303	Parking Vehicles Only 403
Praying, Working Standing On Carriageway 004	Thru-Right 104	Right-Right 204	U-Turn 304	Reversing In Traffic 404
Walking with traffic 005	Right-Right 105	Thru-Left 205	Lane side swipe 305	Reversing into fixed Object 405
Facing traffic 006	Left-Right 106	Left-Left 206	Lane change-Right 306	Leaving driveway 406
Driveway 007	Thru-Left 107	U-Turn 207	Lane change-Left 307	From loading bay 407
On footway 008	Right-Left 108	Right turn s/s 208	Right turn s/s 308	From footway 408
Struck while boarding Or alighting 009	Left-Left 109	Left turn s/s 209	Left turn s/s 309	Pulling out 310



50	60	70	80	90
OVERTAKING	ON PATH	OFF PATH, ON STRAIGHT	OFF PATH, ON CURVE	PASSENGERS & MISCELLANEOUS
Other 50	Other 60	Other 70	Other 80	Other 90
				
Head On 501	Parked 601	Off Carriageway to Left 701	Off Carriageway Right Bend 801	Fell In/From Moving Vehicle 901
				
Out Of Control 502	Double Parked 602	Off Carriageway to Right 702	Off Carriageway Left Bend 802	902
				
Pulling Out 503	Accident Or Broken Down 603	Left Off Carriageway into Object 703	Off Right Bend into object 803	Hit Train 903
				
Cutting In 504	Car door 604	Right off Carriageway into object 704	Off Left Bend into Object 804	Hit Railway Crossing Furniture 904
				
Pulling out Rear End 505	Hit Permanent Obstruction 605	Out of Control On Carriageway 705	Out of Control on Carriageway 805	Hit Animal Off Carriageway 905
				
Overtaking Right Turn 506	Hit Road Works 606	Left turn 706	806	Parked Vehicle Ran Away 906
				
507	Hit Temporary Object on Carriageway 607	Right turn 707	807	Vehicle Movements Unknown 907
				
508	608	Mounts Traffic Island 708	Mounts Traffic Island 808	908
				
509	Hit Animal 609	709	809	909
				
	Load hits vehicle 610			



**Type of Accident**

**Vehicle to Vehicle Collision**

- 01 Right turn into oncoming vehicle
- 02 Right angle collision
- 03 Acute angle-same direction
- 04 Acute angle-opposite direction
- 05 Head on collision
- 06 Rear-end collision
- 07 Collision with parked vehicle
- 08 Collision with one vehicle reverses.
- 09 Other - describe in remarks

**Single Vehicle Collision - (On Carriageway)**

- 10 Struck pedestrian
- 11 Struck animal
- 12 Struck object
- 13 Overturned
- 14 Fall from moving vehicle
- 15 Other accident - describe in remarks

**Single Vehicle Collision - (Off Carriageway)**

- 16 Struck pedestrian
- 17 Struck vehicle
- 18 Struck animal
- 19 Struck object
- 20 Overturned
- 21 No object struck
- 22 Other accident - describe in remarks

Please select the appropriate value

--	--



ENQUIRY MANAGER (Actions: QUSANB1111)

ID: 661145    Status: CO    Complete    Source:  Telephone    Admin Unit:  ACT     Open Enquiries     All Enquiries  
 Recorded By: MFR | Michelle Richter    Responsibility Of: RMS | Road Maintenance Service  
 Enquiry Details:  Further Details     Actions     Damage     Associations     Letters

Name: \_\_\_\_\_    Type: ENQUIRER    Ref: \_\_\_\_\_  
 Organisation: PLACE MANAGEMENT - GUNGAHLIN OPERATIONS - NICHOLLS    Email: \_\_\_\_\_    Home: \_\_\_\_\_    Flag: \_\_\_\_\_  
 Postcode: \_\_\_\_\_    Number: \_\_\_\_\_    Building: \_\_\_\_\_    Sub: \_\_\_\_\_    Work: 6207 2585    Mobile: \_\_\_\_\_  
 Street: \_\_\_\_\_    Local: \_\_\_\_\_    Fax: \_\_\_\_\_    Primary Contact:   
 Dependant Street: \_\_\_\_\_    Property Type: \_\_\_\_\_  
 Town: \_\_\_\_\_  
 County: \_\_\_\_\_

Category: REQS    Request for Services    Class: SSGN    Street, Warn, Haz, Park, Other  
 Enquiry Type: DMG    Damaged  
 Location: Kurunga Drive and Kingsford Smith Drive, Fraser/Spence  
 Description: A car accident has knocked down the traffic/street signs at the above intersection.  
 Action/Remarks: completed by T Smith on 22/06/11  
 Injuries: \_\_\_\_\_  
 Damage: \_\_\_\_\_

Date Recorded: 06-JUN-2011 13:59    Incident Date & Time: 06-JUN-2011 12:42    Correspondence Date: \_\_\_\_\_    Corr Received Date: \_\_\_\_\_  
 Follow Up 1: \_\_\_\_\_    Acknowledgment: \_\_\_\_\_    Follow Up 2: \_\_\_\_\_    Follow Up 3: \_\_\_\_\_  
 Priority: 2    Target Date: 21-JUN-2011 12:42    Complete Date: 23-JUN-2011 08:21    Reference No: \_\_\_\_\_  
 Date/Time Arrived: \_\_\_\_\_    Reason for Late Arrival: \_\_\_\_\_  
 Associated Asset: SONG    SIGN GROUP - 900460076    Road Type: SECT    Closed:     Easting: 1204775 32614700194  
 Create: \_\_\_\_\_    Start: \_\_\_\_\_    End: \_\_\_\_\_    XSP: \_\_\_\_\_    Road: FRASER    Road: FRASER    Morning: 613825 3065050261  
 Get From Map: \_\_\_\_\_    FRASER



Defect Id **15025** Order By **Defect Id (Desc)**

Asset **SIGN GROUP - 900480060**

Road Section **BELCONNEN (RURAL)** XSP **Start Chain**

Road Desc **BELCONNEN (RURAL)**

Location **Kuringa Dr.**

Activity **SG Sign Groups**

Defect Type **SG26 SG - Hazard - Blade and Pole Damaged**

Defect Desc **hazard marker down**

Defect Status **COMPLETED**

Inspector **DOT** Inspection Batch **9744**

Initiation Type **PAT** Inspection Id **15025**

Priority **310** SISS **ALL**

Superseded ?  By

Update Inv ?  R  X **204054.1**

Roadstud Type  Y **614099.3**

Date Inspected **06/AUG/2009** **10:36** Special Instr **ASAP please comp**

Notice Printed  Notice Id

Date Repair Due **16/AUG/2009** Work Status

Date Instructed  Work Order

Target Complete  Work Sheet

Date Completed  Check Batch

Check Date  Check Result

Date Paid  Payment Id

Category **Permanent**  Perm  Inrm  Temp

Repair Desc

Treatment **SGAZ SG - Hazard - Replace Blade and Pole**

Total Cost

Item Code	Description	Dim 1	Dim 2	Dim 3	Quantity	Unit	Rate	Cost

BOQ Items

Edit Defect

Summary

Print



Defect Id: **21112** Order By: Defect Id (Desc)

Asset: LINKS - 1472

Road Section: SPENCE XSP Start Chain

Road Desc: SPENCE

Location: Kuringa Drive Spence

Activity: RP Road Pavement

Defect Type: RP01 RP - Pothole

Defect Desc: pothole that caused damage to car - after Kingsford Smith Drive.

Defect Status: COMPLETED

Recharge: Notice

Repair: Category: Permanent  Perm  Temp

Repair Desc: RPAH RP - Potholes - Coldmix

Total Cost: BOQ Items

Item Code	Description	Dim 1	Dim 2	Dim 3	Quantity	Unit	Rate	Cost

Inspector: MIG Initiation Type: NRM Priority: 310

Inspection Batch: 14589 Inspection Id: 21087

SISS: ALL

Superseded?  N  Y Update Inv?  X  Y Roadstud Type:  Y  N 673869.6

Date Inspected: 09/JUL/2010 15:19

Notice Printed: Special Instr: Claire Newman 043

Notice Id: Date Repair Due: 19/JUL/2010

Date Instructed: Work Status: Work Order: Work Sheet: Check Batch: Check Result: Payment Id:

Target Complete: Date Completed: 08/JUL/2011

Check Date: Date Paid:

Work Status: Work Order: Work Sheet: Check Batch: Check Result: Payment Id:

Check Date: Date Paid:

Work Status: Work Order: Work Sheet: Check Batch: Check Result: Payment Id:

Check Date: Date Paid:

Work Status: Work Order: Work Sheet: Check Batch: Check Result: Payment Id:

Check Date: Date Paid:

Work Status: Work Order: Work Sheet: Check Batch: Check Result: Payment Id:

Check Date: Date Paid:

Work Status: Work Order: Work Sheet: Check Batch: Check Result: Payment Id:

Check Date: Date Paid:

Work Status: Work Order: Work Sheet: Check Batch: Check Result: Payment Id:

Check Date: Date Paid:

Work Status: Work Order: Work Sheet: Check Batch: Check Result: Payment Id:

Check Date: Date Paid:

Work Status: Work Order: Work Sheet: Check Batch: Check Result: Payment Id:

[Edit Defect](#)
[Summary](#)
[Print](#)



Defect Id:  Order By:  Defect Id (Desc)

Asset: LINKS - 1559

Road Section: SCULLIN XSP Start Chain

Road Desc: SCULLIN

Location: Kurunga Drive from Fraser to Spence

Activity: RP Road Pavement

Defect Type: RPD1 RP - Polhole

Defect Desc: Potholes on the edge of the road

Defect Status: COMPLETED

Recharge:

Notify:

Repair:

Category: Permanent  Perm  Imm  Temp

Repair Desc: Coldmix

Treatment: RPAH RP - Potholes - Coldmix

Total Cost:

BOQ Items

Item Code Description Dim 1 Dim 2 Dim 3 Quantity Unit Rate Cost


View Asset

Inspector: JUD

Initiation Type: PE

Priority: 310

Inspection Batch: 15354

Inspection Id: 21966

SISS: ALL

Superseded?  N  Y

Update Inv?  R  X

Roadstud Type:

Date Inspected: 18/AUG/2010 06:34

Notice Printed:

Special Instr: Coldmix

Notice Id:

Date Repair Due: 25/AUG/2010

Date Instructed:

Target Complete:

Date Completed: 08/JUL/2011

Check Date:

Date Paid:

Work Status:

Work Order:

Work Sheet:

Check Batch:

Check Result:

Payment Id:



Defect Id: 24878 Order By: Defect Id (Desc)

Asset: BARRIER AND GUARDRAIL - VB00154

Road Section: FRASER XSP Start Chain

Road Desc: FRASER

Location: KURILINGA DR

Activity: BA Barrier

Defect Type: BA21 Barrier - W Beam drngd

Defect Desc: 2 W-Beam barrier rail damaged with post

Defect Status: COMPLETED

Recharge

Notify

Repair

Category: Permanent  Perm  Imm  Temp

Repair Desc

Treatment: BAPG BA - W Beam Damaged-Replace

Total Cost

BOQ Items

Item Code	Description	Dim 1	Dim 2	Dim 3	Quantity	Unit	Rate	Cost
BA01	GWA Barrier Beam				4	m		

Inspector: HBN  
Initiation Type: NRM  
Priority: 330

Inspection Batch: 17497

Inspection Id: 24878

SISS: ALL

Superseded?  N  By

Update Inv?  X  203442.7

Roadstud Type  Y  614280.7

Date Inspected: 16/DEC/2010 08:10

Notice Printed

Special Instr: Use map for location

Notice Id

Date Repair Due: 15/JAN/2011

Date Instructed

Target Complete

Date Completed: 12/JAN/2011

Check Date

Date Paid

Work Status

Work Order

Work Sheet

Check Batch

Check Result

Payment Id

Edit Defect

Summary

Print

View Asset



Defect Id: **24885** Order By: Defect Id (Desc)

Asset: BARRIER AND GUARDRAIL - VB00157

Road Section: FRASER XSP Start Chain

Road Desc: FRASER

Location: KURRINGA DR, Fraser,

Activity: BA Barrier

Defect Type: BA21 Barrier - W Beam drogd

Defect Desc: Approach End (ET 2000) with one rail damaged

Defect Status: COMPLETED

Recharge

Notify

Repair

Category

Repair Desc

Treatment: BAPG BA - W Beam Damaged-Replace

Total Cost

BOQ Items

Item Code Description

BA01 GW4 Barrier Beam

Inspector: HBN

Initiation Type: NPM

Priority: 330

Date Inspected: 16/DEC/2010 08:22

Notice Printed

Date Repair Due: 15/JAN/2011

Date Instructed

Target Complete

Date Completed: 19/JAN/2011

Check Date

Date Paid

View Asset

Inspection Batch: 17504

Inspection Id: 24885

SISS: ALL

Superseded? N By

Update Inv? X 203622.6

Roadstud Type Y 614233.6

Special Instr: use map for location

Notice Id

Work Status

Work Order

Work Sheet

Check Batch

Check Result

Payment Id

Edit Defect

Summary

Print

Dim 1 Dim 2 Dim 3 Quantity Unit Rate Cost

4 m



Defect Id: **24879** Order By: Defect Id (Desc)

Asset: BARRIER AND GUARDRAIL - VB00188

Road Section: FRASER XSP Start Chain

Road Desc: FRASER

Location: Kuringa dr, fraser

Activity: BA Barrier

Defect Type: BA21 Barrier - W Beam dmgd

Defect Desc: 2 W-Beam rail damaged with post

Defect Status: COMPLETED

Recharge:

Notify:

Repair:

Category: Permanent  Perm  Inm  Temp

Repair Desc:

Treatment: BAPG BA - W Beam Damaged-Replace

Total Cost:

BOQ Items

Item Code Description Dim 1 Dim 2 Dim 3 Quantity Unit Rate Cost

BA01 GW4 Barrier Beam 4 m


Inspector: HBN Inspection Batch: 17507 View Asset

Initiation Type: NRM Inspection Id: 24888

Priority: 330 SISS: ALL

Superseded?  N  By

Update Inv?  X 20/008.5

Roadstud Type:  Y 614710.0

Date Inspected: 16/DEC/2010 08:37

Notice Printed:

Date Repair Due: 15/JAN/2011

Date Instructed:

Target Complete:

Date Completed: 18/JAN/2011

Check Date:

Date Paid:

Work Status:

Work Order:

Work Sheet:

Check Batch:

Check Result:

Payment Id:

Special Instr: use map for location

Notice Id:

Edit Defect

Summary

Print



Defect Id: **26856** Order By: Defect Id (Desc)

View Asset

Asset: **SIGN GROUP - 900460052**  
 Road Section: **BELCONNEN (RURAL)** XSP  Start Chain   
 Road Desc: **BELCONNEN (RURAL)**  
 Location: **Kuringa Dr/ Tillyard**

Inspector: **DOT**  
 Initiation Type: **SAM**  
 Priority: **310**

Inspection Batch: **18856**  
 Inspection Id: **26875**  
 SISS: **ALL**

Activity: **SG** Sign Groups  
 Defect Type: **SGZ7** SG - Hazard - Blade Damaged  
 Defect Desc: **damaged hazard marker blade**  
 Defect Status: **COMPLETED**

Superseded? **N** By:   
 Update Inv? **R** **X** **203446.3**  
 Roadstud Type: **Y** **614284.2**

Recharge:   
 Notify:

Date Inspected: **08/MAR/2011** **09:23**  
 Notice Printed:

Special Instr: **completed by T.Sm**  
 Notice Id:

**Repair**

Category: **Permanent**  Perm  Temp

Date Repair Due: **18/MAR/2011**  
 Date Instructed:   
 Target Complete:

Work Status:   
 Work Order:   
 Work Sheet:

Treatment: **SGBA** SG - Hazard - Replace Blade

Date Completed:   
 Check Date:   
 Date Paid:

Check Result:   
 Check Batch:   
 Payment Id:

**BOQ Items**

Item Code	Description	Dim 1	Dim 2	Dim 3	Quantity	Unit	Rate	Cost

Edit Defect   
 Summary   
 Print

