





1997-01-11  
10:00 AM





Conduit is made of PVC which has a high strength and is resistant to fire





















RS-N2S 2053 9315712008697



STOP END









Project: [illegible]      Date: [illegible]

Location: [illegible]      Description: [illegible]







1 / 2



93.5%





ELECTRIC

2.5 MM2

CABLE

CU


450/750V

2012



Handwritten markings on the cable, possibly in Arabic script.





**KENNARDS**  
HIRE















**DANGER**  
DEEP  
EXCAVATION



HF1




R1

L-PTC2

QUALITY POWER ELECTRICAL EQUIPMENTS PVT. LTD.  
 100/101, PLOT NO. 100/101, INDUSTRIAL AREA, SECTOR 10, Gurgaon, Haryana, India.  
 \*RATED VOLTAGE 230V AC 50/60 Hz 100%  
 RATED CURRENT 22 A 100% 24.2 A  
 FREQ. TYPE 50/60 Hz  
 MFG. YEAR 2017  
 SERIAL NO. 2727 / 00012  
 CUSTOMER: IN ENERGY POWER CONVERSION  
 www.qualitypower.com

R

















Queanbeyan  
Ph: 0408211516 Fax: 02 6299 6100  
admin@rodgers electrical  
www.rodgers electrical  
ABN: 20 801 701 111

Tax Invoice No. **1890**

DATE: 10.8.18  
PHONE:  
MOBILE:



Traffic, pedestrian & plant access managed (TTM)?     Which specific SWMS tasks apply to this lift? 1, 4

Safe access for personnel & plant around crane?

If the answer to any question is no, do not commence work until the issues has been resolved.

Any point of concern? Please note and action:

**DO NOT COMMENCE WORK UNTIL YOU ARE SATISFIED THE JOB IS SAFE**

Signed: \_\_\_\_\_ Foreman: Damien Natho \_\_\_\_\_ Signed: \_\_\_\_\_ Crane Operator: Brent S \_\_\_\_\_




Signed: \_\_\_\_\_ Dogman: \_\_\_\_\_ Signed: \_\_\_\_\_ Additional Dogman: \_\_\_\_\_

RAR Cranes Pty Ltd  
ABN: 89 140 993 664

Email: accounts@rargroup.com.au  
Phone: 02 6299 6100  
Postal: PO Box 61  
Campbell, ACT, 2612

Web: http://www.rargroup.com.au  
Fax: 02 6299 6101  
Office: 36 - 40 Bedford Street,  
Queanbeyan, NSW, 2620





**DO NOT COMMENCE WORK UNTIL YOU ARE SATISFIED THE JOB IS SAFE**

Work at this site involves a high risk of injury or death. It is the responsibility of the person in charge of the work to ensure that all workers are properly trained and that the work is carried out in a safe and sound manner. The person in charge must ensure that all workers are aware of the risks involved in the work and that they are equipped with the necessary safety equipment. The person in charge must also ensure that the work is carried out in accordance with the relevant safety regulations and standards.


If the person in charge is not satisfied that the work can be carried out safely, they must stop the work immediately and consult with the relevant authorities. The person in charge must also ensure that the work is carried out in a safe and sound manner and that all workers are aware of the risks involved in the work.

Any work at this site must be carried out in accordance with the relevant safety regulations and standards. The person in charge must ensure that all workers are aware of the risks involved in the work and that they are equipped with the necessary safety equipment. The person in charge must also ensure that the work is carried out in accordance with the relevant safety regulations and standards.

**Signature:** \_\_\_\_\_  
**Position:** \_\_\_\_\_  
**Date:** \_\_\_\_\_

**Customer:** \_\_\_\_\_  
**Project:** \_\_\_\_\_  
**Address:** \_\_\_\_\_  
**City:** \_\_\_\_\_

**Web:** <http://www.raingroup.com.au>  
**Phone:** 02 9299 6100  
**Office:** 96-100 Belconnen Street, Queanbeyan, NSW, 2620






FEEDER CUBICLE MBS 500 UPDS 750VDC  
Sécheron SA, Genève


















CHEMCEL  
TYPE 81

Secheron



STANLEY  
Part  
Card No. 8833  
Equip. 11/10/2011









BARTON HWY  
Gungahlin  
Gold Creek (via) (100km)  
Hall  
Murrumbateman  
Yass

Crematorium  
Cemetery



Catalyst







60  
ROAD  
WORK







