




ACT Traffic Camera Office Verification of Speed Accuracy Form for Fixed Sites

Date:	10/05/2012	Description of other speed measurement device (A)	Ballinger on VW Amarok 214-277 02/11/2011 to 01/11/2012
Location Number:	1008	Calibration Date of (A)	01/11/2012 AFP
Location Description:	Intersection of Hindmarsh Dr & Tuggeranong Pkwy	Truvello No.	00AU81PS
Direction:	Eastbound	Truvello Calibration date:	07/05/2012 07/05/2013
Notices: Installed re-certified Truvelo 00AU81PS & removed (spare) Truvelo 00AU92PS - conduct (3x) test runs per lane with Ballinger in VW Amarok (214-277).			

	Time	Vehicle Rego No	Fixed DVD Image number	Fixed Camera Speed	Mobile DVD image number	Mobile Camera Speed	Ballinger speed device	Pass/Fail (Within +/-2km/h)
Lane 1								
Run 1	10:46:08	214 277	0000 2x	59			59	PASS
Run 2	11:02:53	214 277	0003 1x	67			68	PASS
Run 3	11:06:45	214 277	0004 1x	61			62	PASS
Lane 2								
Run 1	11:10:50	214 277	0005 1x	62			62	PASS
Run 2	11:13:32	214 277	0006 1x	71			72	PASS
Run 3	12:03:02	214 277	0000 1x	68			69	PASS
Lane 3								
Run 1		214 277						
Run 2		214 277						
Run 3		214 277						




Technicians Name		Technicians Signature		Date 10/05/2012
Observers Name	John Peti	Observers Signature		Date 10/05/2012

ACT Traffic Camera Office Verification of Speed Accuracy Form for Fixed Sites

Date:	29/04/2013	Description of other speed measurement device (A)	Ballinger on VW Amarok 214-277 11/10/2012 to 10/10/2013
Location Number:	1008	Calibration Date of (A)	10/10/2013 AFP
Location Description:	Intersection of Hindmarsh Dr & Tuggeranong Pkwy	Truvello No.	00AU80PS
Direction:	Eastbound	Truvello Calibration date:	18/02/2013 18/02/2014
Notices: Installed re-certified Truvelo 00AU80PS & removed (spare) Truvelo 00AU92PS - conduct (3x) test runs per lane with Ballinger in VW Amarok (214-277).			

* TEST IMAGES SAVED TO C:\1008\130429\0000 TO 0004.JP cc

	Time	Vehicle Rego No	Fixed DVD Image number	Fixed Camera Speed	Mobile DVD image number	Mobile Camera Speed	Ballinger speed device	Pass/Fail (Within +/-2km/h)
Lane 1			Folder File					
Run 1	13:20:49	214 277	0000 15t	56		56		PASS
Run 2	13:24:44	214 277	0000 20t	57		57		PASS
Run 3	13:54:51	214 277	0003 13t	60		62		PASS
Lane 2								
Run 1	14:06:46	214 277	0004 5t	57			56	PASS
Run 2	14:11:57	214 277	0004 19t	53			53	PASS
Run 3	14:23:51	214 277	0004 39t	55			56	PASS
Lane 3								
Run 1		214 277						
Run 2		214 277						
Run 3		214 277						

Technicians Name		Technicians Signature		Date	29/04/2013
Observers Name	John Peti	Observers Signature		Date	29/04/2013

Session No	0000	Operator	OP0045	Location	1008	Date	10/05/2012	Device	00AU81PS	Image No	2
Disk	WD0353	Speed Limit	80	Speed	59	Time	10:46:08.68	Lane	L1	Direction	E



Session No	0000	Operator	OP0045	Location	1008	Date	29/04/2013	Device	00AU80PS	Image No	15
Disk	WD0843	Speed Limit	80	Speed	56	Time	13:20:49.73	Lane	L1	Direction	E



Session No	0003	Operator	OP0045	Location	1008	Date	10/05/2012	Device	00AU81PS	Image No	1
Disk	WD0353	Speed Limit	80	Speed	67	Time	11:02:53.65	Lane	L1	Direction	E



Session No	0000	Operator	OP0045	Location	1008	Date	29/04/2013	Device	00AU80PS	Image No	20
Disk	WD0843	Speed Limit	80	Speed	57	Time	13:24:44.98	Lane	L1	Direction	E



Session No	0004	Operator	OP0045	Location	1008	Date	10/05/2012	Device	00AU81PS	Image No	1
Disk	WD0353	Speed Limit	80	Speed	61	Time	11:06:45.23	Lane	L1	Direction	E



Session No	0000	Operator	OP0045	Location	1008	Date	29/04/2013	Device	00AU80PS	Image No	13
Disk	WD0843	Speed Limit	80	Speed	60	Time	13:54:51.81	Lane	L1	Direction	E



Session No	0005	Operator	OP0045	Location	1008	Date	10/05/2012	Device	00AU81PS	Image No	1
Disk	WD0353	Speed Limit	80	Speed	62	Time	11:10:50.96	Lane	L2	Direction	E



Session No	0000	Operator	OP0045	Location	1008	Date	29/04/2013	Device	00AU80PS	Image No	5
Disk	WD0843	Speed Limit	80	Speed	57	Time	14:06:46.9	Lane	L2	Direction	E



Session No	0006	Operator	OP0045	Location	1008	Date	10/05/2012	Device	00AU81PS	Image No	1
Disk	WD0353	Speed Limit	80	Speed	71	Time	11:13:32.16	Lane	L2	Direction	E



Session No	0000	Operator	OP0045	Location	1008	Date	29/04/2013	Device	00AU80PS	Image No	19
Disk	WD0843	Speed Limit	80	Speed	53	Time	14:11:57.15	Lane	L2	Direction	E



Session No	0001	Operator	OP0045	Location	1008	Date	10/05/2012	Device	00AU81PS	Image No	1
Disk	WD0353	Speed Limit	80	Speed	68	Time	12:03:02.78	Lane	L2	Direction	E



Session No	0000	Operator	OP0045	Location	1008	Date	29/04/2013	Device	00AU80PS	Image No	39
Disk	WD0843	Speed Limit	80	Speed	55	Time	14:23:51.82	Lane	L2	Direction	E





AUSTRALIAN CAPITAL TERRITORY GOVERNMENT
Traffic Camera Office
PO Box 582
Dickson ACT 2602
Telephone: 13 22 81

70.050 (01/2009)

Site Report

Date 23-1-12 Start 13.25 Finish 13.45
Location HINDMARSH TULLY PKWY Location code 1008
Maintenance Officer [REDACTED]
Truvello / Loop card serial number 004081PS

Piezo / Loop Examination

- ☒ In-road sensors
☒ Road surface near sensors in good condition

Clean the Glass Windows on

- ☒ Main system housing
☒ Flash housing

Look for vandalism

- ☒ Main system housing
☒ Flash housing

NT, MCS, GTCD Check the site system is working

- ☒ UPS power indicator is ON (Green)
☒ Main Computer Unit power supply indicator is ON
☒ Main Computer Unit Cooling fan is operating
☒ Router power indicator is ON
☒ Camera body power indicators are ON
☒ Check Date and Time is correct

DRCS Sites

- ☐ Main Computer Unit power supply indicator is ON
☐ Main Computer Unit Cooling fan is operating
☐ Check **all** connections are secure
☐ Router power indicator is ON
☐ Camera body power indicators are ON
☐ Check Date and Time is correct

COMPUTER FROZEN AT DESKTOP ON ARRIVAL. RESTART
COMPUTER, CHECK OPERATION. ALL OK. REPLACE
LOG BOOK

Maintenance Officer's Signature [REDACTED] Date 23-1-12
TCO Officer's Signature [REDACTED] Date [REDACTED]



AUSTRALIAN CAPITAL TERRITORY GOVERNMENT
Traffic Camera Office
PO Box 582
Dickson ACT 2602
Telephone: 13 22 81

76 059 (11/2003)

Site Report

Date	12-4-12	Start	9-10	Finish	10-00
Location	HINDMARSH TOWER PLAZA		Location code	1008	
Maintenance Officer	[REDACTED]				
Truvello / Loop card serial number	00908125				

Piezo / Loop Examination

- ☒ In-road sensors
- ☒ Road surface near sensors in good condition

Clean the Glass Windows on

- ☒ Main system housing
- ☒ Flash housing

Look for vandalism

- ☒ Main system housing
- ☒ Flash housing

NT, MCS, GTCD Check the site system is working

- ☒ UPS power indicator is ON (Green)
- ☒ Main Computer Unit power supply indicator is ON
- ☒ Main Computer Unit Cooling fan is operating
- ☒ Router power indicator is ON
- ☒ Camera body power indicators are ON
- ☒ Check Date and Time is correct

DRCS Sites

- ☐ Main Computer Unit power supply indicator is ON
- ☐ Main Computer Unit Cooling fan is operating
- ☐ Check all connections are secure
- ☐ Router power indicator is ON
- ☐ Camera body power indicators are ON
- ☐ Check Date and Time is correct

Maintenance Officer's Signature	[REDACTED]	Date	12-4-12
TCO Officer's Signature	[REDACTED]	Date	



AUSTRALIAN CAPITAL TERRITORY GOVERNMENT
Traffic Camera Office
PO Box 582
Dickson ACT 2602
Telephone: 13 22 81

Site Report

Date	6-7-12	Start	11:58	Finish	12:18
Location	HINDMARSH TOLL, 1/KM7			Location code	1005
Maintenance Officer	[REDACTED]				
Truvello / Loop card serial number	00908				

Piezo / Loop Examination

- ☒ In-road sensors
- ☒ Road surface near sensors in good condition

Clean the Glass Windows on

- ☒ Main system housing
- ☒ Flash housing

Look for vandalism

- ☒ Main system housing
- ☒ Flash housing

NT, MCS, GTCD Check the site system is working

- ☒ UPS power indicator is ON (Green)
- ☒ Main Computer Unit power supply indicator is ON
- ☒ Main Computer Unit Cooling fan is operating
- ☒ Router power indicator is ON
- ☒ Camera body power indicators are ON
- ☒ Check Date and Time is correct

DRCS Sites

- ☐ Main Computer Unit power supply indicator is ON
- ☐ Main Computer Unit Cooling fan is operating
- ☐ Check all connections are secure
- ☐ Router power indicator is ON
- ☐ Camera body power indicators are ON
- ☐ Check Date and Time is correct

Maintenance Officer's Signature	[REDACTED]	Date	6-7-12
TCO Officer's Signature		Date	



AUSTRALIAN CAPITAL TERRITORY GOVERNMENT
Traffic Camera Office
PO Box 582
Dickson ACT 2602
Telephone: 13 22 81

70.050 (01/2009)

Site Report

Date 11-9-12 Start 11:01 Finish 11:18
Location HINDMARSH - TULLA PKWY Location code 1008
Maintenance Officer [REDACTED]
Truvello / Loop card serial number 004081PS

Piezo / Loop Examination

- ☒ In-road sensors
☒ Road surface near sensors in good condition

Clean the Glass Windows on

- ☒ Main system housing
☒ Flash housing

Look for vandalism

- ☒ Main system housing
☒ Flash housing

NT, MCS, GTCD Check the site system is working

- ☒ UPS power indicator is ON (Green)
☒ Main Computer Unit power supply indicator is ON
☒ Main Computer Unit Cooling fan is operating
☒ Router power indicator is ON
☒ Camera body power indicators are ON
☒ Check Date and Time is correct

DRCS Sites

- ☐ Main Computer Unit power supply indicator is ON
☐ Main Computer Unit Cooling fan is operating
☐ Check all connections are secure
☐ Router power indicator is ON
☐ Camera body power indicators are ON
☐ Check Date and Time is correct

Maintenance Officer's Signature [REDACTED] Date 11-9-12
TCO Officer's Signature [REDACTED] Date [REDACTED]



AUSTRALIAN CAPITAL TERRITORY GOVERNMENT
Traffic Camera Office
PO Box 582
Dickson ACT 2602
Telephone: 13 22 81

79 059 (01/2002)

Site Report

Date Start Finish

Location Location code

Maintenance Officer

Truvello / Loop card serial number

Piezo / Loop Examination

- ☒ In-road sensors
☒ Road surface near sensors in good condition

Clean the Glass Windows on

- ☒ Main system housing
☒ Flash housing

Look for vandalism

- ☒ Main system housing
☒ Flash housing

NT, MCS, GTCD Check the site system is working

- ☒ UPS power indicator is ON (Green)
☒ Main Computer Unit power supply indicator is ON
☒ Main Computer Unit Cooling fan is operating
☒ Router power indicator is ON
☒ Camera body power indicators are ON
☒ Check Date and Time is correct

ORCS Sites

- ☐ Main Computer Unit power supply indicator is ON
☐ Main Computer Unit Cooling fan is operating
☐ Check all connections are secure
☐ Router power indicator is ON
☐ Camera body power indicators are ON
☐ Check Date and Time is correct

Maintenance Officer's Signature Date

TCO Officer's Signature Date



AUSTRALIAN CAPITAL TERRITORY GOVERNMENT
 Traffic Camera Office
 PO Box 582
 Dickson ACT 2602
 Telephone: 13 22 81

Site Report

Date Start Finish

Location Location code

Maintenance Officer

Truvello / Loop card serial number

Piezo / Loop Examination

- ☒ In-road sensors
☒ Road surface near sensors in good condition

Clean the Glass Windows on

- ☒ Main system housing
☒ Flash housing

Look for vandalism

- ☒ Main system housing
☒ Flash housing

NT, MCS, GTCD Check the site system is working

- ☒ UPS power indicator is ON (Green)
☒ Main Computer Unit power supply indicator is ON
☒ Main Computer Unit Cooling fan is operating
☒ Router power indicator is ON
☒ Camera body power indicators are ON
☒ Check Date and Time is correct

DRCS Sites

- ☐ Main Computer Unit power supply indicator is ON
☐ Main Computer Unit Cooling fan is operating
☐ Check all connections are secure
☐ Router power indicator is ON
☐ Camera body power indicators are ON
☐ Check Date and Time is correct

Maintenance Officer's Signature Date

TCO Officer's Signature Date



AUSTRALIAN CAPITAL TERRITORY GOVERNMENT
 Traffic Camera Office
 PO Box 582
 Dickson ACT 2602
 Telephone: 13 22 81

Site Report

Date 7-12-12 Start 13.15 Finish 13.31

Location HINDMARSH - TUGLA PKWY Location code 1008

Maintenance Officer [REDACTED]

Truvello / Loop card serial number 00AU81PS

Piezo / Loop Examination

- ☒ In-road sensors
- ☒ Road surface near sensors in good condition

Clean the Glass Windows on

- ☒ Main system housing
- ☒ Flash housing

Look for vandalism

- ☒ Main system housing
- ☒ Flash housing

NT, MCS, GTCD Check the site system is working

- ☒ UPS power indicator is ON (Green)
- ☒ Main Computer Unit power supply indicator is ON
- ☒ Main Computer Unit Cooling fan is operating
- ☒ Router power indicator is ON
- ☒ Camera body power indicators are ON
- ☒ Check Date and Time is correct

DRCS Sites

- ☐ Main Computer Unit power supply indicator is ON
- ☐ Main Computer Unit Cooling fan is operating
- ☐ Check all connections are secure
- ☐ Router power indicator is ON
- ☐ Camera body power indicators are ON
- ☐ Check Date and Time is correct

Maintenance Officer's Signature [REDACTED] Date 7-12-12

TCO Officer's Signature [REDACTED] Date [REDACTED]



Road Transport Authority
PO Box 582
Dickson ACT 2602
Telephone: 13 22 81

70.050 (12/2012)

Site Report

Date 9-1-13 Start 9.00 Finish 9.20

Location HINDMARSH TUGA PKWY Location code 1008

Maintenance Officer [REDACTED]

Truvello / Loop card serial number 00AUG1PS

Piezo / Loop Examination

- ☒ In-road sensors
- ☒ Road surface near sensors in good condition

Look for vandalism

- ☒ Main system housing
- ☒ Flash housing

NT, MCS, GTCD Check the site system is working

- ☒ UPS power indicator is ON (Green)
- ☒ Main Computer Unit power supply indicator is ON
- ☒ Main Computer Unit Cooling fan is operating
- ☒ Router power indicator is ON
- ☒ Camera body power indicators are ON
- ☒ Check Date and Time is correct
- ☐ Test image taken and TCO have been Notified.

Clean the Glass Windows on

- ☒ Main system housing
- ☒ Flash housing

Name of TCO Officer contacted: [REDACTED]

DRCS Sites

- ☐ Main Computer Unit power supply indicator is ON
- ☐ Main Computer Unit Cooling fan is operating
- ☐ Check **all** connections are secure
- ☐ Router power indicator is ON
- ☐ Camera body power indicators are ON
- ☐ Check Date and Time is correct
- ☐ Test image taken and TCO have been Notified.

Name of TCO Officer contacted: [REDACTED]

<u>LOW BOOK REPLACED</u>

Maintenance Officer's Signature [REDACTED] Date 9-1-13

TCO Officer's Signature [REDACTED] Date [REDACTED]



Road Transport Authority
PO Box 582
Dickson ACT 2602
Telephone: 13 22 81

70,050 (12/2012)

Site Report

Date 22 - 1 - 13 Start 9.40 Finish 10.00

Location HINDMARSH TUGA PKY Location code 1008

Maintenance Officer [REDACTED]

Truvello / Loop card serial number 004081PS

Piezo / Loop Examination

- ☒ In-road sensors
- ☒ Road surface near sensors in good condition

Look for vandalism

- ☒ Main system housing
- ☒ Flash housing

Clean the Glass Windows on

- ☒ Main system housing
- ☒ Flash housing

NT, MCS, GTCD Check the site system is working

- ☒ UPS power indicator is ON (Green)
- ☒ Main Computer Unit power supply indicator is ON
- ☒ Main Computer Unit Cooling fan is operating
- ☒ Router power indicator is ON
- ☒ Camera body power indicators are ON
- ☒ Check Date and Time is correct
- ☐ Test image taken and TCO have been Notified.

Name of TCO Officer contacted:

DRCS Sites

- ☐ Main Computer Unit power supply indicator is ON
- ☐ Main Computer Unit Cooling fan is operating
- ☐ Check all connections are secure
- ☐ Router power indicator is ON
- ☐ Camera body power indicators are ON
- ☐ Check Date and Time is correct
- ☐ Test image taken and TCO have been Notified.

Name of TCO Officer contacted:

Maintenance Officer's Signature [REDACTED] Date 22-1-13

TCO Officer's Signature Date


ACT
Government

Road Transport Authority
PO Box 582
Dickson ACT 2602
Telephone: 13 22 81

70,050 (12/2012)

Site Report

Date 12/2/13 Start 13.45 Finish 14.02

Location H. holmarsh / Parkway Location code 1008

Maintenance Officer [REDACTED]

Truvello / Loop card serial number 00AU81PS
Piezo / Loop Examination

- ☒ In-road sensors
☒ Road surface near sensors in good condition

Look for vandalism

- ☒ Main system housing
☒ Flash housing

Clean the Glass Windows on

- ☒ Main system housing
☒ Flash housing

NT, MCS, GTCD Check the site system is working

- ☒ UPS power Indicator is ON (Green)
☒ Main Computer Unit power supply Indicator is ON
☒ Main Computer Unit Cooling fan is operating
☒ Router power indicator is ON
☒ Camera body power indicators are ON
☒ Check Date and Time is correct
☐ Test image taken and TCO have been Notified.

Name of TCO Officer contacted:
DRCS Sites

- ☐ Main Computer Unit power supply indicator is ON
☐ Main Computer Unit Cooling fan is operating
☐ Check all connections are secure
☐ Router power Indicator is ON
☐ Camera body power indicators are ON
☐ Check Date and Time is correct
☐ Test Image taken and TCO have been Notified.

Name of TCO Officer contacted:

Comments

Maintenance Officer's Signature [REDACTED] Date 12/2/13

TCO Officer's Signature Date



Road Transport Authority
PO Box 582
Dickson ACT 2602
Telephone: 13 22 81

70,050 (12/2012)

Site Report

Date 10-4-13 Start 9.19 Finish 9.40

Location HINDMARSH-TULLA PKWY Location code 1008

Maintenance Officer [REDACTED]

Truvello / Loop card serial number 002V81PS

Piezo / Loop Examination

- ☒ In-road sensors
☒ Road surface near sensors in good condition

Look for vandalism

- ☒ Main system housing
☒ Flash housing

Clean the Glass Windows on

- ☒ Main system housing
☒ Flash housing

NT, MCS, GTCD Check the site system is working

- ☒ UPS power indicator is ON (Green)
☒ Main Computer Unit power supply indicator is ON
☒ Main Computer Unit Cooling fan is operating
☒ Router power indicator is ON
☒ Camera body power indicators are ON
☒ Check Date and Time is correct
☐ Test image taken and TCO have been Notified.

Name of TCO Officer contacted:

DRCS Sites

- ☐ Main Computer Unit power supply indicator is ON
☐ Main Computer Unit Cooling fan is operating
☐ Check all connections are secure
☐ Router power indicator is ON
☐ Camera body power indicators are ON
☐ Check Date and Time is correct
☐ Test image taken and TCO have been Notified.

Name of TCO Officer contacted:

Comments

Maintenance Officer's Signature [REDACTED] Date 10-4-13

TCO Officer's Signature [REDACTED] Date


ACT
Government

Road Transport Authority
PO Box 582
Dickson ACT 2602
Telephone: 13 22 81

70,050 (12/2012)

Site Report

Date 23-4-13 Start 11.13 Finish 11.31

Location HINDMARSH - TURN PKWY Location code 1008

Maintenance Officer [REDACTED]

Truvello / Loop card serial number 00AV92 PG

Piezo / Loop Examination

- ☒ In-road sensors
☒ Road surface near sensors in good condition

Look for vandalism

- ☒ Main system housing
☒ Flash housing

Clean the Glass Windows on

- ☒ Main system housing
☒ Flash housing

NT, MCS, GTCD Check the site system is working

- ☒ UPS power indicator is ON (Green)
☒ Main Computer Unit power supply indicator is ON
☒ Main Computer Unit Cooling fan is operating
☒ Router power indicator is ON
☒ Camera body power indicators are ON
☒ Check Date and Time is correct
☐ Test image taken and TCO have been Notified.

Name of TCO Officer contacted: [REDACTED]

DRCS Sites

- ☐ Main Computer Unit power supply indicator is ON
☐ Main Computer Unit Cooling fan is operating
☐ Check all connections are secure
☐ Router power indicator is ON
☐ Camera body power indicators are ON
☐ Check Date and Time is correct
☐ Test image taken and TCO have been Notified.

Name of TCO Officer contacted: [REDACTED]

Comments

Maintenance Officer's Signature [REDACTED] Date 23-4-13

TCO Officer's Signature [REDACTED] Date [REDACTED]



Road Transport Authority
PO Box 582
Dickson ACT 2602
Telephone: 13 22 81

70,050 (12/2012)

Site Report

Date 9-5-13 Start 10.50 Finish 11.10

Location HINDMARSH TURN PKWY Location code 1008

Maintenance Officer [REDACTED]

Truvello / Loop card serial number 00AU 80PS

Piezo / Loop Examination

- ☒ In-road sensors
- ☒ Road surface near sensors in good condition

Look for vandalism

- ☒ Main system housing
- ☒ Flash housing

NT, MCS, GTCD Check the site system is working

- ☒ UPS power indicator is ON (Green)
- ☒ Main Computer Unit power supply indicator is ON
- ☒ Main Computer Unit Cooling fan is operating
- ☒ Router power indicator is ON
- ☒ Camera body power indicators are ON
- ☒ Check Date and Time is correct
- ☒ Test Image taken and TCO have been Notified.

Clean the Glass Windows on

- ☒ Main system housing
- ☒ Flash housing

Name of TCO Officer contacted: [REDACTED]

DRCS Sites

- ☐ Main Computer Unit power supply indicator is ON
- ☐ Main Computer Unit Cooling fan is operating
- ☐ Check all connections are secure
- ☐ Router power indicator is ON
- ☐ Camera body power indicators are ON
- ☐ Check Date and Time is correct
- ☐ Test Image taken and TCO have been Notified.

Name of TCO Officer contacted: [REDACTED]

Comments
Completed Invoice N-3219

Maintenance Officer's Signature [REDACTED] Date 9-5-13

TCO Officer's Signature [REDACTED] Date 14/6/13

ACT
Government

70,050 (12/2012)

Date 5-6-13 Start 9.25 Finish 9.45

Location	HINDMARSH TUGG PKWY	Location code	100 8
----------	---------------------	---------------	-------

Maintenance Officer [REDACTED]

Truvello / Loop card serial number	004080PS
------------------------------------	----------

Clean the Glass Windows on

- ☒ Main system housing
☒ Flash housing

☒ Main system housing

NT, MCS, GTCD Check the site system is working

- ☒ UPS power Indicator Is ON (Green)
- ☒ Main Computer Unit power supply Indicator Is ON
- ☒ Main Computer Unit Cooling fan Is operating
- ☒ Router power Indicator Is ON
- ☒ Camera body power Indicators are ON
- ☒ Check Date and Time Is correct
- ☐ Test image taken and TCO have been Notified.

Name of TCO Officer contacted: [REDACTED]

☐ Main Computer Unit power supply Indicator is ON

- ☐ Main Computer Unit Cooling fan is operating
- ☐ Check all connections are secure
- ☐ Router power Indicator is ON
- ☐ Camera body power Indicators are ON
- ☐ Check Date and Time is correct
- ☐ Test Image taken and TCO have been Notified.

Name of TCO Officer contacted:

Comments

Completed Invoice No: 3243

Maintenance Officer's Sig	Date	5-6-13
---------------------------	------	--------

TCO Officer's Signature _____ Date 30/07/13


ACT
Government

Road Transport Authority
PO Box 582
Dickson ACT 2602
Telephone: 13 22 81

70,050 (12/2012)

Site Report

Date 11-7-13 Start 13:12 Finish 13:32

Location HINDMARSH - TUGGERAH PKWY Location code 1008

Maintenance Officer [REDACTED]

Truvello / Loop card serial number 00A080PS
Plezo / Loop Examination

- ☒ In-road sensors
- ☒ Road surface near sensors in good condition

Look for vandalism

- ☒ Main system housing
- ☒ Flash housing

Clean the Glass Windows on

- ☒ Main system housing
- ☒ Flash housing

NT, MCS, GTCD Check the site system is working

- ☒ UPS power indicator is ON (Green)
- ☒ Main Computer Unit power supply indicator is ON
- ☒ Main Computer Unit Cooling fan is operating
- ☒ Router power indicator is ON
- ☒ Camera body power indicators are ON
- ☒ Check Date and Time is correct
- ☐ Test Image taken and TCO have been Notified.

Name of TCO Officer contacted: [REDACTED]
DRCS Sites

- ☐ Main Computer Unit power supply indicator is ON
- ☐ Main Computer Unit Cooling fan is operating
- ☐ Check all connections are secure
- ☐ Router power indicator is ON
- ☐ Camera body power indicators are ON
- ☐ Check Date and Time is correct
- ☐ Test Image taken and TCO have been Notified.

Name of TCO Officer contacted: [REDACTED]

Comments
Completed. Invoice No. 5-401

Maintenance Officer's Signature [REDACTED] Date 11-7-13

TCO Officer's Signature [REDACTED] Date 8/5/13



Road Transport Authority
PO Box 582
Dickson ACT 2602
Telephone: 13 22 81

70,050 (12/2012)

Site Report

Date 15.8.13 Start 13.10 Finish 13.45

Location HINDMARSH TOLL PKWY Location code 1008

Maintenance Officer [REDACTED]

Truvello / Loop card serial number 00AU 80PS

Plezo / Loop Examination

- ☐ In-road sensors
- ☒ Road surface near sensors in good condition

Look for vandalism

- ☒ Main system housing
- ☒ Flash housing

NT, MCS, GTCD Check the site system is working

- ☒ UPS power Indicator is ON (Green)
- ☒ Main Computer Unit power supply Indicator is ON
- ☒ Main Computer Unit Cooling fan is operating
- ☒ Router power Indicator is ON
- ☒ Camera body power Indicators are ON
- ☒ Check Date and Time is correct
- ☐ Test Image taken and TCO have been Notified.

Clean the Glass Windows on

- ☒ Main system housing
- ☒ Flash housing

Name of TCO Officer contacted: [REDACTED]

DRCS Sites

- ☐ Main Computer Unit power supply Indicator is ON
- ☐ Main Computer Unit Cooling fan is operating
- ☐ Check all connections are secure
- ☐ Router power Indicator is ON
- ☐ Camera body power Indicators are ON
- ☐ Check Date and Time is correct
- ☐ Test Image taken and TCO have been Notified.

Name of TCO Officer contacted: [REDACTED]

Comments
<u>CHECK COMMENTS WITH [REDACTED]</u>
<u>CHECKED AGAINST INVOICE N-4025 [REDACTED]</u>

Maintenance Officer's Signature [REDACTED] Date 15.8.13

TCO Officer's Signature [REDACTED] Date 02-10-13


ACT
Government

Road Transport Authority
PO Box 582
Dickson ACT 2602
Telephone: 13 22 81

70,050 (12/2012)

Site Report

Date 27-8-13 Start 10.58 Finish 11.20

Location HINDMARSH - TUGG PKWY Location code 1008

Maintenance Officer [REDACTED]

Truvello / Loop card serial number 001V80PS
Plezo / Loop Examination

- ☒ In-road sensors
- ☒ Road surface near sensors In good condition

Look for vandalism

- ☒ Main system housing
- ☒ Flash housing

Clean the Glass Windows on

- ☒ Main system housing
- ☒ Flash housing

NT, MCS, GTCD Check the site system is working

- ☒ UPS power Indicator is ON (Green)
- ☒ Main Computer Unit power supply Indicator is ON
- ☒ Main Computer Unit Cooling fan is operating
- ☒ Router power Indicator is ON
- ☒ Camera body power Indicators are ON
- ☒ Check Date and Time is correct
- ☐ Test Image taken and TCO have been Notified.

Name of TCO Officer contacted: [REDACTED]
DRCS Sites

- ☐ Main Computer Unit power supply Indicator is ON
- ☐ Main Computer Unit Cooling fan is operating
- ☐ Check all connections are secure
- ☐ Router power Indicator is ON
- ☐ Camera body power Indicators are ON
- ☐ Check Date and Time is correct
- ☐ Test Image taken and TCO have been Notified.

Name of TCO Officer contacted: [REDACTED]

Comments
CHECKED AGAINST INVOICE N-4025-jp

Maintenance Officer's Signature [REDACTED] Date 27-8-13

TCO Officer's Signature [REDACTED] Date 08-10-13

GARUS/TCO03 EQUIPMENT & STORES

Maintenance



Road Transport Authority
PO Box 582
Dickson ACT 2602
Telephone: 13 22 81

70,050 (12/2012)

Site Report

Date 10-9-13 Start 12.15 Finish 12.37

Location HINDMARSH TOLL PLAZA Location code 1008

Maintenance Officer 

Truvello / Loop card serial number 004V80PS

Piezo / Loop Examination

- ☒ In-road sensors
- ☒ Road surface near sensors in good condition

Look for vandalism


- ☒ Main system housing
- ☒ Flash housing

Clean the Glass Windows on

- ☒ Main system housing
- ☒ Flash housing

NT, MCS, GTCD Check the site system is working

- ☒ UPS power indicator is ON (Green)
- ☒ Main Computer Unit power supply indicator is ON
- ☒ Main Computer Unit Cooling fan is operating
- ☒ Router power indicator is ON
- ☒ Camera body power indicators are ON
- ☒ Check Date and Time is correct
- ☐ Test image taken and TCO have been Notified.


Name of TCO Officer contacted: 


DRCS Sites

- ☐ Main Computer Unit power supply indicator is ON
- ☐ Main Computer Unit Cooling fan is operating
- ☐ Check all connections are secure
- ☐ Router power indicator is ON
- ☐ Camera body power indicators are ON
- ☐ Check Date and Time is correct
- ☐ Test Image taken and TCO have been Notified.

Name of TCO Officer contacted: 

Comments

Maintenance Officer's Signature  Date 10-9-13

TCO Officer's Signature  Date 10/9/13



Road Transport Authority
PO Box 582
Dickson ACT 2602
Telephone: 13 22 81

70,050 (12/2012)

Site Report

Date 26-9-13 Start 11:00 Finish 11:20

Location HINDMARSH - TULLY PKWY Location code 1008

Maintenance Officer [REDACTED]

Truvello / Loop card serial number 004V80PS

Piezo / Loop Examination

- ☒ In-road sensors
- ☒ Road surface near sensors in good condition

Look for vandalism

- ☒ Main system housing
- ☒ Flash housing

Clean the Glass Windows on

- ☒ Main system housing
- ☒ Flash housing

NT, MCS, GTCD Check the site system is working

- ☒ UPS power indicator is ON (Green)
- ☒ Main Computer Unit power supply indicator is ON
- ☒ Main Computer Unit Cooling fan is operating
- ☒ Router power indicator is ON
- ☒ Camera body power indicators are ON
- ☒ Check Date and Time is correct
- ☐ Test image taken and TCO have been Notified.

Name of TCO Officer contacted: [REDACTED]

DRCS Sites

- ☐ Main Computer Unit power supply indicator is ON
- ☐ Main Computer Unit Cooling fan is operating
- ☐ Check all connections are secure
- ☐ Router power indicator is ON
- ☐ Camera body power indicators are ON
- ☐ Check Date and Time is correct
- ☐ Test image taken and TCO have been Notified.

Name of TCO Officer contacted: [REDACTED]

Comments

Maintenance Officer's Signature [REDACTED]

Date 26-9-13

TCO Officer's Signature [REDACTED]

Date 27-9-13



Road Transport Authority
PO Box 582
Dickson ACT 2602
Telephone: 13 22 81

70,050 (12/2012)

Site Report

Date 29-10-13 Start 9-18 Finish 9-36
Location HINDMARSH TUGG PKWY Location code 1008

Maintenance Officer [REDACTED]

Truvello / Loop card serial number 004U80PS

Plezo / Loop Examination

- ☒ In-road sensors
- ☒ Road surface near sensors in good condition

Look for vandalism

- ☒ Main system housing
- ☒ Flash housing

Clean the Glass Windows on

- ☒ Main system housing
- ☒ Flash housing

NT, MCS, GTCD Check the site system is working

- ☒ UPS power indicator is ON (Green)
- ☒ Main Computer Unit power supply indicator is ON
- ☒ Main Computer Unit Cooling fan is operating
- ☒ Router power indicator is ON
- ☒ Camera body power indicators are ON
- ☒ Check Date and Time is correct
- ☐ Test image taken and TCO have been Notified.

Name of TCO Officer contacted: [REDACTED]

DRCS Sites

- ☐ Main Computer Unit power supply indicator is ON
- ☐ Main Computer Unit Cooling fan is operating
- ☐ Check all connections are secure
- ☐ Router power indicator is ON
- ☐ Camera body power indicators are ON
- ☐ Check Date and Time is correct
- ☐ Test image taken and TCO have been Notified.

Name of TCO Officer contacted: [REDACTED]

Comments

Completed

Maintenance Officer's S [REDACTED]

Date 29-10-13

TCO Officer's Signature [REDACTED]

Date 29/10/13



ACT
Government

Road Transport Authority
PO Box 582
Dickson ACT 2602
Telephone: 13 22 81

70,050 (12/2012)

Site Report

Date 17/10/13 Start 13:20 Finish 13:40

Location HINDMARSH DR Location code 1008

Maintenance Officer [REDACTED]

Truvello / Loop card serial number AU80PS

Piezo / Loop Examination

- ☒ In-road sensors
- ☒ Road surface near sensors in good condition

Look for vandalism

- ☒ Main system housing
- ☒ Flash housing

NT, MCS, GTCD Check the site system is working

- ☒ UPS power indicator is ON (Green)
- ☒ Main Computer Unit power supply indicator is ON
- ☒ Main Computer Unit Cooling fan is operating
- ☒ Router power indicator is ON
- ☒ Camera body power indicators are ON
- ☒ Check Date and Time is correct
- ☒ Test image taken and TCO have been Notified.

Clean the Glass Windows on

- ☒ Main system housing
- ☒ Flash housing

Name of TCO Officer contacted: [REDACTED]

DRCS Sites

- ☐ Main Computer Unit power supply indicator is ON
- ☐ Main Computer Unit Cooling fan is operating
- ☐ Check all connections are secure
- ☐ Router power indicator is ON
- ☐ Camera body power indicators are ON
- ☐ Check Date and Time is correct
- ☐ Test image taken and TCO have been Notified.

Name of TCO Officer contacted: [REDACTED]

Comments
<u>COMPLETED</u>

Maintenance Officer's Signature [REDACTED] Date 17/10/13

TCO Officer's Signature [REDACTED] Date 18/10/13



Road Transport Authority
PO Box 582
Dickson ACT 2602
Telephone: 13 22 81

70,050 (12/2012)

Site Report

Date 14.11.13 Start 11:00 Finish 11:15

Location Hindmarsh / Tuggerah way Location code 1008

Maintenance Officer [REDACTED]

Truvello / Loop card serial number [REDACTED]

Plezo / Loop Examination

- ☒ In-road sensors
- ☒ Road surface near sensors in good condition

Look for vandalism

- ☒ Main system housing
- ☒ Flash housing

Clean the Glass Windows on

- ☒ Main system housing
- ☐ Flash housing

NT, MCS, GTCD Check the site system is working

- ☒ UPS power indicator is ON (Green)
- ☒ Main Computer Unit power supply indicator is ON
- ☐ Main Computer Unit Cooling fan is operating
- ☒ Router power indicator is ON
- ☒ Camera body power indicators are ON
- ☒ Check Date and Time is correct
- ☐ Test image taken and TCO have been Notified [REDACTED]

Name of TCO Officer contacted: [REDACTED]

DRCS Sites

- ☐ Main Computer Unit power supply indicator is ON
- ☐ Main Computer Unit Cooling fan is operating
- ☐ Check all connections are secure
- ☐ Router power indicator is ON
- ☐ Camera body power indicators are ON
- ☐ Check Date and Time is correct
- ☐ Test image taken and TCO have been Notified.

Name of TCO Officer contacted: [REDACTED]

Comments Flash unit lens cracked / broken.

Maintenance Officer's Signature [REDACTED] Date 14.11.13

TCO Officer's Signature [REDACTED] Date 15.11.13.



ACT
Government

Road Transport Authority
PO Box 582
Dickson ACT 2602
Telephone: 13 22 81

70,050 (12/2012)

Site Report

Date 26-11-13 Start 10.03 Finish 10.23

Location HINDMARSH TURN PKWY Location code 1008

Maintenance Officer [REDACTED]

Truvello / Loop card serial number 004080PS

Plezo / Loop Examination

- ☒ In-road sensors
- ☒ Road surface near sensors in good condition

Look for vandalism

- ☒ Main system housing
- ☒ Flash housing

Clean the Glass Windows on

- ☒ Main system housing
- ☒ Flash housing

NT, MCS, GTCD Check the site system is working

- ☒ UPS power Indicator is ON (Green)
- ☒ Main Computer Unit power supply indicator is ON
- ☒ Main Computer Unit Cooling fan is operating
- ☒ Router power indicator is ON
- ☒ Camera body power Indicators are ON
- ☒ Check Date and Time is correct
- ☐ Test Image taken and TCO have been Notified.

Name of TCO Officer contacted: [REDACTED]

DRCS Sites

- ☐ Main Computer Unit power supply indicator is ON
- ☐ Main Computer Unit Cooling fan is operating
- ☐ Check all connections are secure
- ☐ Router power indicator is ON
- ☐ Camera body power Indicators are ON
- ☐ Check Date and Time is correct
- ☐ Test Image taken and TCO have been Notified.

Name of TCO Officer contacted: [REDACTED]

Comments
<i>Completed</i>

Maintenance Officer's Signature [REDACTED] Date 26-11-13

TCO Officer's Signature [REDACTED] Date 26/11/13

ACT
Government

70,050 (12/2012)

Date 10-12-13 Start 11:50 Finish 12:55

Location	HINDMARSH - Tuna PKWY	Location code	1008
----------	-----------------------	---------------	------

Maintenance Officer [REDACTED]

Truvello / Loop card serial number	00A080PS
------------------------------------	----------

- ☒ In-road sensors
- ☒ Road surface near sensors in good condition

- ☒ Main system housing
☒ Flash housing

- ☒ UPS power indicator is ON (Green)
- ☒ Main Computer Unit power supply indicator is ON
- ☒ Main Computer Unit Cooling fan is operating
- ☒ Router power indicator is ON
- ☒ Camera body power indicators are ON
- ☒ Check Date and Time is correct
- ☐ Test Image taken and TCO have been Notified.

Name of TCO Officer contacted: [REDACTED]

- ☐ Main Computer Unit power supply indicator is ON
- ☐ Main Computer Unit Cooling fan is operating
- ☐ Check all connections are secure
- ☐ Router power indicator is ON
- ☐ Camera body power indicators are ON
- ☐ Check Date and Time is correct
- ☐ Test Image taken and TCO have been Notified.

Name of TCO Officer contacted: _____

Comments
COMPUTER FROZEN AT 11:59. REBOOT COMPUTER.
MIL DLL ERROR MESSAGES. BACK ON LINE AT 12:47.
FLASH Mousing KEY BROKEN IN LOCK.
Completed

Maintenance Officer's Signature	Date	10-12-13
---------------------------------	------	----------

TCO Officer's Signature _____ Date 10/12/13



ACT
Government

Road Transport Authority
PO Box 582
Dickson ACT 2602
Telephone: 13 22 81

70,050 (12/2012)

Site Report

Date 16.12.13 Start 12.15 Finish 13:15

Location Hindmarsh Drive Location code 1008

Maintenance Officer

Truvello / Loop card serial number AU 80PS

Piezo / Loop Examination

- ☒ In-road sensors
- ☒ Road surface near sensors in good condition

Clean the Glass Windows on

- ☒ Main system housing
- ☒ Flash housing

Look for vandalism

- ☒ Main system housing
- ☒ Flash housing

Flash glass broken & loose in housing

NT, MCS, GTCD Check the site system is working

- ☒ UPS power indicator is ON (Green)
- ☒ Main Computer Unit power supply indicator is ON
- ☒ Main Computer Unit Cooling fan is operating
- ☒ Router power indicator is ON
- ☒ Camera body power indicators are ON
- ☒ Check Date and Time is correct
- ☒ Test image taken and TCO have been Notified.

Name of TCO Officer contacted:

DRCS Sites

- ☐ Main Computer Unit power supply indicator is ON
- ☐ Main Computer Unit Cooling fan is operating
- ☐ Check all connections are secure
- ☐ Router power indicator is ON
- ☐ Camera body power indicators are ON
- ☐ Check Date and Time is correct
- ☐ Test image taken and TCO have been Notified.

Name of TCO Officer contacted:

Comments C.C. Replaced capture cards.

Completed

Maintenance Officer's Signature Date 16.12.13

TCO Officer's Signature Date 16/12/13



Road Transport Authority
PO Box 582
Dickson ACT 2602
Telephone: 13 22 81

70,050 (12/2012)

Site Report

Date 10-1-14 Start 14.05 Finish 14.23

Location HINDMARSH - TULLA PKWY Location code 1008

Maintenance Officer [REDACTED]

Truvello / Loop card serial number 004V 80PS

Piezo / Loop Examination

- ☒ In-road sensors
- ☒ Road surface near sensors in good condition

Look for vandalism

- ☒ Main system housing
- ☒ Flash housing

Clean the Glass Windows on

- ☒ Main system housing
- ☒ Flash housing

NT, MCS, GTCD Check the site system is working

- ☒ UPS power indicator is ON (Green)
- ☒ Main Computer Unit power supply indicator is ON
- ☒ Main Computer Unit Cooling fan is operating
- ☒ Router power indicator is ON
- ☒ Camera body power indicators are ON
- ☒ Check Date and Time is correct
- ☐ Test image taken and TCO have been Notified.

Name of TCO Officer contacted: [REDACTED]

DRCS Sites

- ☐ Main Computer Unit power supply indicator is ON
- ☐ Main Computer Unit Cooling fan is operating
- ☐ Check all connections are secure
- ☐ Router power indicator is ON
- ☐ Camera body power indicators are ON
- ☐ Check Date and Time is correct
- ☐ Test image taken and TCO have been Notified.

Name of TCO Officer contacted: [REDACTED]

Comments
<u>Completed</u>

Maintenance Officer's Signature [REDACTED] Date 10-1-14

TCO Officer's Signature [REDACTED] Date 10/1/14



ACT
Government

Road Transport Authority
PO Box 582
Dickson ACT 2602
Telephone: 13 22 81

70,050 (12/2012)

Site Report

Date 21-1-14 Start 11:00 Finish 11:21

Location HINDMARSH - TUGG PKWY Location code 1008

Maintenance Officer [REDACTED]

Truvello / Loop card serial number 004V80PS

Piezo / Loop Examination

- ☒ In-road sensors
- ☒ Road surface near sensors in good condition

Look for vandalism

- ☒ Main system housing
- ☒ Flash housing

NT, MCS, GTCD Check the site system is working

- ☒ UPS power indicator is ON (Green)
- ☒ Main Computer Unit power supply indicator is ON
- ☒ Main Computer Unit Cooling fan is operating
- ☒ Router power indicator is ON
- ☒ Camera body power indicators are ON
- ☒ Check Date and Time is correct
- ☐ Test image taken and TCO have been Notified.

Clean the Glass Windows on

- ☒ Main system housing
- ☒ Flash housing

Name of TCO Officer contacted: [REDACTED]

DRCS Sites

- ☐ Main Computer Unit power supply indicator is ON
- ☐ Main Computer Unit Cooling fan is operating
- ☐ Check all connections are secure
- ☐ Router power indicator is ON
- ☐ Camera body power indicators are ON
- ☐ Check Date and Time is correct
- ☐ Test image taken and TCO have been Notified.

Name of TCO Officer contacted: [REDACTED]

Comments
<u>RESTART MODEM</u>

Maintenance Officer's Signature [REDACTED] Date 21-1-14

TCO Officer's Signature [REDACTED] Date 22-1-14



Traffic Camera Office
EQUIPMENT WORK REQUEST/REPAIR FORM
Work Order Number: 0078-2012

Work Order Status History:

24-Apr-2012 -- 01:40 pm -- Completed -- John Peti
 24-Apr-2012 -- 01:10 pm -- Initiated -- John Peti

Brief Summary of Work Required:

Removed Truvelo 00AU81PS for recertification and installed spare Truvelo 00AU92PS.

Fixed Site Affected: 1008-E

Piezo Strip -- Weston -- Intersection of Hindmarsh Dr & Tuggeranong Pkwy - East

Equipment Requiring Work:

00AU81 PS Serial Number: 00AU81 PS -- Remove and send for Certification.

DETAILS OF WORK COMPLETED (Contractors must provide a summary report of the work completed.)

As Above.

PARTS SUPPLIED / REPLACED/ SERIAL NUMBER

N/A

Device estimated time back on line:

(Contractors must sign and date)

Technicians Signature: _____

Date: _____

24/4/12

SECTION 2 (Office only use)

Traffic Camera Office action

Traffic camera back in use, Time _____

Date _____

Signature: _____

Date: _____

Operations Supervisor Name: _____



Traffic Camera Office
EQUIPMENT WORK REQUEST/REPAIR FORM
Work Order Number: 0097-2012

Work Order Status History:

10-May-2012 -- 01:00 pm -- Completed -- John Peti
 10-May-2012 -- 09:45 am -- Initiated -- John Peti

Brief Summary of Work Required:

Removed spare Truvelo 00AU92PS and installed recertified Truvelo 00AU81PS and conducted 3x test runs per lane.

Fixed Site Affected: 1008-E

Piezo Strip -- Weston -- Intersection of Hindmarsh Dr & Tuggeranong Pkwy - East

Equipment Requiring Work:

DETAILS OF WORK COMPLETED (Contractors must provide a summary report of the work completed.)

As Above -

PARTS SUPPLIED / REPLACED/ SERIAL NUMBER

NIL.

Device estimated time back on line:

(Contractors must sign and

Technicians Signature: _____

Date: 10/5/12

SECTION 2 (Office only use)

Traffic Camera Office action

Traffic camera back in use, Time _____ Date _____

Signature: _____

Date: _____

Operations Supervisor Name: _____



Traffic Camera Office
EQUIPMENT WORK REQUEST/REPAIR FORM
 Work Order Number: 0077-2013

Work Order Status History:

16-Apr-2013 -- 09:09 am -- Initiated -- John Peti

Brief Summary of Work Required:

Remove 00AU81PS & install spare Truvelo 00AU92PS.

Fixed Site Affected: 1008-E

Piezo Strip -- Weston -- Intersection of Hindmarsh Dr & Tuggeranong Pkwy - East

Equipment Requiring Work:

00AU81 PS Serial Number: 00AU81 PS -- Remove and send for Certification.

DETAILS OF WORK COMPLETED (Contractors must provide a summary report of the work completed.)

As Above.

OFFLINE: 10:17 HRS 16/4/13.

ONLINE: 10:38 HRS 16/4/13.

PARTS SUPPLIED / REPLACED / SERIAL NUMBER

Nil.

Device estimated time back on line:

(Contractors must sign a

Technicians Signature:

Date: 17/4/13

SECTION 2 (Office only use)

Traffic Camera Office action

Traffic camera back in use, Time _____ Date _____

Signed

Date:

8/5/13

Operations Supervisor Name:



**Traffic Camera Office
EQUIPMENT WORK REQUEST/REPAIR FORM
Work Order Number: 0091-2013**

Work Order Status History:

24-Apr-2013 -- 04:30 pm -- Completed -- Gordon Stone
24-Apr-2013 -- 02:00 pm -- Initiated -- Gordon Stone

Brief Summary of Work Required:

Remove 92PS Install 82PS

Fixed Site Affected: 1008-E

Piezo Strip -- Weston -- Intersection of Hindmarsh Dr & Tuggeranong Pkwy - East

Equipment Requiring Work:

Piezoelectric Axle Sensor at Site 1008 -- Conduct 3 test runs per lane

DETAILS OF WORK COMPLETED (Contractors must provide a summary report of the work completed.)

REMOVED SPARE TRAVELER AW92PS, INSTALLED RECERTIFIED TRAVELER AW81PS
+ ATTEMPT (UNSUCCESSFULLY!) TEST RUNS.

SUSPECT TRAVELER AW81PS IS FAULTY AS IT DOES NOT DETECT VEH'S RELIABLY.

REINSTALLED SPARE TRAVELER AW92PS.

PARTS SUPPLIED / REPLACED / SERIAL NUMBER

OFF: 14:35 HRS 24/4/13.

ON 16:17 HRS 24/4/13.

Device estimated time back on line:

(Contractors must sign

Technicians Signature: _____

Date: 24/4/13

SECTION 2 (Office only use)

Traffic Camera Office action

Traffic camera back in use, Time _____

Date _____

Check [redacted] voice N-3220 Job Completed.

Signature: _____

Date: 14/6/13

Operations Supervisor Name: _____



**Traffic Camera Office
EQUIPMENT WORK REQUEST/REPAIR FORM
Work Order Number: 0092-2013**

Work Order Status History:

24-Apr-2013 -- 04:37 pm -- Initiated -- Gordon Stone

Brief Summary of Work Required:

check Piezo strips, Remove 92PS Install re certified Truvello

Fixed Site Affected: 1008-E

Piezo Strip -- Weston -- Intersection of Hindmarsh Dr & Tuggerahong Pkwy - East

Equipment Requiring Work:

Piezoelectric Axle Sensor at Site 1008 -- Check system remove Truvello 92 install re certified Truvello

DETAILS OF WORK COMPLETED (Contractors must provide a summary report of the work completed.)

Removed SPARE TRUVELLO AU92 PS

INSTALLED SPARE TRUVELLO AU80 PS + CONDUCTED TEST RUNS.

OFF: 12:55 HRS 29/4/13.

ON: 14:36 HRS 29/4/13.

PARTS SUPPLIED / REPLACED/ SERIAL NUMBER

NIL.

NOTE: SUSPECT RECTIFIED TRUVELLO AU80 PS IS FAULTY.

Device estimated time back on line:

(Contractors must sign)

Technicians Signature:

Date: 7/5/13

SECTION 2 (Office only use)

Traffic Camera Office action

Traffic camera back in use, Time _____ Date _____

Signature:

Date:

Operations Supervisor Name:

checked against Invoice N-3220. Job Completed.

14/06/13



**Traffic Camera Office
EQUIPMENT WORK REQUEST/REPAIR FORM
Work Order Number: 0146-2013**

Work Order Status History:

15-Aug-2013 -- 09:19 am -- Initiated -- Gordon Stone

Brief Summary of Work Required:

re-establish connection to device and camera

Fixed Site Affected: 1008-E

Piezo Strip -- Weston -- Intersection of Hindmarsh Dr & Tuggeranong Pkwy - East

Equipment Requiring Work:

Piezoelectric Axle Sensor at Site 1008 -- Can not connect to device

DETAILS OF WORK COMPLETED (Contractors must provide a summary report of the work completed.)

AS ABOVE. RESTRICTED ROUTE.

PARTS SUPPLIED / REPLACED/ SERIAL NUMBER

Nil.

Device estimated time back on line

(Contractors must sign)

Technicians Signature: _____

Date: 27/8/13

SECTION 2 (Office only use)

Traffic Camera Office action

Traffic camera back in use, Time _____

Date _____

Signature: _____

Date: 02-10-2013

Operations: _____



Traffic Camera Office
EQUIPMENT WORK REQUEST/REPAIR FORM
 Work Order Number: 0185-2013

Work Order Status History:

16-Dec-2013 -- 08:18 am -- Initiated -- Gordon Stone

Brief Summary of Work Required:

MIL DLL error message

Fixed Site Affected: 1008-E

Piezo Strip -- Weston -- Intersection of Hindmarsh Dr & Tuggeranong Pkwy - East

Equipment Requiring Work:

Piezoelectric Axle Sensor at Site 1008 -- Repair device

DETAILS OF WORK COMPLETED (Contractors must provide a summary report of the work completed.)

As Above. REPLACED CAPTURE CAMDS.

PARTS SUPPLIED / REPLACED/ SERIAL NUMBER

NIL.

Device estimated time back on line: 13:04 HRS

(Contractors must sign and)

Technicians Signature: _____

Date: 18/12/13

SECTION 2 (Office only use)

Traffic Camera Office action

Traffic camera back in use, Time 13:04 Date 18/12/13

Signature: _____

Date: 18/12/13

Operations Supervisor Name: _____



**Traffic Camera Office
EQUIPMENT WORK REQUEST/REPAIR FORM
Work Order Number: 0042-2014**

Work Order Status History:

19-Feb-2014 -- 09:44 am -- Initiated -- John Peti

Brief Summary of Work Required:

Remove all contents from 1008-E & install into 1002.

Fixed Site Affected: 1008-E

Piezo Strip -- Weston -- Intersection of Hindmarsh Dr & Tuggeranong Pkwy - East

Equipment Requiring Work:

DETAILS OF WORK COMPLETED (Contractors must provide a summary report of the work completed.)

Removed all equipment from site 1008E on 20/02/2014. Began preparing Poltec from site 1008E to be installed at site 1002N. Poltec at site 1002N was not replaced.

Site 1002N:

Offline at 13:30hrs on 20/02/2014.

Online at 14:19hrs on 20/02/2014.

PARTS SUPPLIED / REPLACED/ SERIAL NUMBER

Nil.

Device estimated time back on line: _____

(Contractors must sign and date)

Technicians Signature: _____

Date: 20/02/2014

SECTION 2 (Office only use)

Traffic Camera Office action

Traffic camera back in use, Time 14:19 HRS Date 20-02-2014

COMPLETED

Signature: _____

Date: 20-02-2014

Operation: _____



Traffic Camera Office
EQUIPMENT WORK REQUEST/REPAIR FORM
Work Order Number: 0151-2014

Work Order Status History:

21-Aug-2014 -- 11:08 am -- Initiated -- Tony Taseski

Brief Summary of Work Required:

Fix site 1008 Radar RT3 serial number 201404000551. Conduct 3 test runs per lane.

Fixed Site Affected:

-- --

Equipment Requiring Work:

DETAILS OF WORK COMPLETED (Contractors must provide a summary report of the work completed.)

AS ABOVE

PARTS SUPPLIED / REPLACED/ SERIAL NUMBER

Device estimated time back on line: _____

(Contractors must sign)

Technicians Signature: _____

Date: 21/8/2014

SECTION 2 (Operations Supervisor)

Traffic Camera Office

Traffic camera back in use, Time

15:05

Date

21/8/14

Signature

Date:

21/8/14

Operations Supervisor Name

Associated data records for the period of 01/11/2013 until 01/12/2013 in relation to the speed measuring device located at the intersection of Hindmarsh Drive and Tuggeranong Parkway, Weston

LOCATION_CODE	OFFENCE_DATE	INF_TIME	SPEED_LIMIT	RLC_ACTION_CODE				Legend		
1008	02/11/2013	12:07:50	80	R				R	Red Light Camera	
1008	03/11/2013	19:33:49	80	S				S	Speeding	
1008	15/11/2013	23:07:25	80	R						
1008	26/11/2013	11:20:58	80	R						