

From: Sch 2.2(a)(ii)
Sent: 15/12/2022 8:23 AM
To: "WorkSafe" <WorkSafe@worksafe.act.gov.au>
Subject: Un retained cut affecting Sch 2.2(a)(ii) strathnairn

Caution: This email originated from outside of the ACT Government. Do not click links or open attachments unless you recognise the sender and know the content is safe. [Learn why this is important](#)

Good morning.
Thanks for

taking my call yesterday. Attached are some images depicting the site cut performed at Strathnairn.

After repeated attempts with trying to resolve this matter directly with Acheive homes being unsuccessful. I was hoping Worksafe ACT could be of assistance.

My finished residence at Sch 2.2(a)(ii) Sch 2.2(a)(ii).

We are unable to erect a fence , even if we did our side boundary is supposed to be 960mm from our building. With the past rain events some of the bank has collapsed reducing the boundary to in some places around 680mm, therefore creating an even greater hazard. The Nominal depth of the neighbors cut is around 900mm have attached some images.

Would it be possible to access this situation


I appreciate your help in this matter ,

Please don't hesitate to call me if you have any questions









Kind Regards

Sch 2.2(a)(ii)

















