



ENVIRONMENTAL & INDUSTRIAL LABORATORIES

P.O. BOX 653, UNLEY, SOUTH AUSTRALIA 5061 PHONE 274 1396
 P.O. BOX 76, DICKSON, A.C.T. 2602 PHONE 48 7801
 P.O. BOX 52, HAYMARKET, N.S.W. 2000 PHONE 698 2270



RESULTS OF AIRBORNE FIBRE MONITORING AT WODEN SHOPPING SQUARE

CONTRACTOR ASBESTOS EXTRACTORS

DATE 15-16/06/87

SLIDE NO.	POSITION	ON.	OFF.	F/ML.	
WP927	adj. growing concern	1749	2050	0.04	X
WP928	adj. collins book sellers	1750	2052	0.03	X
WP929	change	1822	2104	*****	
WP930	clean decon	1823	2103	*****	
WP931	adj. growing concern	2050	0047	<.01	
WP932	adj. collins booksellers	2052	0048	0.02	
WP933	lunchroom	2058	0055	<.01	
WP934	laundry	2100	0056	<.01	
WP935	clean decon	2103	0059	*****	
WP936	change	2104	0100	*****	
WP937	adj. growing concern	0047	0426	<.01	
WP938	adj. collins booksellers	0048	0427	<.01	
WP939	lunchroom	0055	0433	<.01	
WP940	laundry	0056	0434	<.01	
WP941	change	0100	0419	<.01	
WP942	clean decon	0059	0420	<.01	

WORK IN PROGRESS: ***** too dirty to read - some fibre present.
 final clean in preparation for clearances & inspection.

John Rolson
 FOR EIL

X DENOTES LEVEL = TO OR
 GREATER THAN SPECIFIED
 LIMIT.



ENVIRONMENTAL & INDUSTRIAL LABORATORIES

P.O. BOX 653, UNLEY, SOUTH AUSTRALIA 5061 PHONE 274 1396
 P.O. BOX 76, DICKSON, A.C.T. 2602 PHONE 48 7801
 P.O. BOX 52, HAYMARKET, N.S.W. 2000 PHONE 698 2270



RESULTS OF AIRBORNE FIBRE MONITORING AT WODEN SHOPPING SQUARE

CONTRACTOR ASBESTOS EXTRACTORS

DATE 14/06/87

SLIDE NO.	POSITION	ON.	OFF.	F/ML.
WP 911	adj. growing concern	1741	2052	<.01
WP 912	' collins book sellers	1745	2053	<.01
WP 913	clean decon	1752	2105	<.01 *
WP 914	change	1753	2106	<.01 *
WP 915	adj. growing concern	2052	0050	<.01
WP 916	adj. collins book sellers	2053	0051	<.01
WP 917	clean decon	2105	0102	<.01 **
WP 918	change	2106	0104	<.01 **
WP 919	lunchroom	2056	0058	<.01
WP 920	laundry	2055	0059	<.01
WP 921	change	0102	0430	<.01 *
WP 922	clean decon	0104	0431	<.01 *
WP 923	laundry	0059	0425	<.01
WP 924	lunchroom	0058	0426	<.01
WP 925	adj. growing concern	0050	0410	<.01
WP 926	adj. collins book sellers	0051	0411	<.01

WORK IN PROGRESS:

- * heavy background dust.
- ** very heavy background dust.
- final clean of area.

John Robson

FOR EIL

X DENOTES LEVEL = TO OR GREATER THAN SPECIFIED LIMIT.



ENVIRONMENTAL & INDUSTRIAL LABORATORIES

P.O. BOX 653, UNLEY, SOUTH AUSTRALIA 5061 PHONE 274 1396
 P.O. BOX 76, DICKSON, A.C.T. 2602 PHONE 48 7801
 P.O. BOX 52, HAYMARKET, N.S.W. 2000 PHONE 698 2270



RESULTS OF AIRBORNE FIBRE MONITORING AT WODEN SHOPPING SQUARE

CONTRACTOR ASBESTOS EXTRACTORS

DATE 05/06/87

SLIDE NO.	POSITION	ON.	OFF.	F/ML.
WP 867	1st floor adj. F6	0701	1232	<.01
WP 868	' ' adj. fire exit	0700	1233	<.01
WP 869	top of new stairs	0705	1235	<.01
WP 870	adj. claridges	0703	1236	<.01
WP 871	adj. DJ's bar	0709	1238	<.01
WP 872	adj. DJ's restaurant	0708	1239	<.01

WORK IN PROGRESS: demounting 1st floor removal area.

John Rolise
 FOR EIL

X DENOTES LEVEL = TO OR GREATER THAN SPECIFIED LIMIT.



ENVIRONMENTAL & INDUSTRIAL LABORATORIES

P.O. BOX 653, UNLEY, SOUTH AUSTRALIA 5061 PHONE 274 1396
 P.O. BOX 76, DICKSON, A.C.T. 2602 PHONE 48 7801
 P.O. BOX 52, HAYMARKET, N.S.W. 2000 PHONE 698 2270



RESULTS OF AIRBORNE FIBRE MONITORING AT WODEN SHOPPING SQUARE

CONTRACTOR ASBESTOS EXTRACTORS DATE 4/6/87

SLIDE NO.	POSITION.	ON.	OFF.	F/ML.
WP 855	1st. floor adjacent F6	0744	1156	<.01
WP 856	1st. floor adj. fire exit	0742	1158	<.01
WP 857	top of new stairs	0735	1151	<.01
WP 858	adjacent Claridges	0732	1149	<.01
WP 859	adjacent D.J's restaurant	0737	1145	<.01
WP 860	' ' bar	0740	1147	<.01
WP 861	1st. floor adjacent F6	1156	1750	<.01
WP 862	' ' fire exit	1158	1749	<.01
WP 863	top of new stairs	1151	1747	<.01
WP 864	adjacent Claridges	1149	1746	<.01
WP 865	adjacent D.J's restaurant	1145	1744	<.01
WP 866	' ' bar	1147	1743	<.01

WORK IN PROGRESS: plastic demount 1st floor level.

John Rolso
 FOR EIL

X DENOTES LEVEL = TO OR
 GREATER THAN SPECIFIED
 LIMIT.



ENVIRONMENTAL & INDUSTRIAL LABORATORIES

P.O. BOX 653, UNLEY, SOUTH AUSTRALIA 5061 PHONE 274 1396
 P.O. BOX 76, DICKSON, A.C.T. 2602 PHONE 48 7801
 P.O. BOX 52, HAYMARKET, N.S.W. 2000 PHONE 698 2270



RESULTS OF AIRBORNE FIBRE MONITORING AT WODEN SHOPPING SQUARE
CONTRACTOR ASBESTOS EXTRACTORS DATE 03/06/87

SLIDE NO.	POSITION	ON.	OFF.	F/ML.
WP849	1st floor adj. F6	1805	2126	<.01
WP850	' ' adj. fire exit	1806	2125	<.01
WP851	top of new stairs	1808	2134	<.01
WP852	adj. claridges	1810	2132	<.01
WP853	adj. DJ's bar	1814	2130	<.01
WP854	adj. DJ's restaurant	1812	2129	<.01

WORK IN PROGRESS: plastic demount on first floor area.

John Rolso
 FOR EIL

X DENOTES LEVEL = TO OR
 GREATER THAN SPECIFIED
 LIMIT.



ENVIRONMENTAL & INDUSTRIAL LABORATORIES

P.O. BOX 853, UNLEY, SOUTH AUSTRALIA 5061 PHONE 274 1396
 P.O. BOX 76, DICKSON, A.C.T. 2602 PHONE 48 7801
 P.O. BOX 52, HAYMARKET, N.S.W. 2000 PHONE 698 2270



RESULTS OF AIRBORNE FIBRE MONITORING AT WODEN SHOPPING SQUARE
 CONTRACTOR ASBESTOS EXTRACTORS DATE 02/06/87

SLIDE NO.	POSITION	ON.	OFF.	F/ML.
WP841	south change	1643	1743	<.01
WP842	south clean decon	1644	1744	<.01
WP843	dirty decon	1647	1748	<.01
WP844	beams from southern end 1	1648	1749	<.01
WP845	' ' 2	1649	1750	<.01
WP846	' ' 3	1650	1751	<.01
WP847	' ' 4	1651	1752	<.01
WP848	tunnel adj. decons	1652	1753	<.01

WORK IN PROGRESS: p.v.a. and initial clearances.

John Robson

FOR EIL

X DENOTES LEVEL = TO OR
 GREATER THAN SPECIFIED
 LIMIT.



ENVIRONMENTAL & INDUSTRIAL LABORATORIES

P.O. BOX 653, UNLEY, SOUTH AUSTRALIA 5061 PHONE 274 1396
 P.O. BOX 76, DICKSON, A.C.T. 2602 PHONE 48 7801
 P.O. BOX 52, HAYMARKET, N.S.W. 2000 PHONE 698 2270



RESULTS OF AIRBORNE FIBRE MONITORING AT WODEN SHOPPING SQUARE

CONTRACTOR ASBESTOS EXTRACTORS

DATE 01-02.6.87

SLIDE NO.	POSITION	ON	OFF	F/ML	
WP814	south change	1821	2107	0.03	
WP815	south clean decon	1820	2108	0.04	
WP816	top of new stairs	1828	2051	<.01	
WP817	adj. Claridges	1842	2049	<.01	
WP818	adj. DJ's Bar	1831	2053	<.01	
WP819	adj. DJ's Restaurant	1830	2052	<.01	
WP820	1st floor adj. fire exit	1825	2056	<.01	
WP821	adj. Claridges	2049	0046	<.01	
WP822	top of new stairs	2051	0047	<.01	
WP823	adj. DJ's Restaurant	2052	0044	<.01	
WP824	adj. DJ's Bar	2053	0045	<.01	
WP825	1st floor adj. fire exit	2056	0037	<.01	
WP826	lunchroom	2101	0050	<.01	
WP827	laundry	2106	0051	<.01	
WP828	south change	2107	0053	0.04	
WP829	south clean decon	2108	0052	0.04	
WP830	1st floor adj. fire exit	0037	0422	<.01	
WP831	top of new stairs	0047	0424	<.01	
WP832	adj. Claridges	0046	0423	<.01	
WP833	adj. DJ's Restaurant	0044	0426	<.01	
WP834	adj. DJ's Bar	0045	0427	<.01	
WP835	lunchroom	0050	0432	<.01	
WP836	laundry	0051	0431	<.01	
WP837	south change	0053	0448	0.06 X	
WP838	south clean decon	0052	0447	0.07 X	
WP839	south change	s.t.	1110	1345	0.01
WP840	south clean decon	s.t.	1111	1346	0.01

WORK IN PROGRESS: final clean in preparation for inspection.

John Robson

FOR EIL

X DENOTES LEVEL = TO OR
 GREATER THAN SPECIFIED
 LIMIT.



ENVIRONMENTAL & INDUSTRIAL LABORATORIES

P.O. BOX 653, UNLEY, SOUTH AUSTRALIA 5061 PHONE 274 1396
 P.O. BOX 76, DICKSON, A.C.T. 2602 PHONE 48 7801
 P.O. BOX 52, HAYMARKET, N.S.W. 2000 PHONE 698 2270



RESULTS OF AIRBORNE FIBRE MONITORING AT WODEN SHOPPING SQUARE

CONTRACTOR ASBESTOS EXTRACTORS

DATE 31/05/87
01/06/87

SLIDE NO.	POSITION	ON.	OFF.	F/ML.	
WP787	south change	1849	2115	0.01	
WP788	' ' clean decon	1850	2116	0.01	
WP789	top of new stairs	1842	2101	<.01	
WP790	adj. claridges	1858	2100	<.01	
WP791	adj. DJ's restaurant	1844	2105	<.01	
WP792	adj. DJ' bar	1845	2106	<.01	
WP793	1st floor adj. fire exit	1838	2056	<.01	
WP794	lunchroom	2110	0100	<.01	
WP795	laundry	2112	0102	<.01	
WP796	south clean decon	2116	0104	0.11	X
WP797	' ' change	2115	0105	0.11	X
WP798	top of new stairs	2101	0054	<.01	
WP799	adj. claridges	2100	0052	<.01	
WP800	adj. DJ's restaurant	2105	0055	<.01	
WP801	adj. DJ's bar	2106	0056	<.01	
WP802	1st floor adj. fire exit	2056	0045	<.01	
WP803	lunchroom	0100	0508	<.01	
WP804	laundry	0102	0509	<.01	
WP805	south clean decon	0104	0207	<.01	
WP806	' ' change	0105	0206	<.01	
WP807	top of new stairs	0054	0502	<.01	
WP808	adj. claridges	0052	0501	<.01	
WP809	adj. DJ's restaurant	0055	0503	<.01	
WP810	adj. DJ's bar	0056	0504	<.01	
WP811	1st floor adj. fire exit	0045	0500	<.01	
WP812	south clean decon	0207	0510	<.01	
WP813	' ' change	0206	0511	<.01	

WORK IN PROGRESS: removal.

John Robson

FOR EIL

X DENOTES LEVEL = TO OR GREATER THAN SPECIFIED LIMIT.



ENVIRONMENTAL & INDUSTRIAL LABORATORIES

P.O. BOX 653, UNLEY, SOUTH AUSTRALIA 5061 PHONE 274 1396
 P.O. BOX 76, DICKSON, A.C.T. 2602 PHONE 48 7801
 P.O. BOX 52, HAYMARKET N.S.W. 2000 PHONE 698 2270



RESULTS OF AIRBORNE FIBRE MONITORING AT WODEN SHOPPING SQUARE

CONTRACTOR ASBESTOS EXTRACTORS

DATE 30-31/05/87

SLIDE NO.	POSITION	ON.	OFF.	F/ML.	
WP778	south change	1802	2101	0.75	X
WP779	' ' clean decon	1803	2102	0.73	X
WP780	1st floor adj. fire exit	1755	2055	<.01	
WP781	adj. claridges	1748	2048	<.01	
WP782	top of new stairs	1749	2049	<.01	
WP783	adj. DJ's restaurant	1751	2051	<.01	
WP784	adj. DJ's bar	1752	2052	<.01	
WP785	south change s.t.	0959	1118	<.01	
WP786	south clean decon s.t.	1000	1119	<.01	

WORK IN PROGRESS: removal through south decon.

FOR EIL

X DENOTES LEVEL = TO OR GREATER THAN SPECIFIED LIMIT.



ENVIRONMENTAL & INDUSTRIAL LABORATORIES

P.O. BOX 653, UNLEY, SOUTH AUSTRALIA 5061 PHONE 274 1396
 P.O. BOX 76, DICKSON, A.C.T. 2602 PHONE 48 7801
 P.O. BOX 52, HAYMARKET, N.S.W. 2000 PHONE 698 2270



RESULTS OF AIRBORNE FIBRE MONITORING AT WODEN SHOPPING SQUARE

CONTRACTOR ASBESTOS EXTRACTORS

DATE 29-30/05/87

SLIDE NO.	POSITION	ON.	OFF.	F/ML.
WP762	south change	2126	0054	<.01
WP763	' ' clean decon	2125	0055	<.01
WP764	top of new stairs	2128	0043	<.01
WP765	adj. claridges	2130	0042	<.01
WP766	1st floor adj. fire exit	2134	0039	<.01
WP767	adj. DJ's bar	2142	0046	<.01
WP768	adj. DJ's restaurant	2141	0045	<.01
WP769	lunchroom	0052	0421	<.01
WP770	laundry	0053	0418	<.01
WP771	top of new stairs	0043	0413	<.01
WP772	adj. claridges	0042	0412	<.01
WP773	adj. DJ's restaurant	0045	0414	<.01
WP774	adj. DJ's bar	0046	0415	<.01
WP775	1st floor adj. fire exit	0039	0409	<.01
WP776	south clean decon	0055	0420	<.01
WP777	' ' change	0054	0419	<.01

WORK IN PROGRESS: removal through south decon unit.

John Rolso
FOR EIL

X DENOTES LEVEL = TO OR GREATER THAN SPECIFIED LIMIT.



ENVIRONMENTAL & INDUSTRIAL LABORATORIES

P.O. BOX 653, UNLEY, SOUTH AUSTRALIA 5061 PHONE 274 1396
 P.O. BOX 76, DICKSON, A.C.T. 2602 PHONE 48 7801
 P.O. BOX 52, HAYMARKET, N.S.W. 2000 PHONE 698 2270



RESULTS OF AIRBORNE FIBRE MONITORING AT WODEN SHOPPING SQUARE

CONTRACTOR ASBESTOS EXTRACTORS

DATE 28-29.5.87

SLIDE NO.	POSITION	ON.	OFF.	F/ML.
WP739	top of new stairs	1756	2100	<.01
WP740	adj. Claridges	1755	2059	<.01
WP741	adj. DJ's Bar	1759	2058	<.01
WP742	adj. DJ's Restaurant	1758	2058	<.01
WP743	1st floor fire exit	1800	2055	<.01
WP744	south clean decon	1805	2107	<.01
WP745	south change	1806	2108	<.01
WP746	south clean decon	2107	0008	<.01
WP747	south change	2108	0009	<.01
WP748	adj. Claridges	2059	0015	<.01
WP749	adj. DJ's Bar	2058	0018	<.01
WP750	adj. DJ's Restaurant	2057	0019	<.01
WP751	1st floor adj fire exit	2055	0011	<.01
WP752	top of new stairs	2100	0016	<.01
WP753	lunchroom	2105	0006	<.01
WP754	top of new stairs	0016	0406	<.01
WP755	adj. Claridges	0015	0406	<.01
WP756	adj. DJ's Bar	0018	0407	<.01
WP757	adj. DJ's Restaurant	0019	0408	<.01
WP758	1st floor adj. fire exit	0011	0409	<.01
WP759	lunchroom	0006	0410	<.01
WP760	south clean decon	0008	0419	<.01
WP761	south change	0009	0420	<.01

WORK IN PROGRESS: Stripping.

[Handwritten signature]
FOR EIL

X DENOTES LEVEL = TO OR GREATER THAN SPECIFIED LIMIT.



ENVIRONMENTAL & INDUSTRIAL LABORATORIES

P.O. BOX 653, UNLEY, SOUTH AUSTRALIA 5061 PHONE 274 1396
 P.O. BOX 76, DICKSON, A.C.T. 2602 PHONE 48 7801
 P.O. BOX 52, HAYMARKET, N.S.W. 2000 PHONE 698 2270



RESULTS OF AIRBORNE FIBRE MONITORING AT WODEN SHOPPING SQUARE

CONTRACTOR ASBESTOS EXTRACTORS

DATE 27-28.5.87

SLIDE NO.	POSITION.	ON.	OFF.	F/ML.
WP714	south change	1756	2114	<.01
WP715	' ' clean decon	1757	2115	<.01
WP716	top of new stairs	1746	2101	<.01
WP717	adj. Claridges	1745	2100	<.01
WP718	adj. DJ's Restaurant	1748	2103	<.01
WP719	adj. DJ's Bar	1749	2104	<.01
WP720	1st floor adj. fire exit	1743	2055	<.01
WP721	south change	2114	0118	<.01
WP722	' ' clean decon	2115	0119	<.01
WP723	lunchroom	2110	0116	<.01
WP724	laundry	2112	0117	<.01
WP725	top of new stairs	2101	0108	<.01
WP726	adj. Claridges	2100	0106	<.01
WP727	adj. DJ's Bar	2104	0112	<.01
WP728	adj. DJ's Restaurant	2103	0110	<.01
WP729	1st floor adj. fire exit	2055	0058	<.01
WP730	south change	0118	0233	<.01
WP731	' ' clean decon	0119	0234	<.01
WP732	lunchroom	0116	0230	<.01
WP733	laundry	0117	0231	<.01
WP734	top of new stairs	0108	0239	<.01
WP735	adj. Claridges	0106	0237	<.01
WP736	adj. DJ's Bar	0112	0241	<.01
WP737	adj. DJ's Restaurant	0110	0240	<.01
WP738	1st floor adj. fire exit	0058	0235	<.01

WORK IN PROGRESS: Stripping.

[Signature]
FOR EIL

X DENOTES LEVEL = TO OR GREATER THAN SPECIFIED LIMIT.



ENVIRONMENTAL & INDUSTRIAL LABORATORIES

P.O. BOX 653, UNLEY, SOUTH AUSTRALIA 5061 PHONE 274 1396
 P.O. BOX 76, DICKSON, A.C.T. 2602 PHONE 48 7801
 P.O. BOX 52, HAYMARKET, N.S.W. 2000 PHONE 698 2270



RESULTS OF AIRBORNE FIBRE MONITORING AT WODEN SHOPPING SQUARE
 CONTRACTOR ASBESTOS EXTRACTORS DATE 26.5.87

SLIDE NO.	POSITION.	ON.	OFF.	F/ML.
WP687	south clean decon	1837	2044	<.01
WP688	' ' change	1836	2043	<.01
WP689	1st floor adj. fire exit	1841	2050	<.01
WP690	' ' adj. Jonathons Cafeteria	1846	2051	<.01
WP691	top of new stairs	1850	2054	<.01
WP692	adj. Claridges	1852	2059	<.01
WP693	adj. DJ's Restaurant	1854	2056	<.01
WP694	adj. DJ's Bar	1855	2057	<.01
WP695	south clean decon	2044	0100	<.01
WP696	' ' change	2043	0059	0.01
WP697	lunchroom	2046	0032	<.01
WP698	1st floor adj. fire exit	2050	0052	<.01
WP699	' ' Jonathons Cafeteria	2051	0055	<.01
WP700	top of new stairs	2054	0044	<.01
WP701	adj. DJ's restaurant	2056	0046	<.01
WP702	adj. DJ's Bar	2057	0047	<.01
WP703	adj. Claridges	2059	0042	<.01
WP704	lunchroom	0032	0427	<.01
WP705	laundry	0033	0426	0.03 *
WP706	adj. claridges	0042	0416	<.01
WP707	top of new stairs	0044	0417	<.01
WP708	adj. DJ's restaurant	0046	0419	<.01
WP709	adj. DJ's bar	0048	0420	<.01
WP710	1st floor adj. fire exit	0052	0411	<.01
WP711	' ' Jonathons Cafeteria	0055	0412	<.01
WP712	south change	0059	0438	<.01
WP713	' ' clean decon	0100	0439	<.01

WORK IN PROGRESS: removal through south decon.
 * unlikely to be fibre - mainly lint from dryer.

John Rolosa
 FOR EIL

X DENOTES LEVEL = TO OR GREATER THAN SPECIFIED LIMIT.



INSPECTION RECORD

Nº 175457

Permit Holder: J. MALCOLM

Block: 2 & 3 Section: 8 Suburb: PHILLIP.

Stage: Post P.V.A. to western removal area (fire doors).

A brief inspection of parts of the construction on this site has indicated that:

Work may proceed to next stage
 may not proceed to next stage

The following matters appear to require your attention

Complete cleaning of fire door track runners
& door cavity in walls.

Notify when completed.

OK checked P.M. 17/6/87

Please rebook this inspection stage when rectified

Posted

Left on site

[Signature] 17.6.87
Building Inspector

NOTE: Inspectors can be contacted at the office ONLY BETWEEN 11 am-12 noon.

Permits are granted on the condition that the materials and methods of construction will conform with the acceptable standards set out in the Building Manual, that work will be carried out in a proper and workmanlike manner, in accordance with the approval plan and specifications, with adequate safety precautions, and by the holder of the permit or a person employed by or under contract to him.

Spot checks of construction by the Building Inspector are carried out to enable the Department to administer the Building Ordinance. The Department does not have the role of supervising construction on behalf of owners and is not able to ensure the quality of finish of buildings. It is recommended that if necessary owners engage competent building design and construction consultants to advise them.

It should be noted that this Inspection Record is not intended to provide a certification that the building work complies absolutely with the prescribed requirements. Inspection Records should not be used to indicate satisfactory progress or conformance with contractual arrangements.

NOTE: Inspectors can be contacted at the office ONLY BETWEEN 11 am-12 noon.

Permits are granted on the condition that the materials and methods of construction will conform with the acceptable standards set out in the Building Manual, that work will be carried out in a proper and workmanlike manner, in accordance with the approval plan and specifications, with adequate safety precautions, and by the holder of the permit or a person employed by or under contract to him.

Spot checks of construction by the Building Inspector are carried out to enable the Department to administer the Building Ordinance. The Department does not have the role of supervising construction on behalf of owners and is not able to ensure the quality of finish of buildings. It is recommended that if necessary owners engage competent building design and construction consultants to advise them.

It should be noted that this Inspection Record is not intended to provide a certification that the building work complies absolutely with the prescribed requirements. Inspection Records should not be used to indicate satisfactory progress or conformance with contractual arrangements.



INSPECTION RECORD

No 163048

62

Permit Holder: J. MALCOLM

Block: 243 Section: 8 Suburb: PHILLIP

Stage:

Part PVA to South removal area
beams, columns & ceilings

A brief inspection of parts of the construction on this site has indicated that:

- Work may proceed to next stage
- may not proceed to next stage

The following matters appear to require your attention

Clean up areas as discussed then
ok. Will check at next inspection.

Please rebook this inspection stage when rectified

Posted

Left on site

J. Chamber 3.5.87
Building Inspector

NOTE: Inspectors can be contacted at the office ONLY BETWEEN 11 am–12 noon.

Permits are granted on the condition that the materials and methods of construction will conform with the acceptable standards set out in the Building Manual, that work will be carried out in a proper and workmanlike manner, in accordance with the approval plan and specifications, with adequate safety precautions, and by the holder of the permit or a person employed by or under contract to him.

Spot checks of construction by the Building Inspector are carried out to enable the Department to administer the Building Ordinance. The Department does not have the role of supervising construction on behalf of owners and is not able to ensure the quality of finish of buildings. It is recommended that if necessary owners engage competent building design and construction consultants to advise them.

It should be noted that this Inspection Record is not intended to provide a certification that the building work complies absolutely with the prescribed requirements. Inspection Records should not be used to indicate satisfactory progress or conformance with contractual arrangements.



INSPECTION RECORD

No 163047 ⁶¹

Permit Holder: J MALCOLM

Block: 2+3 Section: 8 Suburb: PHILLIP

Stage: Pre-removal + smoke test. (South removal area)

A brief inspection of parts of the construction on this site has indicated that:

- Work may proceed to next stage
- may not proceed to next stage

The following matters appear to require your attention

Seal up leak at end of tunnel 3 as discussed on site then ok.

Please rebook this inspection stage when rectified

Posted

Left on site

[Signature] 26.5.87
Building Inspector

NOTE: Inspectors can be contacted at the office ONLY BETWEEN 11 am–12 noon.

Permits are granted on the condition that the materials and methods of construction will conform with the acceptable standards set out in the Building Manual, that work will be carried out in a proper and workmanlike manner, in accordance with the approval plan and specifications, with adequate safety precautions, and by the holder of the permit or a person employed by or under contract to him.

Spot checks of construction by the Building Inspector are carried out to enable the Department to administer the Building Ordinance. The Department does not have the role of supervising construction on behalf of owners and is not able to ensure the quality of finish of buildings. It is recommended that if necessary owners engage competent building design and construction consultants to advise them.

It should be noted that this Inspection Record is not intended to provide a certification that the building work complies absolutely with the prescribed requirements. Inspection Records should not be used to indicate satisfactory progress or conformance with contractual arrangements.



ENVIRONMENTAL & INDUSTRIAL LABORATORIES

P.O. BOX 853, UNLEY, SOUTH AUSTRALIA 5061 PHONE 274 1396
 P.O. BOX 76, DICKSON, A.C.T. 2602 PHONE 48 7801
 P.O. BOX 52, HAYMARKET, N.S.W. 2000 PHONE 698 2270

RESULTS OF AIRBORNE FIBRE MONITORING AT WODEN SHOPPING SQUARE

CONTRACTOR ASBESTOS EXTRACTORS

DATE 25-26/05/87

SLIDE NO.	POSITION.	ON.	OFF.	F/ML.
WP659	south change	1729	2100	<.01
WP660	' ' clean decon	1730	2101	****
WP661	north change	1734	2129	<.01
WP662	' ' clean decon	1742	2130	<.01
WP663	top of new stairs	1745	2116	<.01
WP664	adj. claridges	1749	2115	<.01
WP665	adj. DJ's restaurant	1751	2119	<.01
WP666	adj. DJ's bar	1752	2120	<.01
WP667	1st floor adj. fire exit	1757	2111	<.01
WP668	' ' adj. F6	1758	2113	<.01
WP669	' ' adj. fire exit	2111	0108	<.01
WP670	south change	2129	0135	<.01
WP671	' ' clean decon	2130	0136	<.01
WP672	top of new stairs	2116	0125	<.01
WP673	adj. claridges	2115	0124	<.01
WP674	adj. DJ's restaurant	2119	0129	<.01
WP675	adj. DJ's bar	2120	0130	<.01
WP676	lunchroom	2103	0100	<.01
WP677	laundry	2105	0102	<.01
WP678	south change	0135	0347	<.01
WP679	' ' clean decon	0136	0348	<.01
WP680	top of new stairs	0125	0400	<.01
WP681	adj. claridges	0124	0359	<.01
WP682	adj. DJ's restaurant	0129	0402	<.01
WP683	adj. DJ's bar	0130	0403	<.01
WP684	lunchroom	0100	0345	<.01
WP685	laundry	0102	0346	<.01
WP686	adj. fire exit first floor	0108	0352	<.01

WORK IN PROGRESS: final inspection of north area and smoke test on south area.
 setting up south area.
 **** filter paper too wet to read.

John Robson.
 FOR EIL

X DENOTES LEVEL = TO OR
 GREATER THAN SPECIFIED
 LIMIT.



ENVIRONMENTAL & INDUSTRIAL LABORATORIES

P.O. BOX 653, UNLEY, SOUTH AUSTRALIA 5061 PHONE 274 1396
 P.O. BOX 76, DICKSON, A.C.T. 2602 PHONE 48 7801
 P.O. BOX 52, HAYMARKET, N.S.W. 2000 PHONE 698 2270

RESULTS OF AIRBORNE FIBRE MONITORING AT WODEN SHOPPING SQUARE

CONTRACTOR ASBESTOS EXTRACTORS

DATE 24/5/87

SLIDE NO.	POSITION.	ON.	OFF.	F/M.
WP 644	south clean decon	1811	2107	<.01
WP 645	' ' change	1810	2106	<.01
WP 646	top of stairs	1805	2133	<.01
WP 647	adjacent Claridges	1803	2131	<.01
WP 648	adj. DJ's bar	1809	2137	<.01
WP 649	' ' restaurant	1808	2136	<.01
WP 650	1st. floor adj. fire exit	1800	2110	<.01
WP 651	south clean decon	2107	0018	<.01
WP 652	' ' change	2106	0017	<.01
WP 653	lunchroom	2104	0016	<.01
WP 654	top of new stairs	2133	0010	<.01
WP 655	1st floor adj. fire exit	2140	0009	<.01
WP 656	adj. DJ's bar	2137	0011	<.01
WP 657	adj. DJ's restaurant	2136	0012	<.01
WP 658	adj. claridges	2131	0010	<.01

WORK IN PROGRESS: removal through south decon.

John Robson

FOR EIL

X DENOTES LEVEL = TO OR GREATER THAN SPECIFIED LIMIT.



ENVIRONMENTAL & INDUSTRIAL LABORATORIES

P.O. BOX 653, UNLEY SOUTH AUSTRALIA 5061 PHONE 274 1396
 P.O. BOX 76, DICKSON, A.C.T. 2602 PHONE 48 7801
 P.O. BOX 52, HAYMARKET, N.S.W. 2000 PHONE 698 2270

RESULTS OF AIRBORNE FIBRE MONITORING AT WODEN SHOPPING SQUARE
CONTRACTOR ASBESTOS EXTRACTORS **DATE** 23/05/87

SLIDE NO.	POSITION	ON.	OFF.	F/ML.
WP 621	south change	1816	2105	<.01
WP 622	' ' clean decon	1817	2106	0.01
WP 623	top of new stairs	1809	2045	<.01
WP 624	adj. DJ's bar	1813	2051	<.01
WP 625	' ' restaurant	1812	2052	<.01
WP 626	adj. Claridges	1806	2044	<.01
WP 627	1st. floor adj. fire exit	1754	2042	<.01
WP 628	south change	2105	0005	0.01
WP 629	' ' clean decon	2106	0006	0.02
WP 630	top of new stairs	2045	2350	<.01
WP 631	adj. DJ's restaurant	2052	2353	<.01
WP 632	' ' bar	2051	2352	<.01
WP 633	adj. Claridges	2044	2349	<.01
WP 634	1st. floor adj. fire exit	2042	2346	<.01
WP 635	lunchroom	2055	2359	<.01
WP 636	' '	2359	0414	<.01
WP 637	south change	0005	0415	0.02
WP 638	' ' clean decon	0006	0416	****
WP 639	top of stairs	2350	0410	<.01
WP 640	adj. DJ's bar	2352	0412	<.01
WP 641	' ' restaurant	2353	0413	<.01
WP 642	adj. Claridges	2349	0409	<.01
WP 643	1st. floor adj. fire exit	2346	0408	<.01

WORK IN PROGRESS:

**** very wet filter paper, wouldn't dry properly.
 removal first two shifts, bag removal last shift.

John Robson

FOR EIL

X DENOTES LEVEL = TO OR
 GREATER THAN SPECIFIED
 LIMIT.



ENVIRONMENTAL & INDUSTRIAL LABORATORIES

P.O. BOX 653, UNLEY, SOUTH AUSTRALIA 5061 PHONE 274 1396
 P.O. BOX 76, DICKSON, A.C.T. 2602 PHONE 48 7801
 P.O. BOX 52, HAYMARKET, N.S.W. 2000 PHONE 698 2270



RESULTS OF AIRBORNE FIBRE MONITORING AT WODEN SHOPPING SQUARE

CONTRACTOR ASBESTOS EXTRACTORS

DATE 22/05/87

SLIDE NO.	POSITION.	ON.	OFF.	F/ML.
WP614	adj. DJ's restaurant	2055	2247	<.01
WP615	adj. DJ's bar	2056	2248	<.01
WP616	adj. claridges	2059	2245	<.01
WP617	top of new stairs	2058	2244	<.01
WP618	south clean decon	2101	2252	0.02
WP619	' ' change	2100	2253	<.01
WP620	1st floor adj. fire exit	2053	2243	<.01

WORK IN PROGRESS: removal area clean up and bag removal.

John Rolso

FOR EIL

X DENOTES LEVEL = TO OR GREATER THAN SPECIFIED LIMIT.



ENVIRONMENTAL & INDUSTRIAL LABORATORIES

P.O. BOX 653, UNLEY, SOUTH AUSTRALIA 5061 PHONE 274 1396
 P.O. BOX 76, DICKSON, A.C.T. 2602 PHONE 48 7801
 P.O. BOX 52, HAYMARKET, N.S.W. 2000 PHONE 698 2270

RESULTS OF AIRBORNE FIBRE MONITORING AT WODEN SHOPPING SQUARE

CONTRACTOR ASBESTOS EXTRACTORS

DATE 19/20-05-87

SLIDE NO.	POSITION	ON.	OFF.	F/ML.
WP 546	top of stairs	1801	2028	<.01
WP 547	adj. Claridges	1800	2035	<.01
WP 548	adj. DJ's bar	1806	2038	<.01
WP 549	adj. DJ's restaurant	1805	2037	<.01
WP 550	1st. floor corridor adj. F6	1809	2027	<.01
WP 551	' adj. fire exit	1810	2025	<.01
WP 552	adjacent Theatrette	1815	2030	<.01
WP 553	Top of stairs	2028	0235	<.01
WP 554	adj. Claridges	2035	0236	<.01
WP 555	adj. DJ's restaurant	2037	0238	<.01
WP 556	adj. DJ's bar	2038	0239	<.01
WP 557	1st. floor corridor adj. fire exit	2025	0300	<.01
WP 558	' adj. F6	2027	0301	<.01
WP 559	Adjacent theatrette	2030	0303	<.01

WORK IN PROGRESS: setting up and removal from ends of beams.

John Robson

FOR EIL

X DENOTES LEVEL = TO OR GREATER THAN SPECIFIED LIMIT.



ENVIRONMENTAL & INDUSTRIAL LABORATORIES

P.O. BOX 653, UNLEY, SOUTH AUSTRALIA 5061 PHONE 274 1396
 P.O. BOX 76, DICKSON, A.C.T. 2602 PHONE 48 7801
 P.O. BOX 52 HAYMARKET, N.S.W. 2000 PHONE 698 2270


RESULTS OF AIRBORNE FIBRE MONITORING AT WODEN SHOPPING SQUARE

CONTRACTOR ASBESTOS EXTRACTORS

DATE 18/19-05-87

SLIDE NO.	POSITION.	ON.	OFF.	F/ML.
WP525	north clean decon	1826	1945	<.01
WP526	' ' change	1825	1946	<.01
WP527	adj. claridges	1840	2327	<.01
WP528	top of new stairs	1840	2340	<.01
WP529	adj. DJ's bar	1845	2343	<.01
WP530	adj. DJ's restaurant	1847	2342	<.01
WP531	1st floor corridor adj. F6	1850	2330	<.01
WP532	' ' ' ' adj. fire exit	1853	2331	<.01
WP533	dry decon no.1	1940	2015	<.01
WP534	north clean decon	1945	2358	<.01
WP535	' ' change	1946	2359	<.01
WP536	south change	2050	2350	<.01
WP537	' ' clean decon	2052	2351	0.02
WP538	top of new stairs	2340	0345	<.01
WP539	adj. claridges	2327	0344	<.01
WP540	adj. DJ' bar	2343	0348	<.01
WP541	adj. DJ's restaurant	2342	0347	<.01
WP542	1st. floor corridor adj. F6	2347	0333	<.01
WP543	' ' ' ' adj fire exit	2346	0336	<.01
WP544	clean decon south	2351	0353	<.01
WP545	change south	2350	0354	<.01

WORK IN PROGRESS:


 FOR EIL

X DENOTES LEVEL = TO OR GREATER THAN SPECIFIED LIMIT.



ENVIRONMENTAL & INDUSTRIAL LABORATORIES

P.O. BOX 653, UNLEY, SOUTH AUSTRALIA 5061 PHONE 274 1396
 P.O. BOX 76, DICKSON, A.C.T. 2602 PHONE 48 7801
 P.O. BOX 52, HAYMARKET, N.S.W. 2000 PHONE 698 2270



RESULTS OF AIRBORNE FIBRE MONITORING AT WODEN SHOPPING SQUARE
 CONTRACTOR ASBESTOS EXTRACTORS DATE 17-18/05/87

SLIDE NO.	POSITION	ON.	OFF.	F/ML.
WP505	top of new stairs	1842	2130	<.01
WP506	adj. DJ's restaurant	1836	2133	<.01
WP507	adj. DJ's bar	1837	2134	<.01
WP508	adj. claridges	1841	2131	<.01
WP509	1st floor adj. fire exit	1828	2137	<.01
WP510	' ' adj. F6	1829	2138	<.01
WP511	north clean decon	1810	2158	<.01
WP512	' ' change	1811	2157	<.01
WP513	top of new stairs	2130	0307	<.01
WP514	adj. DJ's restaurant	2133	0311	<.01
WP515	adj. DJ's bar	2134	0312	<.01
WP516	adj. claridges	2131	0308	<.01
WP517	1st floor adj. F6	2138	0315	<.01
WP518	' ' adj. fire exit	2137	0316	<.01
WP519	lunchroom	2142	0300	<.01
WP520	laundry	2145	0301	<.01
WP521	north clean decon	2158	0320	0.36 X
WP522	' ' change	2157	0321	0.24 X
WP523	' ' clean decon s.t.	0420	0520	<.01
WP524	' ' change s.t.	0421	0521	<.01

WORK IN PROGRESS: setting up and removal from beams through north decon.

John Robson

FOR EIL

X DENOTES LEVEL = TO OR GREATER THAN SPECIFIED LIMIT.



ENVIRONMENTAL & INDUSTRIAL LABORATORIES

P.O. BOX 653, UNLEY, SOUTH AUSTRALIA 5061 PHONE 274 1396
 P.O. BOX 76, DICKSON, A.C.T. 2602 PHONE 48 7801
 P.O. BOX 52, HAYMARKET, N.S.W. 2000 PHONE 698 2270



RESULTS OF AIRBORNE FIBRE MONITORING AT WODEN SHOPPING SQUARE

CONTRACTOR ASBESTOS EXTRACTORS

DATE 16-17/05/87

SLIDE NO.	POSITION.	ON.	OFF.	F/ML.
WP486	top of new stairs	1752	2031	<.01
WP487	adj. DJ's bar	1757	2035	<.01
WP488	adj. DJ's restaurant	1756	2034	<.01
WP489	adj. claridges	1754	2030	<.01
WP490	north clean decon	1806	2056	<.01
WP491	' change	1807	2057	<.01
WP492	1st floor adj. F6	1800	2037	<.01
WP493	' ' adj. fire exit	1759	2038	<.01
WP494	laundry	1805	2045	<.01
WP495	top of new stairs	2031	2352	<.01
WP496	adj. DJ's bar	2035	2357	<.01
WP497	adj. DJ's restaurant	2034	2356	<.01
WP498	adj. claridges	2030	2350	<.01
WP499	1st floor adj. F6	2037	2359	<.01
WP500	' ' adj. fire exit	2038	0000	<.01
WP501	north clean decon	2056	0007	<.01
WP502	' change	2057	0006	<.01
WP503	lunchroom	2042	0005	<.01
WP504	laundry	2045	0004	<.01

WORK IN PROGRESS: setting up and removal from beams through north decon.

John Robson

FOR EIL

X DENOTES LEVEL = TO OR
 GREATER THAN SPECIFIED
 LIMIT.



ENVIRONMENTAL & INDUSTRIAL LABORATORIES

P.O. BOX 653, UNLEY, SOUTH AUSTRALIA 5061 PHONE 274 1396
P.O. BOX 76, DICKSON, A.C.T. 2602 PHONE 48 7801
P.O. BOX 52, HAYMARKET, N.S.W. 2000 PHONE 698 2270

RESULTS OF AIRBORNE FIBRE MONITORING AT WODEN SHOPPING SQUARE

CONTRACTOR ASBESTOS EXTRACTORS

DATE 15/16-05-87

SLIDE NO.	POSITION.	ON.	OFF.	F/ML.
WP 486	top of new stairs	1752	2031	<.01
WP 487	adj. DJ's bar	1757	2035	<.01
WP 488	adj. DJ's restaurant	1756	2034	<.01
WP 489	adj. Claridges	1754	2030	<.01
WP 490	north clean decon	1806	2056	<.01
WP 491	change	1807	2057	<.01
WP 492	1st floor adj. F6	1800	2037	<.01
WP 493	adj. fire exit	1759	2038	<.01
WP 494	laundry	1805	2045	<.01
WP 495	top of new stairs	2031	2352	<.01
WP 496	adj. DJ's bar	2035	2357	<.01
WP 497	adj. DJ's restaurant	2034	2356	<.01
WP 498	adj. Claridges	2030	2350	<.01
WP 499	1st floor adj. F6	2037	2359	<.01
WP 500	adj. fire exit	2038	0000	<.01
WP 501	north clean decon	2056	0007	<.01
WP 502	change	2057	0006	<.01
WP 503	lunchroom	2042	0005	<.01
WP 504	laundry	2045	0004	<.01

WORK IN PROGRESS: setting up removal area

John Robson

FOR EIL

X DENOTES LEVEL = TO OR
GREATER THAN SPECIFIED
LIMIT.



ENVIRONMENTAL & INDUSTRIAL LABORATORIES

P.O. BOX 653, UNLEY, SOUTH AUSTRALIA 5061 PHONE 274 1396
 P.O. BOX 76, DICKSON, A.C.T. 2602 PHONE 48 7801
 P.O. BOX 52 HAYMARKET, N.S.W. 2000 PHONE 698 2270



RESULTS OF AIRBORNE FIBRE MONITORING AT WODEN SHOPPING SQUARE

CONTRACTOR ASBESTOS EXTRACTORS

DATE 15-16/05/87

SLIDE NO.	POSITION	ON.	OFF.	F/ML.
WP460	top of new stairs	1815	2055	<.01
WP461	adj. DJ's restaurant	1817	2100	<.01
WP462	adj. DJ's bar	1818	2101	<.01
WP463	1st floor adj. fire exit	1822	2045	<.01
WP464	' ' adj. F6	1823	2047	<.01
WP465	theatrette	1827	2050	<.01
WP466	buffer zone adj. DJ's bar	1832	2052	<.01
WP467	top of new stairs	2055	0055	<.01
WP468	adj. DJ's restaurant	2100	0058	<.01
WP469	adj. DJ's bar	2059	0057	<.01
WP470	adj. claridges	2059	0057	<.01
WP471	adj. sliding fire door	2104	0101	<.01
WP472	1st floor adj. fire exit	2045	0046	<.01
WP473	' ' adj. F6	2047	0045	<.01
WP474	north clean decon	2011	0108	<.01
WP475	' ' change	2110	0107	<.01
WP476	lunchroom	2108	0105	<.01
WP477	top of new stairs	0055	0408	<.01
WP478	adj. DJ's restaurant	0058	0410	<.01
WP479	adj. DJ's bar	0100	0411	<.01
WP480	adj. claridges	0057	0407	<.01
WP481	1st floor adj. fire exit	0046	0357	<.01
WP482	' ' adj. F6	0045	0356	<.01
WP483	north clean decon	0108	0416	0.02
WP484	' ' change	0107	0417	<.01
WP485	lunchroom	0105	0415	<.01

WORK IN PROGRESS: setting up removal area at end of beams.

John Robson

FOR EIL

X DENOTES LEVEL = TO OR
 GREATER THAN SPECIFIED
 LIMIT.



ENVIRONMENTAL & INDUSTRIAL LABORATORIES

P.O. BOX 653, UNLEY, SOUTH AUSTRALIA 5061 PHONE 274 1396
 P.O. BOX 76, DICKSON, A.C.T. 2602 PHONE 48 7801
 P.O. BOX 52, HAYMARKET, N.S.W. 2000 PHONE 698 2270



RESULTS OF AIRBORNE FIBRE MONITORING AT WODEN SHOPPING SQUARE

CONTRACTOR ASBESTOS EXTRACTORS

DATE 14/5/87

SLIDE NO.	POSITION.	ON.	OFF.	F/ML.
WP441	laundry	1800	2101	<.01
WP442	north clean decon	1759	2104	<.01
WP443	' ' change	1758	2105	<.01
WP444	top of new stairs	1750	2057	<.01
WP445	adj. D.J.'s bar	1756	2059	<.01
WP446	' ' restaurant	1754	2059	<.01
WP447	1st. floor hall adj. F6	1810	2055	<.01
WP448	' ' adj. fire exit	1811	2054	<.01
WP449	adj. Claridges	1751	2056	<.01
WP450	laundry	2101	2101	<.01
WP451	north clean decon	2104	2104	<.01
WP452	' ' change	2105	2105	<.01
WP453	top of new stairs	2057	2057	<.01
WP454	adj. D.J.'s bar	2059	2059	<.01
WP455	' ' restaurant	2059	2059	<.01
WP456	' ' Claridges	2056	2056	<.01
WP457	1st. floor hall adj. F6	2054	2054	<.01
WP458	' ' fire exit	2055	2055	<.01
WP459	lunchroom	2104	2536	<.01

WORK IN PROGRESS; Removal.

John Robson

FOR EIL.

X DENOTES LEVEL = TO OR GREATER THAN SPECIFIED LIMIT.



INSPECTION RECORD

No 166895 ⁵⁰

Permit Holder: J. MALCOLM

Block: 243 Section: 8 Suburb: PHILLIP

Stage: PRE PUA BEAMS & PURLINS IN NORTHERN
REMOVAL AREA.

A brief inspection of parts of the construction on this site has indicated that:

Work may proceed to next stage
 may not proceed to next stage

The following matters appear to require your attention

OKAY TO REMOVE SIDES OF PLASTIC
TUNNELS BETWEEN ROOF AND CEILING
TO ALLOW CLEANING OF CEILING AREA.

Please rebook this inspection stage when rectified

Posted

Left on site

J. [Signature] 18.15.87
Building Inspector

NOTE: Inspectors can be contacted at the office ONLY BETWEEN 11 am-12 noon.

Permits are granted on the condition that the materials and methods of construction will conform with the acceptable standards set out in the Building Manual, that work will be carried out in a proper and workmanlike manner, in accordance with the approval plan and specifications, with adequate safety precautions, and by the holder of the permit or a person employed by or under contract to him.

Spot checks of construction by the Building Inspector are carried out to enable the Department to administer the Building Ordinance. The Department does not have the role of supervising construction on behalf of owners and is not able to ensure the quality of finish of buildings. It is recommended that if necessary owners engage competent building design and construction consultants to advise them.

It should be noted that this Inspection Record is not intended to provide a certification that the building work complies absolutely with the prescribed requirements. Inspection Records should not be used to indicate satisfactory progress or conformance with contractual arrangements.



ENVIRONMENTAL & INDUSTRIAL LABORATORIES

P.O. BOX 653, UNLEY, SOUTH AUSTRALIA 5061 PHONE 274 1396
 P.O. BOX 76, DICKSON, A.C.T. 2602 PHONE 48 7801
 P.O. BOX 52, HAYMARKET N.S.W. 2000 PHONE 698 2270



RESULTS OF AIRBORNE FIBRE MONITORING AT WODEN SHOPPING SQUARE
 CONTRACTOR ASBESTOS EXTRACTORS DATE 13-14.5.87

SLIDE NO.	POSITION	ON:	OFF:	F/ML:
WP413	top of new stairs	1742	2159	<.01
WP414	adj. DJ's Bar	1745	2156	<.01
WP415	adj. DJ's Restaurant	1746	2157	<.01
WP416	adj. Claridges	1748	2200	<.01
WP417	north change	1800	2137	0.02
WP418	north clean decon	1759	2136	0.01
WP419	1st floor adj. fire exit	1815	2154	<.01
WP420	1st floor hall adj. F6	1813	2153	<.01
WP421	neg. air no. 1	1802	2112	no fibre
WP422	neg. air no. 2	1804	2111	no fibre
WP423	1st floor adj. F6	2153	0059	<.01
WP424	1st floor adj. fire exit	2154	0100	<.01
WP425	adj. DJ's Bar	2156	0055	<.01
WP426	adj. DJ's Restaurant	2157	0056	<.01
WP427	top of new stairs	2159	0052	<.01
WP428	adj. Claridges	2200	0050	<.01
WP429	laundry	2106	0112	<.01
WP430	north clean decon	2136	0115	0.04
WP431	north change	2137	0116	0.01
WP432	adj. Claridges	0050	0405	<.01
WP433	top of new stairs	0052	0404	<.01
WP434	adj. DJ's Bar	0055	0402	<.01
WP435	adj. DJ's Restaurant	0056	0401	<.01
WP436	1st floor hall adj. F6	0059	0408	<.01
WP437	1st floor fire exit	0100	0409	<.01
WP438	laundry	0112	0416	<.01
WP439	north clean decon	0115	0445	wet filter, no fibre
WP440	north change	0116	0445	0.01

WORK IN PROGRESS: Removal

John Robson

FOR EIL

X DENOTES LEVEL = TO OR GREATER THAN SPECIFIED LIMIT.

Glen

48



ENVIRONMENTAL & INDUSTRIAL LABORATORIES

P.O. BOX 653, UNLEY, SOUTH AUSTRALIA 5061 PHONE 274 1396
 P.O. BOX 76, DICKSON, A.C.T. 2602 PHONE 48 7801
 P.O. BOX 52, HAYMARKET, N.S.W. 2000 PHONE 698 2270



RESULTS OF AIRBORNE FIBRE MONITORING AT WODEN SHOPPING SQUARE

CONTRACTOR ASBESTOS EXTRACTORS

DATE 13/5/87

SLIDE NO.	POSITION.	ON.	OFF.	F/ML.
WP405	north decon	0140	0500	0.02
WP406	north change	0142	0501	0.02
WP407	top of new stairs.	0055	0453	<.01
WP408	adj dj,s bar.	0057	0456	<.01
WP409	adj dj,s restaurant.	0056	0455	<.01
WP410	1st floor adj fire exit.	0129	0451	<.01
WP411	1st floor adj f6	0130	0449	<.01
WP412	1st floor above suzannes.	0135	0450	<.01

WORK IN PROGRESS:

removal.

John Rolisa

FOR EIL

X DENOTES LEVEL = TO OR GREATER THAN SPECIFIED LIMIT.



ENVIRONMENTAL & INDUSTRIAL LABORATORIES

P.O. BOX 653, UNLEY, SOUTH AUSTRALIA 5061 PHONE 274 1396
 P.O. BOX 76, DICKSON, A.C.T. 2602 PHONE 48 7801
 P.O. BOX 52, HAYMARKET, N.S.W. 2000 PHONE 698 2270



RESULTS OF AIRBORNE FIBRE MONITORING AT WODEN SHOPPING SQUARE

CONTRACTOR ASBESTOS EXTRACTORS

DATE 12.5.87

SLIDE NO.	POSITION.	ON.	OFF.	F/ML.
WP382	north change.	1600	1745	<.01
WP383	north clean decon.	1601	1746	<.01
WP384	1st floor corridor adj f6	1550	1756	<.01
WP385	1st floor adj fire exit.	1552	1755	<.01
WP386	top of new stairs	1553	1752	<.01
WP387	adj dj,s bar.	1556	1753	<.01
WP388	adj dj,s restaunt.	1555	1751	<.01
WP389	north change.	1745	2055	<.01
WP390	north clean decon.	1746	2056	<.01
WP391	top of new stairs.	1752	2036	<.01
WP392	adj dj,s bar.	1753	2039	<.01
WP393	adj dj,s restaunt.	1751	2038	<.01
WP394	1st floor corridor adj f6	1756	2045	<.01
WP395	1st floor adj fire exit.	1755	2047	<.01
WP396	above suzannes 1st floor.	1752	2046	<.01
WP397	above suzannes 1st floor.	2046	0135	<.01
WP398	1st floor corridor adj f6	2045	0130	<.01
WP399	1st floor adj fire exit.	2047	0129	<.01
WP400	north decon	2055	0140	<.01
WP401	north change.	2056	0142	<.01
WP402	top of new stairs	2036	0055	<.01
WP403	adj dj,s bar.	2039	0057	<.01
WP404	adj dj,s restaunt.	2038	0056	<.01

WORK IN PROGRESS: smoke test and removal.

John Rolson
FOR EIL

X DENOTES LEVEL = TO OR GREATER THAN SPECIFIED LIMIT.



ENVIRONMENTAL & INDUSTRIAL LABORATORIES

P.O. BOX 653, UNLEY, SOUTH AUSTRALIA 5061 PHONE 274 1396
 P.O. BOX 76, DICKSON, A.C.T. 2602 PHONE 48 7801
 P.O. BOX 52, HAYMARKET, N.S.W. 2000 PHONE 698 2270



RESULTS OF AIRBORNE FIBRE MONITORING AT WODEN SHOPPING SQUARE

CONTRACTOR ASBESTOS EXTRACTORS

DATE 11/05/87

SLIDE NO.	POSITION.	ON.	OFF.	F/ML.
WP371	north change	1632	1738	<.01
WP372	' clean decon	1633	1739	<.01
WP373	adj. theatrette	1625	1730	<.01
WP374	ACTEA	1627	1731	<.01
WP375	1st floor corridor adj. F6	1700	2113	<.01
WP376	' ' adj. fire exit	1702	2112	<.01
WP377	top of new stairs	1710	2103	<.01
WP378	adj. DJ's bar	1714	2106	<.01
WP379	adj. DJ's restaurant	1713	2105	<.01
WP380	north change	1738	2056	<.01
WP381	' clean decon	1739	2056	<.01

W

WORK IN PROGRESS: smoke test on north change & decon.

John Robson

FOR EIL

X DENOTES LEVEL = TO OR GREATER THAN SPECIFIED LIMIT.



ENVIRONMENTAL & INDUSTRIAL LABORATORIES

P.O. BOX 653, UNLEY, SOUTH AUSTRALIA 5061 PHONE 274 1396
 P.O. BOX 76, DICKSON, A.C.T. 2602 PHONE 48 7801
 P.O. BOX 52, HAYMARKET N.S.W. 2000 PHONE 698 2270



RESULTS OF AIRBORNE FIBRE MONITORING AT WODEN SHOPPING SQUARE

CONTRACTOR ASBESTOS EXTRACTORS

DATE 8-9/05/87

SLIDE NO.	POSITION	ON.	OFF.	F/ML.
WP292	south change	1807	2101	<.01
WP293	north change	1809	2104	<.01
WP294	south change	2101	0004	0.03
WP295	south clean decon	2102	0005	0.04
WP296	north change	2104	0007	<.01
WP297	north clean decon	2105	0008	0.01
WP298	top of new stairs	2100	0023	<.01
WP299	adj. DJ's restaurant	2102	0025	<.01
WP300	adj. DJ's bar	2103	0026	<.01
WP301	1st floor corridor adj. F6	2112	0015	<.01
WP302	' ' adj. fire exit	2111	0014	<.01
WP303	south change	0004	0352	0.03
WP304	south clean decon	0005	0352	0.02
WP305	north change	0007	0354	<.01
WP306	north clean decon	0008	0354	<.01
WP307	lunchroom	0201	0350	0.02
WP308	laundry	0205	0351	0.02
WP309	1st floor fire exit	0014	0322	<.01
WP310	' ' corridor adj.F6	0015	0321	<.01
WP311	top of new stairs	0023	0315	<.01
WP312	adj. DJ's restaurant	0025	0317	<.01
WP313	adj. DJ's bar	0026	0318	<.01

WORK IN PROGRESS: setting up removal area.

John Rolso

FOR EIL

X DENOTES LEVEL = TO OR GREATER THAN SPECIFIED LIMIT.



ENVIRONMENTAL & INDUSTRIAL LABORATORIES

P.O. BOX 653, UNLEY, SOUTH AUSTRALIA 5061 PHONE 274 1396
 P.O. BOX 76, DICKSON, A.C.T. 2602 PHONE 48 7801
 P.O. BOX 52 HAYMARKET, N.S.W. 2000 PHONE 698 2270



RESULTS OF AIRBORNE FIBRE MONITORING AT WODEN SHOPPING SQUARE

CONTRACTOR ASBESTOS EXTRACTORS

DATE 7-8.5.87

SLIDE NO.	POSITION.	ON.	OFF.	F/ML.
WP269	1st floor hall adj. F6	1808	2108	<.01
WP270	' ' adj. fire stairs	1810	2109	<.01
WP271	north change	1822	2108	<.01
WP272	' ' clean decon	1823	2107	0.01
WP273	south change	1838	2110	<.01
WP274	' ' clean decon	1850	2110	<.01
WP275	north decon neg. air no. 1	1858	2108	no fibre
WP276	' ' no. 2	1902	2109	no fibre
WP277	top of new stairs	1909	2112	<.01
WP278	adj. DJ's restaurant	1914	2114	<.01
WP279	adj. DJ's bar	1915	2115	<.01
WP280	1st floor hall adj. F6	2108	0100	<.01
WP281	' ' adj. fire exit	2109	0100	<.01
WP282	north clean decon	2107	0053	<.01
WP283	north change	2108	0054	<.01
WP284	top of new stairs	2257	0345	<.01
WP285	adj. DJ's bar	2301	0348	<.01
WP286	adj. DJ's restaurant	2300	0349	<.01
WP287	north clean decon	0053	0410	<.01
WP288	north change	0054	0409	<.01
WP289	neg. air no. 3	0057	0406	no fibre
WP290	1st floor hall adj. F6	0240	0353	<.01
WP291	' ' adj. fire exit	0241	0353	<.01

WORK IN PROGRESS: Setting up. Removing Sisal.

[Signature]
 FOR EIL

X DENOTES LEVEL = TO OR
 GREATER THAN SPECIFIED
 LIMIT.



ENVIRONMENTAL & INDUSTRIAL LABORATORIES

P.O. BOX 653, UNLEY, SOUTH AUSTRALIA 5061 PHONE 274 1396
 P.O. BOX 76, DICKSON, A.C.T. 2602 PHONE 48 7801
 P.O. BOX 52 HAYMARKET, N.S.W. 2000 PHONE 698 2270



INTERIM RESULTS

RESULTS OF AIRBORNE FIBRE MONITORING AT WODEN SHOPPING SQUARE

CONTRACTOR ASBESTOS EXTRACTORS

DATE 6-7.5.87

SLIDE NO.	POSITION.	ON.	OFF.	F/ML.
WP252	1st floor hall adj. F6	0045	0448	<.01
WP253	south clean decon	0443	0650	<.01
WP254	top of new stairs	0708	1218	<.01
WP255	adj. DJ's restaurant	0712	1221	<.01
WP256	adj. DJ's bar	0711	1222	<.01
WP257	1st floor hall adj. F6	0700	1211	<.01
WP258	' ' adj. fire exit	0659	1210	<.01
WP259	' ' adj. Theatrette	0702	1212	<.01
WP260	' ' ACTEA	0704	1214	<.01
WP261	' ' hall adj. F6	1211	1718	<.01
WP262	' ' adj. fire exit	1210	1719	<.01
WP263	' ' adj. theatrette	1213	1715	<.01
WP264	' ' ACTEA	1214	1716	<.01
WP265	top of new stairs	1218	1710	<.01
WP266	adj. DJ's restaurant	1221	1708	<.01
WP267	adj. DJ's bar	1222	1707	<.01
WP268	north decon	1230	1713	0.02

WORK IN PROGRESS: Setting up. Removing Sisal.

[Handwritten Signature]

FOR EIL

X DENOTES LEVEL = TO OR GREATER THAN SPECIFIED



ENVIRONMENTAL & INDUSTRIAL LABORATORIES

P.O. BOX 653, UNLEY, SOUTH AUSTRALIA 5061 PHONE 274 1396
 P.O. BOX 76, DICKSON, A.C.T. 2602 PHONE 48 7801
 P.O. BOX 52, HAYMARKET, N.S.W. 2000 PHONE 698 2270



RESULTS OF AIRBORNE FIBRE MONITORING AT WODEN SHOPPING SQUARE

CONTRACTOR ASBESTOS EXTRACTORS DATE 6-7/5/87

SLIDE NO.	POSITION.	ON.	OFF.	F/ML.
WP216	top of new stairs	0718	1215	<.01
WP217	adj dj,s bar.	0723	1218	<.01
WP218	adj dj,s restaurant.	0721	1217	<.01
WP219	1st floor corridor.	0710	1208	<.01
WP220	1st floor adj fire exit.	0709	1207	<.01
WP221	1st floor adj theatrette.	0712	1211	<.01
WP222	1st floor a.c.t.e.a	0715	1209	<.01
WP223	1st floor corridor f6	1208	1655	<.01
WP224	1st floor adj fire exit.	1207	1654	<.01
WP225	1st floor a.c.t.e.a.	1211	1658	<.01
WP226	1st floor adj theatrette.	1209	1657	<.01
WP227	adj dj,s bar.	1218	1712	<.01
WP228	adj dj,s restaurant.	1217	1711	<.01
WP229	top of new stairs.	1215	1714	<.01
WP230	Sth decon tunnel.north	1223	1704	<.01
WP231	Sth decon tunnel.south.	1225	1705	<.01
WP232	Nth decon change.	1230	1709	<.01
WP233	1st floor adj fire exit.	1817	2112	<.01
WP234	1st floor corridor adj f6.	1818	2110	<.01
WP235	top of new stairs.	1820	2114	<.01
WP236	adj dj,s bar.	1822	2116	<.01
WP237	adj dj,s restaurant.	1822	2117	<.01
WP238	change.	1851	2107	0.02
WP239	clean decon.	1852	2108	0.02
WP240	1st floor corridor adj. F6	2110	0045	<.01
WP241	' ' adj. fire exit	2112	0046	<.01
WP242	top of new stairs	2114	0055	<.01
WP243	adj. DJ's bar	2116	0102	<.01
WP244	adj. DJ's restaurant	2117	0100	<.01
WP245	change	2107	0050	<.01
WP246	clean decon	2108	0050	<.01
WP245a	laundry	2105	0047	<.01
WP247	top of new stairs	0055	0519	<.01
WP248	adj. DJ's restaurant	0100	0521	<.01
WP249	adj. DJ's bar	0102	0522	<.01
WORK IN PROGRESS: Setting up.				
WP250	clean decon	0050	0444	<.01
WP251	change	0050	0445	<.01
WP252	south decon	0443	0650	<.01

John Robson
FOR EIL

X DENOTES LEVEL = TO OR GREATER THAN SPECIFIED LIMIT.



INSPECTION RECORD

No 166892 ⁷⁴⁰

Permit Holder: J. MALCOLM

Block: 243 Section: 8 Suburb: PHILLIP.

Stage:

RANDOM AT SET UP STAGE. (HIGH FIBRE LEVELS IN DECOR & CHANGE)

A brief inspection of parts of the construction on this site has indicated that:

- Work may proceed ~~to next stage~~
- may not proceed to next stage

The following matters appear to require your attention

Provide plastic flops at junctions of removal funnels & access tunnels.

Provide negative air extraction duct to air lock area at dirty end of decontamination unit ~~as~~ as discussed on site

Please rebook this inspection stage when rectified

Posted

Left on site

[Signature] 6.15.87
Building Inspector

NOTE: Inspectors can be contacted at the office ONLY BETWEEN 11 am-12 noon.

Permits are granted on the condition that the materials and methods of construction will conform with the acceptable standards set out in the Building Manual, that work will be carried out in a proper and workmanlike manner, in accordance with the approval plan and specifications, with adequate safety precautions, and by the holder of the permit or a person employed by or under contract to him.

Spot checks of construction by the Building Inspector are carried out to enable the Department to administer the Building Ordinance. The Department does not have the role of supervising construction on behalf of owners and is not able to ensure the quality of finish of buildings. It is recommended that if necessary owners engage competent building design and construction consultants to advise them.

It should be noted that this Inspection Record is not intended to provide a certification that the building work complies absolutely with the prescribed requirements. Inspection Records should not be used to indicate satisfactory progress or conformance with contractual arrangements.



INSPECTION RECORD

No 166894 ⁴¹

Permit Holder: I. MALCOLM

Block: 2+3

Section: 8

Suburb: PHILLIP

Stage:

PRE REMOVAL & SMOKE TEST TO DETERMINE
REMOVAL AREA

A brief inspection of parts of the construction on this site has indicated that:

Work may proceed to next stage
 may not proceed to next stage

The following matters appear to require your attention

- 1) Seal leaks at laps of panels
- 2) Seal tunnel adjacent to change room & clean decan.
- 3) Seal leaks in plastic at west end of tunnel 2.

Please rebook this inspection stage when rectified

Posted

Left on site

J. Clarke 11.15.87
Building Inspector

NOTE: Inspectors can be contacted at the office ONLY BETWEEN 11 am-12 noon.

GM

Permits are granted on the condition that the materials and methods of construction will conform with the acceptable standards set out in the Building Manual, that work will be carried out in a proper and workmanlike manner, in accordance with the approval plan and specifications, with adequate safety precautions, and by the holder of the permit or a person employed by or under contract to him.

Spot checks of construction by the Building Inspector are carried out to enable the Department to administer the Building Ordinance. The Department does not have the role of supervising construction on behalf of owners and is not able to ensure the quality of finish of buildings. It is recommended that if necessary owners engage competent building design and construction consultants to advise them.

It should be noted that this Inspection Record is not intended to provide a certification that the building work complies absolutely with the prescribed requirements. Inspection Records should not be used to indicate satisfactory progress or conformance with contractual arrangements.



ENVIRONMENTAL & INDUSTRIAL LABORATORIES

P.O. BOX 653, UNLEY, SOUTH AUSTRALIA 5061 PHONE 274 1396
 P.O. BOX 76, DICKSON, A.C.T. 2602 PHONE 48 7801
 P.O. BOX 52, HAYMARKET, N.S.W. 2000 PHONE 698 2270



RESULTS OF AIRBORNE FIBRE MONITORING AT WODEN SHOPPING SQUARE

CONTRACTOR ASBESTOS EXTRACTORS DATE 5-6/05/87

SLIDE NO.	POSITION.	ON.	OFF.	F/ML.	
WP198	change s.t.	2114	2230	<.01	
WP199	clean decon s.t.	2115	2230	<.01	
WP198A	change	2230	0104	0.40	X
WP199A	clean decon	2230	0104	0.40	X
WP200	1st floor corridor adj. F6	2052	0025	<.01	
WP201	' ' adj. fire exit	2053	0026	<.01	
WP202	top of new stairs	2105	0005	<.01	
WP203	adj. DJ's bar	2107	0007	<.01	
WP204	adj. DJ's restaurant	2108	0008	<.01	
WP205	laundry	2117	0004	<.01	
WP206	1st floor corridor adj. F6	0025	0513	<.01	
WP207	' ' adj. fire exit	0026	0512	<.01	
WP208	top of new stairs	0005	0506	<.01	
WP209	adj. DJ's bar	0030	0508	<.01	
WP210	adj. DJ's restaurant	0031	0509	<.01	
WP211	ground floor adj. CBS	0004	0505	<.01	
WP212	change s.t.	0145	0227	<.01	
WP213	clean decon s.t.	0146	0227	<.01	
WP214	clean decon	0227	0501	<.01	
WP215	change	0228	0502	<.01	

WORK IN PROGRESS: setting up removal area

John Robson
FOR EIL

X DENOTES LEVEL = TO OR GREATER THAN SPECIFIED LIMIT.



ENVIRONMENTAL & INDUSTRIAL LABORATORIES

P.O. BOX 653, UNLEY, SOUTH AUSTRALIA 5061 PHONE 274 1396
 P.O. BOX 76, DICKSON, A.C.T. 2602 PHONE 48 7801
 P.O. BOX 52, HAYMARKET, N.S.W. 2000 PHONE 698 2270



RESULTS OF AIRBORNE FIBRE MONITORING AT WODEN SHOPPING SQUARE

CONTRACTOR ASBESTOS EXTRACTORS

DATE 05/05/87

SLIDE NO.	POSITION.	ON.	OFF.	F/ML.	
WP163	1st floor adj. theatrette	0013	0557	<.01	
WP164	' ' adj. entrance to ACTEA.	0016	0558	<.01	
WP165	' ' adj. room F6	0018	0555	<.01	
WP166	' ' corridor	2358	0554	<.01	
WP167	' ' adj. fire exit	2357	0553	<.01	
WP168	change	2355	0602	0.19	X
WP169	clean decon	2356	0603	0.15	X
WP170	top of new stairs	0004	0546	<.01	
WP171	adj. DJ's bar	0006	0549	<.01	
WP172	adj. DJ's restaurant	0007	0551	<.01	
WP173	top of new stairs	0546	1215	<.01	
WP174	adj. DJ's bar	0549	1220	<.01	
WP175	adj. DJ's restaurant	0551	1218	<.01	
WP176	1st floor adj. fire exit	0553	1223	<.01	
WP177	' ' corridor	0554	1225	<.01	
WP178	' ' adj. theatrette	0557	1227	<.01	
WP179	' ' adj. entrance to ACTEA.	0558	1229	<.01	
WP180	change s.t.	1211	1609	<.01	
WP181	clean decon s.t.	1212	1610	0.01	
WP182	top of new stairs	1215	1758	<.01	
WP183	adj. DJ's restaurant	1218	1803	<.01	
WP184	adj. DJ's bar	1220	1804	<.01	
WP185	1st floor adj. fire exit	1223	1809	<.01	
WP186	' ' corridor	1225	1811	<.01	
WP187	' ' adj. theatrette	1227	1812	<.01	
WP188	' ' adj. entrance to ACTEA.	1229	1813	<.01	
WP189	1st floor corridor	1811	2052	<.01	
WP190	' ' adj. fire exit	1809	2053	<.01	
WP191	top of new stairs	1758	2105	<.01	
WP192	adj. DJ's bar	1804	2107	<.01	
WP193	adj. DJ's restaurant	1803	2108	<.01	
WP194	ground floor adj. CBS	1807	2103	<.01	
WP195	change	1835	2114	1.53	X
WP196	clean decon	1826	2115	1.24	X
WP197	lunchroom	2118	0005	<.01	

WORK IN PROGRESS: setting up removal area

John Rolso

FOR EIL

X DENOTES LEVEL = TO OR GREATER THAN SPECIFIED LIMIT.



ENVIRONMENTAL & INDUSTRIAL LABORATORIES

P.O. BOX 653, UNLEY, SOUTH AUSTRALIA 5061 PHONE 274 1396
 P.O. BOX 76, DICKSON, A.C.T. 2602 PHONE 48 7801
 P.O. BOX 52, HAYMARKET, N.S.W. 2000 PHONE 698 2270

RESULTS OF AIRBORNE FIBRE MONITORING AT WODEN SHOPPING SQUARE

CONTRACTOR ASBESTOS EXTRACTORS DATE 04/05/87

SLIDE NO.	POSITION.	ON.	OFF.	F/ML.
WP127	1st floor adj. fire exit	0000	0710	<.01
WP128	' ' corridor	0001	0711	<.01
WP129	' ' adj. theatrette	2355	0712	<.01
WP130	' ' adj. entrance to ACTEA.	2357	0713	<.01
WP131	top of new stairs	0003	0716	<.01
WP132	adj. DJ's restaurant	0004	0718	<.01
WP133	adj. DJ's bar	0006	0719	<.01
WP134	1st floor adj. fire exit	0710	1157	<.01
WP135	' ' corridor	0711	1158	<.01
WP136	' ' adj. theatrette	0712	1159	<.01
WP137	' ' adj. entrance to ACTEA	0713	1200	<.01
WP138	top of new stairs	0716	1204	<.01
WP139	adj. DJ's restaurant	0718	1206	<.01
WP140	adj. DJ's bar	0719	1208	<.01
WP141	1st. floor adj. fire exit	1157	1803	<.01
WP142	' ' corridor	1158	1802	<.01
WP143	' ' adj. theatrette	1159	1806	<.01
WP144	' ' adj. entrance to ACTEA	1200	1807	<.01
WP145	top of stairs	1204	1755	<.01
WP146	adj. D.J.'s restaurant	1206	1758	<.01
WP147	' ' bar	1208	1759	<.01
WP148	' ' bar	1759	0006	<.01
WP149	' ' restaurant	1758	0007	<.01
WP150	top of new stairs	1755	0004	<.01
WP151	1st. floor corridor	1802	2216	0.04 X
WP152	' ' adj. fire exit	1803	2217	0.05 X
WP153	' ' adj. theatrette	1806	0013	<.01
WP154	' ' adj. entrance to ACTEA	1807	0016	<.01
WP155	clean decon s.t.	1909	2102	2.18 X
WP156	change s.t.	1912	2100	2.39 X
WP157	clean decon s.t.	2102	2219	0.04 X
WP158	change s.t.	2100	2220	0.05 X
WP159	1st. floor corridor s.t.	2217	2358	<.01
WP160	' ' adj. fire exit s.t.	2216	2357	<.01
WP161	clean decon s.t.	2219	2356	<.01
WP162	change s.t.	2220	2355	<.01

WORK IN PROGRESS:

setting up removal area. s.t.- short term.
 all clearances attained after high readings.

[Signature]
 FOR EIL:

X DENOTES LEVEL = TO OR GREATER THAN SPECIFIED LIMIT.