


ACT ASBESTOS SURVEY



Address: FARRER
DBSUD: 334/

Are the address details correct? Yes No
Was a resident home? Yes No

Roof Construction Flat Gable No Roof Space
Roofing Material Tiles Metal Asbestos Sheet

Sarking Yes No Type _____
Repaired Yes No

House extension suspected? Yes No

Estimated area of house 120 sq. ms 140 160 180+

Access to roof denied? Yes No

Reason (if Yes above) Power of Entry Other _____

Damage resulting from inspection? Yes No

Damage report completed? Yes


Internal Access Required? Yes No

Insulation Suspect Amosite Suspect Crocidolite Cellulose
Glass Fibre Batts Glass Fibre Fluff Foam
Rock Wool Fluff Rock Wool Batts Other
None

Inspector: R. FARRER
Signature: [Signature]

Date: 11/2/89
Time: _____

Analysis Results Amosite Confirmed Crocidolite Confirmed Non Asbestos



Central Office
Action taken Yes